
Office	ate District	State of No	ew Mexico			C-103
District I		Energy, Minerals an	d Natural Resource	es WELL A		27, 2004
1625 N. French Dr., Hobbs, N District II	IM 88240	OH COMORDMA	TION DIVIDION		30-025-06758	_
1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indica	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410				TATE FEE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa	Fe, NM	Santa I C,	14W1 07505	b. State	Oil & Gas Lease No.	
87505	DDV MOTIC	TEC AND DEDODTE ON	WELL C	7 1 2000	Name or Unit Agreement	Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Turner	(Apache NEDU 919S)	Tvaine /
1. Type of Well: Oil Well Gas Well Other Water Source				8. Well	10	/
2. Name of Operator Apache Corporation				9. OGRI	ID Number 00873	/
3. Address of Operator 6120 South Yale, Suite 1500				10. Pool	name or Wildcat	
Tulsa, OK 74136-4224				Hare; S	San Andres (Gas)	
4. Well Location						
Unit Letter M	: 3			ad 660	_feet from theWest	line
Section 22		Township 21S 11. Elevation (Show when	Range 37E	NMPM P. etc.)	CountyLea	Marie Alian
		3427' DF	ner DK, KKB, KI, G	n, eic.)		Floring Photo
Pit or Below-grade Tank Ap	plication 🗌 or		111111111111111111111111111111111111111		The state of the s	
Pit typeDepth	to Groundwat				earest surface water	
Pit Liner Thickness:	mil	Below-Grade Tank: Volum	nebl	ols; Construction M	Aaterial	
12.	. Check A	ppropriate Box to Indi	cate Nature of No	otice, Report o	r Other Data	
NOTIC	CE OF INT	TENTION TO:		SUBSEQUE	NT REPORT OF:	
PERFORM REMEDIAL	WORK 🗌		☐ REMEDIAL	. WORK	☐ ALTERING CAS	ING 🗌
TEMPORARILY ABANE			<u> </u>	E DRILLING OP	<u> </u>	
PULL OR ALTER CASI	NG 🗌	MULTIPLE COMPL	CASING/C	EMENT JOB		
			1			
OTHER:		-		mporarily Aband		X
13. Describe propos		eted operations. (Clearly s	tate all pertinent deta	ils, and give pert	inent dates, including estir	nated date
13. Describe propos	proposed wor	eted operations. (Clearly sk). SEE RULE 1103. For	tate all pertinent deta	ils, and give pert	inent dates, including estir	nated date
13. Describe propos of starting any p or recompletion	proposed wor	k). SEE RULE 1103. For	tate all pertinent deta Multiple Completio	ils, and give pert	inent dates, including estir	nated date
13. Describe propos of starting any p or recompletion 12/13/2005 MIR	oroposed wor U. Held safe		tate all pertinent deta Multiple Completio	ils, and give pert	inent dates, including estir	nated date
13. Describe propos of starting any p or recompletion 12/13/2005 MIR 12/14-19/2005 Clea	oroposed wor U. Held safe n out hole.	k). SEE RULE 1103. For	tate all pertinent deta Multiple Completio ping.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent deta Multiple Completio oing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' ceme	tate all pertinent deta Multiple Completio oing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent deta Multiple Completio oing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent deta Multiple Completio bing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent deta Multiple Completio bing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH	U. Held safe n out hole. and set CIBI with sub pun	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent deta Multiple Completio bing. ent. Test casing to 500 re well for TA.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose of recompletion 12/13/2005 MIR 12/14-19/2005 Clea 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parke	U. Held safe n out hole. and set CIBI with sub pun er & Parker r	ty meeting. Pulled prod tult of @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attractions.	tate all pertinent detar Multiple Completion oing. ent. Test casing to 500 re well for TA. ached.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose of recompletion 12/13/2005 MIR 12/14-19/2005 Clea 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parke	U. Held safe n out hole. and set CIBI with sub pun er & Parker r	ty meeting. Pulled prod tult of @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attractions.	tate all pertinent detar Multiple Completion oing. ent. Test casing to 500 re well for TA. ached.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose of recompletion 12/13/2005 MIR 12/14-19/2005 Clea 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parke	U. Held safe n out hole. and set CIBI with sub pun er & Parker r	ty meeting. Pulled prod tult of @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attractions.	tate all pertinent detar Multiple Completion oing. ent. Test casing to 500 re well for TA. ached.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any propose of recompletion 12/13/2005 MIR 12/14-19/2005 Clea 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parke	U. Held safe n out hole. and set CIBI with sub pun er & Parker r	ty meeting. Pulled prod tule? @ 3920', dump 35' cement and 4-3/4" tubing. Secu	tate all pertinent detar Multiple Completion oing. ent. Test casing to 500 re well for TA. ached.	ils, and give pert ns: Attach wellb	inent dates, including estir ore diagram of proposed c	nated date
13. Describe propose of starting any progression or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket	U. Held safern out hole. and set CIBI with sub puner & Parker range Abandon	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent detard Multiple Completion Multiple Completion on the Mu	owledge and belie	inent dates, including estirore diagram of proposed cay.	nated date ompletion
13. Describe propose of starting any progression or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket	U. Held safern out hole. and set CIBI with sub puner & Parker range Abandon	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent deta Multiple Completio oing. ent. Test casing to 500 re well for TA. ached. to the best of my kno idelines \(\), a general pe	owledge and beliermit ☐ or an (attach	inent dates, including estir ore diagram of proposed cay. If I further certify that any pined) alternative OCD-approve	nated date ompletion
13. Describe propose of starting any progression or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket Items of the start of the	This App Abandon	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent detard Multiple Completion Multiple Completion on the Mu	owledge and beliermit ☐ or an (attach	inent dates, including estirore diagram of proposed cay.	nated date ompletion
13. Describe propose of starting any progression or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket I hereby certify that the it grade tank has been/will be considered and the stank of the	This App Abandon	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent detar Multiple Completion on Multiple Completion	owledge and belie	inent dates, including estir ore diagram of proposed cay. If I further certify that any pined) alternative OCD-approve	nated date ompletion
13. Describe propose of starting any progression or recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket Items of the start of the	This App Abandon	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent detary Multiple Completion on Multiple Completion	owledge and beliermit or an (attach	inent dates, including estirore diagram of proposed cay. If I further certify that any pined) alternative OCD-approve DATE 01/10/20 Orp.comTelephone No. (918)	it or below-d plan
13. Describe propose of starting any progression of recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket I hereby certify that the item of the grade tank has been/will be considered by the constant of the start of the st	This Apple Abandon Thornation a constructed or con	roval of Temporary ment Expires bove is true and complete losed according to NMOCD gu	tate all pertinent detary Multiple Completion on Multiple Completion	owledge and belie chnician linton@apacheco	inent dates, including estirore diagram of proposed cay. ay. DATE 01/10/20 DATE OF COMTelephone No. (918) AGER JAN 1 9 26 DATE DATE	it or below-d plan
13. Describe propose of starting any progression of recompletion 12/13/2005 MIR 12/14-19/2005 Cleat 12/20/2005 RIH 12/21/2005 RIH 12/30/2005 Parket I hereby certify that the it grade tank has been/will be considered as a second of the sec	This Apple Abandon Thornation a constructed or con	ty meeting. Pulled prod tult @ 3920', dump 35' cement and 4-3/4" tubing. Securan M.I.T. Signed chart attraction of Temporary ment Expires	tate all pertinent detary Multiple Completion on Multiple Completion	owledge and belie chnician linton@apacheco	inent dates, including estirore diagram of proposed cay. ay. DATE 01/10/20 DATE OF COMTelephone No. (918) AGER JAN 1 9 26 DATE DATE	it or below-d plan



:

: