Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103			
Office	Energy, Minerals and Natural Resources			Revised March 25, 1999			
District I 1625 N. French Dr., Hobbs, NM 88240	Lifergy, winterais		WELL API NO.				
District II				30-025-2133			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of Lease			
District III	1220 South St. Francis Dr.			· · ·			
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe,/NM 87505						
District IV	Sama re, inter o / 303			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505		1 : <del>1</del> 4 1 :	1.12 20106	K-3	62		
SUNDRY NOTICES AND REPORTS ON WELLS						ment Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACKSTO A							
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						/	
PROPOSALS.)							
1. Type of Well: Oil Well Gas Well Other X SUD							
Oil Well Gas Well Other X Starting   2. Name of Operator 8. Well No.							
Vintage Petroleum, Inc.						-	
					9. Pool name or Wildcat		
3. Address of Operator							
110 West Seventh Street, Tulsa, OK 74119					Mescalero San Andres		
4. Well Location							
Unit Letter_I: 2310_	feet from the	south	line and	990	feet from the		
eastline	<b>T</b> 1: 103		205		~	_	
Section 23	Township 10S	Rang		NMPM	County:	Lea	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						•	
	PLUG AND ABANDON		REMEDIAL WORK				
		$\sim$		-			
	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND	æ	
					ABANDONN	MENT	
	MULTIPLE		CASING TEST AN	ID			
	COMPLETION		CEMENT JOB				
OTHER:			OTHER:				

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated 1. date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

It is Vintage Petroleum policy to have a daily safety meeting on location each day prior to commencing operations. This meeting will be noted in the daily report to the Tulsa office and on the rig daily report. Plugging and Abandonment Procedure:

- 1) Contact New Mexico OCD and advise of preparation to plug the well with 48 hour notice.
- 2) RUPU. ND wellhead and NU BOP. PU work string and tag bottom at 3996'. Circulate hole with 9.5 ppg brine with 12.5 pounds of gel per barrel.
- Spot 100' plug from PBTD of 3996' to 3896' (+/-). 3)
- 4) Spot 100' plug from 3500' to 3400'. Perf, tag and squeeze (50' inside and 50' outside).
- 5) Spot 100' plug from 1727'-1627'.
- 6) Spot 100' plug from 415'-315' and tag.
- Spot plug from 60' to surface. RD & MOPU. Cut off wellhead and anchors. 7)
- 8) Install P&A marker and clean up location.
- 9) File C-103 with New Mexico OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Megan T. Wondoal	TITLE Regulatory Analyst	DATE 1/11/2006

Telephone No. 9/8-878-5407

Type or print name Megan T. Wondowl (This space for State use) APPPROVED BY Mis Welliams Conditions of approval, if any

TIDE DISTRICT SUPERVISOR/GENERAL MANAGE

-<sup>DATE</sup> **IAN 2 0 2005** 

