State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION DIVI	SION
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-26917
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210	,	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NO	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR P	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	O A NORTH HOBBS (G/SA) UNIT
DIFFERENT RESERVOIR. USE ".	APPLICATION FOR PERMIT" (Form C-101) for such proposa	
Type of Well: Oil Well	Gas Well Other Injector	8. Well No. 132
Name of Operator Occidental Permian Ltd.		9. OGRID No. 157984
Address of Operator 1017 W. Stanolind Rd., HOBBS,	NM 88240 505/397-8200	10. Pool name or Wildcat HOBBS (G/SA)
4. Well Location	303/371-0200	
Unit Letter L : 1623	Feet From The SOUTH 1218	Feet From The WEST Line
Section 29	Township 18-S Range	38-E NMPM LEA County
	11. Elevation (Show whether DF, RKB, RT GR, etc.) 3641' GR	
Pit or Below-grade Tank Application	or Closure	
	nd Water Distance from nearest fresh water	well Distance from nearest surface water
Pit Liner Thickness mil		
12. Chec	ck Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DE	
		BLUNG OPNS. I I PLUG & ABANDONMENT I I
PULL OR ALTER CASING	Multiple Completion CASING TEST A	ND CEMENT JOB
PULL OR ALTER CASING OTHER:	Multiple Completion CASING TEST A	ND CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O	Multiple Completion CASING TEST A	ND CEMENT JOB tinent dates, including estimated date of starting any
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per b. For Multiple Completions: Attach wellbore diagram of	ND CEMENT JOB tinent dates, including estimated date of starting any
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipmer 2. Sqz old csg leak @4050 and per	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the compl	ND CEMENT JOB tinent dates, including estimated date of starting any f proposed completion or recompletion.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipmer 2. Sqz old csg leak @4050 and per 3. Re-Perforate the following inter	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 3. For Multiple Completions: Attach wellbore diagram of att. rfs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes)	tinent dates, including estimated date of starting any f proposed completion or recompletion.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipmer 2. Sqz old csg leak @4050 and per 3. Re-Perforate the following inter	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 3. For Multiple Completions: Attach wellbore diagram of att. rfs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes)	tinent dates, including estimated date of starting any f proposed completion or recompletion.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 which is stimulated t	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 3. For Multiple Completions: Attach wellbore diagram of a t. offs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes) (2100 g 15% NEFE HCL acid in 3 settings, 23 24 25, on/off tool w/1.875 ss "F" nipple, 120 jts 2-7/8" Duct t csg to 640 psi for 30 min and chart for the NMOCD	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 26 28 2976.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 which is stimulated t	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 3. For Multiple Completions: Attach wellbore diagram of the Adoption of	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 6 Pkr set @3976'.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/ 5. RIH w/5.5" UNI VI pc pkr, XI. 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location.	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 26 28 28 28 28 28 28 28 28 28 28 28 28 28
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oproposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/s. RIH w/5.5" UNI VI pc pkr, XI. 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 6 Pkr set @3976'.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/ 5. RIH w/5.5" UNI VI pc pkr, XI. 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location.	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 6 Pkr set @3976'.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipmer 2. Sqz old csg leak @4050 and per 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 wr 5. RIH w/5.5" UNI VI pc pkr, XL 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 July 276'.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w. 5. RIH w/5.5" UNI VI pc pkr, XL 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 July 276'.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/s. RIH w/5.5" UNI VI pc pkr, XI. 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006 I hereby certify that the information above it constructed or closed according to NMOSD guideline.	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per b. For Multiple Completions: Attach wellbore diagram of the completions of the state of the stat	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL Completion of the set @3976'. In the certify that any pit or below-grade tank has been/will be all alternative OCD-approved
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w. 5. RIH w/5.5" UNI VI pc pkr, XL 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006 I hereby certify that the information above i constructed or closed according to NMOCD guideline SIGNATURE	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 5. For Multiple Completions: Attach wellbore diagram of nt. rfs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes). 2100 g 15% NEFE HCL acid in 3 settings. 23 24 25. on/off tool w/1.875 ss "F" nipple, 120 jts 2-7/8" Duc t csg to 640 psi for 30 min and chart for the NMOCD OCCUPATION SEQUENT TITLE Wor	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 26 27 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/s. RIH w/5.5" UNI VI pc pkr, XL 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006 I hereby certify that the information above is constructed or closed according to NMOSD guideline SIGNATURE TYPE OR PRINT NAME Robert Gil	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 5. For Multiple Completions: Attach wellbore diagram of nt. rfs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes). 2100 g 15% NEFE HCL acid in 3 settings. 23 24 25. on/off tool w/1.875 ss "F" nipple, 120 jts 2-7/8" Duc t csg to 640 psi for 30 min and chart for the NMOCD OCCUPATION SEQUENT TITLE Wor	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL 26 26 27 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/s. RIH w/5.5" UNI VI pc pkr, XI. 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006 I hereby certify that the information above i constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Robert Gil	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per B. For Multiple Completions: Attach wellbore diagram of the completions of the completion of the com	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL and super CBL Pkr set @3976'. In the certify that any pit or below-grade tank has been/will be alternative OCD-approved Rever Completion Specialist DATE 02/03/2006 Poxy.com TELEPHONE NO. 505/397-8206
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU. Pull Injection equipment 2. Sqz old csg leak @4050 and pent 3. Re-Perforate the following inter 4. Stimulate perfs 4187 to 4245 w/s. RIH w/5.5" UNI VI pc pkr, XL 6. Circ csg w/100 bbl pkr fluid. Ts 7. RDPU. Clean Location. Rig Up Date: 01/17/2006 Rig Down Date: 02/02/2006 I hereby certify that the information above is constructed or closed according to NMOSD guideline SIGNATURE TYPE OR PRINT NAME Robert Gil	Multiple Completion CASING TEST A OTHER: perations (Clearly state all pertinent details, and give per 5. For Multiple Completions: Attach wellbore diagram of nt. rfs 4071, 76, 78, 91 w/350 sx Class A cmt w/2% CaC val; 4085-95 using 1 spf, 120 deg sp ph. (11 holes). 2100 g 15% NEFE HCL acid in 3 settings. 23 24 25. on/off tool w/1.875 ss "F" nipple, 120 jts 2-7/8" Duc t csg to 640 psi for 30 min and chart for the NMOCD OCCUPATION SEQUENT TITLE Wor	tinent dates, including estimated date of starting any f proposed completion or recompletion. and super CBL and super CBL The retify that any pit or below-grade tank has been/will be alternative OCD-approved skover Completion Specialist DATE 02/03/2006 Poxy.com TELEPHONE NO. 505/397-8206

