Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resourc	es May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	•	WELL API NO. 30-025-21431
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		A-1118-21
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
DIFFERENT RESERVOIR. USE "APPLIC." PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FOR SUCH	
	Gas Well 🗌 Other	8. Well Number OOZ
2. Name of Operator SHIMN	ERY OIL COMPANY, INC.	9. OGRID Number 20713
3. Address of Operator		10. Pool name or Wildcat
606 W TENNESSEE	STE 107 MIDLAND TX 797	101 LOUINGTON PADDOCK
4. Well Location		1800
Unit Letter 3 :	660 feet from the N line at	
Section 5 Township 17 S Range 37 E NMPM County		
	11. Elevation (Show whether DR, RKB, RT, G 3818 G-R	R, etc.)
Pit or Below-grade Tank Application _ or		Reference to the second of the
Pit type Depth to Groundwa	terDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume b	bls; Construction Material
12 Check A	ppropriate Box to Indicate Nature of N	otice. Report or Other Data
NOTICE OF IN	l	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	
TEMPORARILY ABANDON		CE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL   CASING/C	EMENT JOB
OTHER:	☐ OTHER:	
OTHER: 13. Describe proposed or compl		ails, and give pertinent dates, including estimated date
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all pertinent det	ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
13. Describe proposed or compl	eted operations. (Clearly state all pertinent det	
<ol> <li>Describe proposed or compl of starting any proposed wo or recompletion.</li> </ol>	eted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion	
13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion	ons: Attach wellbore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62:	ons: Attach wellbore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new	eted operations. (Clearly state all pertinent det. rk). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62:	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig.	eted operations. (Clearly state all pertinent det. rk). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig.	eted operations. (Clearly state all pertinent detr.). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. tole. RDMO. WO replacement rods.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig.	eted operations. (Clearly state all pertinent detr.). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. tole. RDMO. WO replacement rods.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate Ferror 12-6-05 Acidize each new 12-7-05 Test tbg back in he 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 B	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or compl of starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO +	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate Ferror 12-6-05 Acidize each new 12-7-05 Test tbg back in he 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 B	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate Ferror 12-6-05 Acidize each new 12-7-05 Test tbg back in he 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 B	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate Ferror 12-6-05 Acidize each new 12-7-05 Test tbg back in he 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 B	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate Ferror 12-6-05 Acidize each new 12-7-05 Test tbg back in he 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 B	eted operations. (Clearly state all pertinent determ). SEE RULE 1103. For Multiple Completion it. Lay down bad rods. POH w/ tbg. Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. iole. RDMO. WO replacement rods.  pump on 76 RS. POP @ 1-1/2x86x9.  - 115 BW Gas TSTM.  - 130 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion 57, 6259, 6264, 6266, 6276 & 6278
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO +	eted operations. (Clearly state all pertinent detr.). SEE RULE 1103. For Multiple Completion of the Lay down bad rods. POH w/tbg.  Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. Hole. RDMO. WO replacement rods.  Pump on 76 RS. POP @ 1-1/2x86x9.  115 BW Gas TSTM.  120 BW Gas TSTM.  120 BW Gas TSTM.	ons: Attach wellbore diagram of proposed completion  57, 6259, 6264, 6266, 6276 & 6278  Characteristics of the completion of the completio
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO + 12-23-06 24	eted operations. (Clearly state all pertinent detr.). SEE RULE 1103. For Multiple Completions. SEE RULE 1103. For Multiple Completions.  Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. Hole. RDMO. WO replacement rods.  Pump on 76 RS. POP @ 1-1/2x86x9.  115 BW Gas TSTM.  120 BW Gas TSTM.  120 BW Gas TSTM.	owledge and belief. I further certify that any pit or belowershit $\square$ or an (attached) alternative OCD-approved plan $\square$ .
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig.  to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO +	eted operations. (Clearly state all pertinent detrk). SEE RULE 1103. For Multiple Completion of the Rule 1103. For	owledge and belief. I further certify that any pit or belowermit $\square$ or an (attached) alternative OCD-approved plan $\square$ .
13. Describe proposed or complete of starting any proposed wo or recompletion.  12-2-05 MIRU pulling unit 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 40 BO + 2-23-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO + SIGNATURE	eted operations. (Clearly state all pertinent detr.). SEE RULE 1103. For Multiple Completions. SEE RULE 1103. For Multiple Completions.  Paddock 1 JS each @ 6179, 6188, 6195, 6228, 62: perf using PPI w/ 3 bbls 15% NEFEHCL acid. Hole. RDMO. WO replacement rods.  Pump on 76 RS. POP @ 1-1/2x86x9.  115 BW Gas TSTM.  120 BW Gas TSTM.  120 BW Gas TSTM.	owledge and belief. I further certify that any pit or belowershit $\square$ or an (attached) alternative OCD-approved plan $\square$ .
13. Describe proposed or complof starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO + SIGNATURE	eted operations. (Clearly state all pertinent detrk). SEE RULE 1103. For Multiple Completion of the co	owledge and belief. I further certify that any pit or below- mit or an (attached) alternative OCD-approved plan  DATE 2-24-06  Telephone No.
13. Describe proposed or complof starting any proposed wo or recompletion.  12-2-05 MIRU pulling uni 12-5-05 Log & perforate F 12-6-05 Acidize each new 12-7-05 Test tbg back in h 12-8-05 WO rig. to 2-19-06 WO rig. 2-20-06 MIRU. Ran 1-1/2 2-21-06 24 Hrs P 40 BO + 2-22-06 24 Hrs P 20 BO + 2-23-06 24 Hrs P 20 BO + SIGNATURE	eted operations. (Clearly state all pertinent detrk). SEE RULE 1103. For Multiple Completion of the co	owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan

, i,s