

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <u>30-025-27682</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <input type="checkbox"/>
7. Lease Name or Unit Agreement Name <u>Lea</u>
8. Well Number <u>#2</u>
9. OGRID Number <u>004094</u>
10. Pool name or Wildcat <u>San Andres</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other Disposal

2. Name of Operator
Chaparral S.W.D., L.P.

3. Address of Operator
P. O. Box 1769 Eunice, NM 88231

4. Well Location
Unit Letter A : 850 feet from the North line and 950 feet from the East line
Section 17 Township 23S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Pull 2 7/8 tubing out hole - looking for hole in tube
2. Take out of hole
3. Run tubing back in hole - test above slips
4. Replace bad pit
5. Set packer and put back on production - ADI Tension Packer - set packer pull up turn 1/4 turn left and pull 10 points - release packer set down and turn 1/4 turn to right as soon as I can get unit



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul Prather TITLE Partner DATE 02-23-06

Type or print name Paul Prather

Telephone No. 390 1437

(This space for State use)

APPROVED BY Hayden Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 01 2006

Conditions of approval, if any