Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
District 1 - (575) 393-6161 NOV 1 6 2013 Minerals and Natural Resources	August 1, 2011
1025 N. Pickell Dr., 1000 S., (NM 6024)	WELL API NO. 30-025-01434
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	Indicate Type of Lease
District III - (505) 334-6178 RECEIVET 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE
District IV – (505) 476-3460  1220 S. St. Francis Dr., Santa Fe, NM  87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Shahara State
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other	8. Well Number 7
2. Name of Operator  EnergyQuest	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
4526 Research Forest Dr. Ste. 200, The Woodlands, TX 77381	Maljamar
4. Well Location Unit Letter : 1980   feet from the W   line and	60 feet from the S line
	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc. 4187 GL	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  RE CONVETEMPORARILY ABANDON  CHANGE PLANS  CC RETURE  PULL OR ALTER CASING  MULTIPLE COMPL  CA CSNG_ INT TO COMPLET:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.  1. Set CIBP @ 4275. Circulate hole w/ mud laden fluid.	MITTING <swdinjection> ERSION RBDMS RN TO TA ENVIRO CHG LOC PA P&amp;A NR P&amp;A R d give pertinent dates, including estimated date</swdinjection>
7. Cut off wellhead and weld on Dry Hole Marker. MUST	oil Conservation Division BE NOTIFIED 24 Hours the beginning of operations
3. Perf & Sqz 25 sx @ 2315 2215. WOC & Tag 2600 - 2590 4. Perf & Sqz 25 sx @ 1280-1180. WOC & Tag. 7450 - 7350 5. Perf & Sqz 35 sx @ 370-270. WOC & Tag. 6. Perf & Sqz 35 sx @ 150 to surface. 7. Cut off wellhead and weld on Dry Hole Marker.  Spud Date:  Rig Release Date:	BE NOTIFIED 24 Hours the beginning of operations
3. Perf & Sqz 25 sx @ 2315-2215. WOC & Tag 2600-2590 4. Perf & Sqz 25 sx @ 1280-1180. WOC & Tag. /450 - /350 5. Perf & Sqz 35 sx @ 370-270. WOC & Tag. 6. Perf & Sqz 35 sx @ 150 to surface. 7. Cut off wellhead and weld on Dry Hole Marker.  The O  MUST  Prior to 1	BE NOTIFIED 24 Hours the beginning of operations
3. Perf & Sqz 25 sx @ 2315-2215. WOC & Tag 2600-2590 4. Perf & Sqz 25 sx @ 1280-1180. WOC & Tag. 7450-7350 5. Perf & Sqz 35 sx @ 370-270. WOC & Tag. 6. Perf & Sqz 35 sx @ 150 to surface. 7. Cut off wellhead and weld on Dry Hole Marker.  Spud Date:  Rig Release Date:  The O  MUST  Prior to 1  I hereby certify that the information above is true and complete to the best of my knowledge.	BE NOTIFIED 24 Hours the beginning of operations
3. Perf & Sqz 25 sx @ 2315-2215. WOC & Tag 4. Perf & Sqz 25 sx @ 1280-1180. WOC & Tag. 5. Perf & Sqz 35 sx @ 370-270. WOC & Tag. 6. Perf & Sqz 35 sx @ 150 to surface. 7. Cut off wellhead and weld on Dry Hole Marker.  Spud Date:  Rig Release Date:  The O  MUST  Prior to 1  Signature Base Sqz 35 sx @ 150 to surface.  The O  Type or print name Scott ADAMI E-mail address:	BE NOTIFIED 24 Hours the beginning of operations te and belief.
3. Perf & Sqz 25 sx @ 2315-2215. WOC & Tag 2600-2550 4. Perf & Sqz 25 sx @ 1280-1180. WOC & Tag. 1450-1350 5. Perf & Sqz 35 sx @ 370-270. WOC & Tag. 6. Perf & Sqz 35 sx @ 150 to surface. 7. Cut off wellhead and weld on Dry Hole Marker.  Spud Date:  Rig Release Date:  The O  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE BASAL Action TITLE SENIOR OPERA	BE NOTIFIED 24 Hours the beginning of operations  the and belief.  PHONE: 381 - 875 - 6200

Energy Quest Shahara State #7 30-025-01434 16-175-33E 1980FUL, 660 FSL

HOBBS OCD

NOV 1 6 2015

RECEIVED

83/8 e 318

Paris 4304 - 4457

5/20 4495

Shahara State #7 30-025-01434 16-175-33E 1980FUL, 660 FSL

