Office	rict State of New			Form C-103
District I - (575) 393-6161	OBBS OCDEnergy, Minerals and	Natural Resources	WELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88. <u>District II</u> – (575) 748-1283		TON DUMENON	30-025-02721	
811 S. First St., Artesia, NM 884 OV 1 6 2015 OIL CONSERVATION DIVISION			5. Indicate Type of I	Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87	1220 South St.	Francis Dr.	STATE 🖂	FEE
District IV (505) 476-3460	Santa Fe. Ni	M 87505	6. State Oil & Gas I	ease No.
1220 S. St. Francis Dr., Santa Fe, 87505	MOTIATE			
SUNDRY	NOTICES AND REPORTS ON WI	ELLS	7. Lease Name or U	nit Agreement Name
	PROPOSALS TO DRILL OR TO DEEPEN O			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			STATE TD	
1. Type of Well: Oil Well	Gas Well Other		8. Well Number	
2. Name of Operator			9. OGRID Number	
Devon Energy Production Company, LP			6137	
Address of Operator State of Operator State of Operator			10. Pool name or W	
4. Well Location	klanoma City, OK 73102		TOWNSEND;PERM	IO UPPER PENN
	. 000 fact from the South	line and 1000	fact from the	Fast line
Unit LetterW_ Section 02	:990_feet from theSouth Township 16S	nline and1980_ Range 35E	feet from the	
Section 02	11. Elevation (Show whether			Lea County, NM
直接被消化性性	4008 KB; 3997'GL; 11' KE			
12. Ch	eck Appropriate Box to Indica	te Nature of Notice,	Report or Other Da	ata
NOTICE	SE INTENTION TO	1	-	
PERFORM REMEDIAL WOR	OF INTENTION TO: RK ☐ PLUG AND ABANDON ☒	_B E-PERM	ITTING <swd< td=""><td>INJECTION></td></swd<>	INJECTION>
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐	C CONVER	RSION R	BDMS
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐	C RETURN		Α
DOWNHOLE COMMINGLE		CSNG	ENVIRO	CHG LOC
CLOSED-LOOP SYSTEM		INT TO P	P&A NR	P&A R
OTHER:		OINER.	P&A NR_	P&A R
OTHER: 13. Describe proposed or	completed operations. (Clearly state	OITER. e all pertinent details, and	d give pertinent dates,	including estimated date
OTHER: 13. Describe proposed or of starting any proposed.	completed operations. (Clearly states sed work). SEE RULE 19.15.7.14 N	OITER. e all pertinent details, and	d give pertinent dates,	including estimated date
OTHER: 13. Describe proposed or	completed operations. (Clearly states sed work). SEE RULE 19.15.7.14 N	OITER. e all pertinent details, and	d give pertinent dates,	including estimated date
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRLI POOH w/rod	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion.	OTHER. e all pertinent details, and MAC. For Multiple Cor	d give pertinent dates, inpletions: Attach well	including estimated date
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'.	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP	OTHER. e all pertinent details, and MAC. For Multiple Cor ubing from 10,602'.	d give pertinent dates, inpletions: Attach well	including estimated date
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAPH @ 9,765' - 9,565'. (T. Wolfcamp @	OTHER. e all pertinent details, and MAC. For Multiple Cor ubing from 10,602'. PW/255X5 CM 9,763')	d give pertinent dates, in pletions: Attach well	including estimated date
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C1	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T. Wolfcamp @ 50'). Pump 45 sx (160') Cl H in/out (160').	OTHER. e all pertinent details, and MAC. For Multiple Cor ubing from 10,602'. PW/255X5 CM 9,763') 2,8150'. 7,000'. (T.4b)	d give pertinent dates, in pletions: Attach well	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'.	OTHER. e all pertinent details, and MAC. For Multiple Corruption 10,602'. PW/255X5 CM'; 9,763') 2,8,150' - 7,990'. (T.Abo) 6,273' - 6,123'. (T.Glo)	d give pertinent dates, impletions: Attach well of @ 8,150')	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T. Wolfcamp @ 50'). Pump 45 sx (160') Cl H in/out (160').	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 5X5 CM'. 29,763') 28,150' - 7,990'. (T.Ab.) 26,273' - 6,123'. (T.Glo) 24,750' - 4,600'. (Csg s)	d give pertinent dates, inpletions: Attach well of @ 8,150') orieta @ 6,273')	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C12 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' – 9,565'. (T. Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'.	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 3X3 CM (20,000) @ 8,150' - 7,990'. (T.Ab) @ 6,273' - 6,123'. (T.Glo) @ 4,750' - 4,600'. (Csg s) @ 3,043' - 2,833'. (T.Yat) @ 2,000' - 1,850'. (T.Sal)	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C12 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP H @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'.	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 3X3 CM (20,000) @ 8,150' - 7,990'. (T.Ab) @ 6,273' - 6,123'. (T.Glo) @ 4,750' - 4,600'. (Csg s) @ 3,043' - 2,833'. (T.Yat) @ 2,000' - 1,850'. (T.Sal)	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAPH @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 50 sx (210') Cl C in/out @ 10'. Pump 35 sx (150') Cl C in/out @ 10'. Circulate 90 sx Cl C in/out to surfet dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 3X3 CM (20,000) @ 8,150' - 7,990'. (T.Ab) @ 6,273' - 6,123'. (T.Glo) @ 4,750' - 4,600'. (Csg s) @ 3,043' - 2,833'. (T.Yat) @ 2,000' - 1,850'. (T.Sal)	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP H @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'.	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 3X3 CM (20,000) @ 8,150' - 7,990'. (T.Ab) @ 6,273' - 6,123'. (T.Glo) @ 4,750' - 4,600'. (Csg s) @ 3,043' - 2,833'. (T.Yat) @ 2,000' - 1,850'. (T.Sal)	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAPH @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 50 sx (210') Cl C in/out @ 10'. Pump 35 sx (150') Cl C in/out @ 10'. Circulate 90 sx Cl C in/out to surfet dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrupting from 10,602'. PW/25 3X3 CM (20,000) @ 8,150' - 7,990'. (T.Ab) @ 6,273' - 6,123'. (T.Glo) @ 4,750' - 4,600'. (Csg s) @ 3,043' - 2,833'. (T.Yat) @ 2,000' - 1,850'. (T.Sal)	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') C11 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 N or recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAPH @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 50 sx (210') Cl C in/out @ 10'. Pump 35 sx (150') Cl C in/out @ 10'. Circulate 90 sx Cl C in/out to surfet dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrections from 10,602'. PW/25 5X5 CM'. 29,763') 28,150' - 7,990'. (T.Ab.) 36,273' - 6,123'. (T.Glo) 4,750' - 4,600'. (Csg s) 3,043' - 2,833'. (T.Yad.) 2,000' - 1,850'. (T.Sal.) ace.	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 3,04 9. Perf sqz holes @ 390 10. Cut wellhead off. Set 9# mud will be circul	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Circulate 90 sx Cl C in/out to surfat dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrections from 10,602'. PW/25 5X5 CM'. 29,763') 28,150' - 7,990'. (T.Ab.) 36,273' - 6,123'. (T.Glo) 4,750' - 4,600'. (Csg s) 3,043' - 2,833'. (T.Yad.) 2,000' - 1,850'. (T.Sal.) ace.	npletions: Attach well o @ 8,150') orieta @ 6,273') shoe @ 4,697') — woo es @ 3,043'; B.Salt @	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 2,00 8. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. Set 9# mud will be circul Spud Date:	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAPH @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pum	OTHER. e all pertinent details, and MAC. For Multiple Corrections from 10,602'. PW/25 5X5 CM' @ 9,763') @ 8,150' - 7,990'. (T.Aba. @ 6,273' - 6,123'. (T.Gla. @ 4,750' - 4,600'. (Csg s. @ 3,043' - 2,833'. (T.Yal. @ 2,000' - 1,850'. (T.Sal. face.	npletions: Attach well of @ 8,150') orieta @ 6,273') shoe @ 4,697') — worder @ 3,043'; B.Salt @ t @ 2,000')	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 2,00 8. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. Set 9# mud will be circul Spud Date:	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Circulate 90 sx Cl C in/out to surfat dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrections from 10,602'. PW/25 5X5 CM' @ 9,763') @ 8,150' - 7,990'. (T.Aba. @ 6,273' - 6,123'. (T.Gla. @ 4,750' - 4,600'. (Csg s. @ 3,043' - 2,833'. (T.Yal. @ 2,000' - 1,850'. (T.Sal. face.	npletions: Attach well of @ 8,150') orieta @ 6,273') shoe @ 4,697') — worder @ 3,043'; B.Salt @ t @ 2,000')	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. Set 9 # mud will be circul Spud Date:	completed operations. (Clearly states sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Circulate 90 sx Cl C in/out to surfect dry hole marker. ated between each plug. Rig Release	OITER. e all pertinent details, and MAC. For Multiple Cor Details from 10,602'. Pw/ 25 5x5	and belief.	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. Set 9 # mud will be circul Spud Date:	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Circulate 90 sx Cl C in/out to surfet dry hole marker. ated between each plug. Rig Release Right and complete to the surfet dry hole marker.	OTHER. e all pertinent details, and MAC. For Multiple Corrections from 10,602'. PW/25 5X5 CM' @ 9,763') @ 8,150' - 7,990'. (T.Aba. @ 6,273' - 6,123'. (T.Gla. @ 4,750' - 4,600'. (Csg s. @ 3,043' - 2,833'. (T.Yal. @ 2,000' - 1,850'. (T.Sal. face.	and belief.	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set • 9# mud will be circul Spud Date:	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAP H @ 9,765' – 9,565'. (T. Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 35 sx (150') Cl C in/out @ 13'. Pump 50 sx (210') Cl C in/out @ 13'. Pump 35 sx (150') Cl C in/out @ 13'.	OITER. e all pertinent details, and MAC. For Multiple Cor Details from 10,602'. Pw/ 25 5x5 2m'. 9,763') 8,150' - 7,990'. (T.Ab.) 6,273' - 6,123'. (T.Glo) 4,750' - 4,600'. (Csg s) 3,043' - 2,833'. (T.Yal.) 2,000' - 1,850'. (T.Sal.) ace. the best of my knowledge Production Technologis	d give pertinent dates, impletions: Attach well of @ 8,150') orieta @ 6,273') choe @ 4,697') — wood at @ 2,000') et and belief. DATE	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 2,00 9. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. See 9# mud will be circul Spud Date: I hereby certify that the information of the complete of	completed operations. (Clearly states sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Circulate 90 sx Cl C in/out to surfect dry hole marker. ated between each plug. Rig Release	OITER. e all pertinent details, and MAC. For Multiple Cor Details from 10,602'. Pw/ 25 5x5 2m'. 9,763') 8,150' - 7,990'. (T.Ab.) 6,273' - 6,123'. (T.Glo) 4,750' - 4,600'. (Csg s) 3,043' - 2,833'. (T.Yal.) 2,000' - 1,850'. (T.Sal.) ace. the best of my knowledge Production Technologis	d give pertinent dates, impletions: Attach well of @ 8,150') orieta @ 6,273') choe @ 4,697') — wood at @ 2,000') et and belief. DATE	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 4. Perf sqz holes @ 8,15 5. Perf sqz holes @ 4,75 7. Perf sqz holes @ 3,04 8. Perf sqz holes @ 2,00 9. Perf sqz holes @ 390 10. Cut wellhead off. Set • 9# mud will be circul Spud Date:	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25" Cl H cement. Tag. CAPH @ 9,765' – 9,565'. (T.Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 50 sx (210') Cl C in/out @ 73'. Pump 50 sx (210') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. Pump 50 sx (210') Cl C in/out @ 73'. Pump 50'. Pump 50 sx (210') Cl C in/out @ 73'. Pump 50'. Pump 50	OTHER. e all pertinent details, and MAC. For Multiple Cor higher from 10,602'. O	d give pertinent dates, impletions: Attach well of @ 8,150') or @ 8,150') orieta @ 6,273') whose @ 4,697') — woodes @ 3,043'; B.Salt @ 1 @ 2,000') et and belief. theDATE	including estimated date bore diagram of
OTHER: 13. Describe proposed or of starting any proposed proposed completion 1. MIRU. POOH w/rod 2. Set CIBP @ 10,200'. 3. Spot 25 sx (200') CI 14. Perf sqz holes @ 8,15 5. Perf sqz holes @ 6,27 6. Perf sqz holes @ 4,75 7. Perf sqz holes @ 2,00 9. Perf sqz holes @ 3,04 8. Perf sqz holes @ 390 10. Cut wellhead off. See 9# mud will be circul Spud Date: I hereby certify that the information of the complete of	completed operations. (Clearly state sed work). SEE RULE 19.15.7.14 Nor recompletion. pump, 2-7/8" & 2-3/8" production to Cap w/25 Cl H cement. Tag. CAP H @ 9,765' - 9,565'. (T. Wolfcamp @ 50'. Pump 45 sx (160') Cl H in/out @ 73'. Pump 35 sx (150') Cl C in/out @ 73'. P	OTHER. e all pertinent details, and MAC. For Multiple Cor higher from 10,602'. O	d give pertinent dates, impletions: Attach well of @ 8,150') or @ 8,150') orieta @ 6,273') whose @ 4,697') — woodes @ 3,043'; B.Salt @ 1 @ 2,000') et and belief. theDATE	including estimated date bore diagram of

DEC 0 2 2015

DEVON EN	ERGY PRODUCTION COMPANY LP
Well Name: STATE TD #1	Field: TOWNSEND
ocation: 990' FSL & 1980' FEL; SEC 2-T16S-R35	E County: LEA State: NM
Elevation: 4008' KB; 3997' GL; 11' KB to GL	Spud Date: 6/8/55 Compl Date: 8/5/55
API#: 30-025-02721 Prepared by: Ronnie Slack	Date: 7/29/15 Rev:
17-1/2" hole 13-3/8", 48#, H40, @ 339' Cmt'd w/400 sx, circ to surface	Proposed: 1. Perf sqz holes @ 390'. 2. Circ 90 sx (390') Cl C in/out to surface. 3. Cut wellhead off. Set dry hole marker.
HOBBS OCD NOV 1 6 2015	9# mud Proposed: 1. Perf sqz holes @ 2,000'. 2. Pmp 35 sx (150') Cl C in/out @ 2,000' - 1,850'. Tag. (T. Salt @ 2,000')
RECEIVED	Proposed: 1. Perf sqz holes @ 3,043'. 2. Pmp 50 sx (210') Cl C in/out @ 3,043' - 2,833'. Tag. (T. Yates @ 3,043'; B.Salt @ 2,905')
11" Hole 8-5/8", 32#, J55 & H40, @ 4,697' Cmt'd w/2100 sx, circ to surface	Proposed: 1. Perf sqz holes @ 4,750'. 2. Pmp 35 sx (150') Cl C in/out @ 4,750' - 4,600'. Tag.
Sqzd csg leak @ 5,210-5,241 w/250 sx (6/17/09)	9# mud
	Proposed: 1. Perf sqz holes @ 6,273'. 2. Pmp 35 sx (150') Cl C in/out @ 6,273' - 6,123'. (T.Glorieta @ 6,273')
TOC @ 8,320' (cbl-6/20/96)	Proposed: 1. Perf sqz holes @ 8,150'. 2. Pmp 45 sx (160') Cl H in/out @ 8,150' - 7,990'. (T.Abo @ 8,150')
	Proposed: Spot 25 sx (200') Cl H @ 9,765' - 9,565'. (T. Wolfcamp @ 9,763')
WOLFCAMP PERFS 10,265' - 10,293' (6/29/96) 10,340' - 10,370' (6/20/96) 10,385' - 10,395' (6/20/96) 10,460' - 10,480' (6/18/96) 10,490' - 10,507' (6/18/96) 10,530' - 10,584' (8/3/55)	Proposed: Set CIBP @ 10,200. Cap w/35' CI H cmt. Tag.
7-7/8" Hole 5-1/2", 15.5# & 17#, N80 & J55, @ 10,697' Cmt'd w/450 sx	Cmt retainer drilled out from 5,120, chased to 10,640 (6/23/0 10,653' PBD

