Ho	
Submit I Copy To Appropriate District State of New Mexico	Form C-103
District 1 - (575) 393-6161 JIII Energy Minerals and Natural Resource	Revised August 1, 2011
District II – (575) 393-6161 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District III – (505) Rd., Aztec	WELL API NO. 30-025-23304
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd, Aztec NM 87410 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Section 28
1. Type of Well: Oil Well Gas Well Other:	8. Well Number: 243
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	10. Foot name of windcat Hobbs (G/SA)
4. Well Location	
Unit LetterN:750feet from theSouth line and1	790feet from theWestline
Section 28 Township 18S Range	38E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, G	R, etc.)
3646' (GL)	
12 Check Appropriate Day to Indicate Nature of N	ation Report on Other Data
12. Check Appropriate Box to Indicate Nature of No.	otice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	
	CE DRILLING OPNS. P AND A
	EMENT JOB
OTHER: RU for failed Bradenhead test OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent deta	ails, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Section 2012 For Multiple	ple Completions: Attach wellbore diagram of
proposed completion or recompletion.	
1. MIRU PU Durin	g this procedure we plan to use
2. ND wellhead. NU BOP the c	losed-loop system with a steel
3. POOH with ESP equipment	and haul contents to the required
4. KIII W/ 7 (25#) KDI + 2 Joints tog + 95/8 (50#) packet	
5. Test top of liner dispo 6. Test backside	sarper oper material
 Once leak is isolated determine POA to fix 	
- Leak is believed to be coming from wellhead packoff, top of 7" liner, o	r from 9-5/8" casing. If leak is in the packoff, this
will be replaced. If leak is in the 9-5/8" casing or top of liner, the leak will be squeez	ed with cement and a 7" tie-back liner will be ran to
surface	
 Once well is repaired, RIH with ESP equipment ND BOP. NU Wellhead. 	Condition of Approval: notify
10. RDMO PU	Condition of Apploval: nothe
	OCD Hobbs office 24 hours
	OCD Hobbs office 24 hours
Spud Date: Rig Release Date: Pri	
Spud Date: Rig Release Date:	OCD Hobbs office 24 hours
	OCD Hobbs office 24 hours or of running MIT Test & Chart
	OCD Hobbs office 24 hours or of running MIT Test & Chart
I hereby certify that the information above is true and complete to the best of my know	OCD Hobbs office 24 hours or of running MIT Test & Chart owledge and belief.
I hereby certify that the information above is true and complete to the best of my known SIGNATURE	OCD Hobbs office 24 hours or of running MIT Test & Chart owledge and belief. erDATE06/01/2016
I hereby certify that the information above is true and complete to the best of my known SIGNATURE	OCD Hobbs office 24 hours or of running MIT Test & Chart owledge and belief. terDATE06/01/2016
I hereby certify that the information above is true and complete to the best of my known SIGNATURE	OCD Hobbs office 24 hours or of running MIT Test & Chart owledge and belief. terDATE06/01/2016