UNITED STATES OCD-HOBBS DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well				FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NMLC054667 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. Crosby Deep #3 9. API Well No. 30-025-11870 10. Field and Pool, or Exploratory Area Crosby Fusselman 11. County or Parish, State Lea Co., NM	
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYP	E OF ACTION		
If the proposal is to deepen dire Attach the Bond under which the	ectionally or recomplete horizont the work will be performed or provolved operations. If the operational Abandonment Notices shall y for final inspection.)	tally, give subsurface location rovide the Bond No. on file v ion results in a multiple come	ns and measured and with BLM/BIA. Requires or recompletion	Well Integrity Other Abandon al f any proposed work and approximate duration thereof. true vertical depths of all pertinent markers and zones. nired subsequent reports shall be filed within 30 days in in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has	
2. Circulate hole	e w/9# mud top of CIBP @ 8 ug @ 4000'			1232A 25262	
6. Set stub plug 7. Set 50 sx plug 8. Set 10 sx plug	50' in & out of g @ 1500'	f 7" stub & ta			
6. Set stub plug 7. Set 50 sx plug 8. Set 10 sx plug	50' in & out or g @ 1500' g @ 40' ole marker & res	f 7" stub & ta	1	on Analyst	
6. Set stub plug 7. Set 50 sx plug 8. Set 10 sx plug 9. Install dry ho 14. Thereby certify that the for Name (Printed/Typed)	50' in & out or g @ 1500' g @ 40' ole marker & res	f 7" stub & ta	Producti	on Analyst	
6. Set stub plug 7. Set 50 sx plug 8. Set 10 sx plug 9. Install dry ho 14. Ihereby certify that the for Name (Printed/Typed) Glenda Hunt	50' in & out or g @ 1500' g @ 40' ole marker & res	f 7" stub & ta store location Title	Producti 1/30/06		
6. Set stub plug 7. Set 50 sx plug 8. Set 10 sx plug 9. Install dry ho 14. Ihereby certify that the for Name (Printed/Typed) Glenda Hunt Signature Approved by MS Ba Conditions of approval, if any, ar certify that the applicant holds leg which would entitle the applicant	50' in & out or g @ 1500' g @ 40' cole marker & resorted to the second of this ac gal or equitable title to those right to conduct operations thereon.	f 7" stub & ta store location Title Date DR FEDERAL OR otice does not warrant or ghts in the subject lease	Producti 1/30/06 STATE OFFI Title A.E.	CE USE	

GMM