Submit 1 Copy To Appropriate District State of New Mexico	Form C-103				
Office <u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013				
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-025-36010 ✓				
District III – (505) 334-6178 District III – (505) 334-6178 District III – (505) 334-6178	5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 87410 ≤ 2000	STATE FEE				
District IV – (505) 476-3460 UI 0 0 2000 Santa Fe, INIVI 87505	6. State Oil & Gas Lease No. 27816				
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	STATE "I"				
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 2				
2. Name of Operator Energen Resources Corporation	9. OGRID Number 162928				
3. Address of Operator	10. Pool name or Wildcat				
3510 N. "A" St. Bldgs. A&B Midland, TX 79705	Saunders, San Andres 🧹				
4. Well Location Unit Letter N 990 feet from the South line and	1650 feet from the West line				
Section 4 Township 15-S Range 33-E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data				
NOTICE OF INTENTION TO: SUB	SEQUENT				
PERFORM REMEDIAL WORK D PLUG AND ABANDON X REMEDIAL WOR					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	P&A R				
CLOSED-LOOP SYSTEM					
OTHER: OTHER:					
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of 					
proposed completion or recompletion.	mprotonol i ritari i encore englian er				
See attached P&A proposed procedure and well bore diagrams.					
See allached i do proposed procedure and well bore diagrams.	Mayou				
THANK YOU!	wieg				
V					
NOTIFY OCD 24 HOURS					
Spud Date: R PLUGGING OPERATIONS	6				
I hereby certify that the information above is true and complete to the best of my knowledg	e and beller.				
Briel II.					
SIGNATURE Minda Muthyes	enDATE06/21/2016				
Type or print name Brenda F. Rathjen E-mail address: brathjen@ene	rgen.com PHONE: 432-688-3323				
For State Use Only	1				
APPROVED BY: Malletistalen TITLE Petroleum Engr.	Specialist DATE 7/5/2016				

Conditions of Approval (if any):

ENERGEN RESOURCES CORPORATION

STATE -I- 2, API # 30-025-36010

AFE # PB15500355, \$150,000 990' FSL & 1650' FWL Sec. 4, T-15-S, R-33-E Lea County, NM

The State -I- 2 was spud 10/14/02, and was completed 11/12/02 as a San Andres producer. It has been shut-in since September, 2015. The lease has been abandoned and lost due to lack of production. The well needs to be plugged and abandoned. There is fill in the casing to about 3155' that will have to be cleaned out, adding to the expense of the P&A.

For scope changes during work, stop and discuss with engineering before proceeding

API:	30-025-36010	KB:	4212'	PBTD: 5089'
Spud Date:	10/14/2002	GLE:	4206'	TD: 5135'

Plug and Abandon Procedure

SAFETY CONSIDERATIONS

Observe all Energen Guidelines for PPE and H2S Safety Observe perforation and contractor safety guidelines Wireline and explosives on location while perforating Workstring should be in good condition and tested to 5000 psi. BOP should be in good working condition and tested Rig anchors will need to be tested prior to MIRU Keep a TIW valve open and on the rig floor at all times Notify the NM OCD 24 hours prior to starting P&A operations Meet with engineer, superintendents, and consultant prior to beginning the job, to assure that everyone is agreement with the procedure.

- MIRU Well Service Unit.
- 2 NDWH
- 3 NU adapter flange and BOP for 5-1/2" csg and 2-7/8" tubing. Test to 500 psi above working pressure.
- 4 Unload and rack 5,000' 2-7/8" workstring. Maintain kill truck w/10 ppg brine on location.
- 5 RIH with workstring. Circulate hole with mud.
- 6 PU & RIH w/bit, DC's, XO, 2-7/8" workstring and tag fill.
- 7 RU swivel and stripper, test casing, and clean-out fill to below 4900'
- 8 Circulate hole clean, then circulate hole with 10 ppg mud
- 9 Set CIBP @ 4900'
- 10 Dump bail 5 sx cmt or 25 sx through tubing on top CIBP. All cement to be Class "
- 11 Spot 25 sx Class, "A" cmt @ 3000', base of salt sections
- 12 Spot 25 sx Class "H" cmt @ 2000' top of salt sections
- 13 Spot Class "If" cmt from 507' to surface (shoe).
- 14 ND BOP. Top off well with cement. RD and clean location.
- 15 Verify cmt to surface all strings.
- 16 Cut off all casing strings at base of cellar or 3' below restored ground level.
- 17 Cover wellbore with metal plate welded in place or with cement cap.
- 18 Erect capped abandonment marker inscribed with well information.
- 19 Cut off dead man anchors and fill in cellar. RDMO.
- 20 Clean and restore location to natural condition and fulfill any and all regulatory requirements.

C Spot 25 5x at 4056 (DV Tool) WOC & TAG Test csg; report

verify cement to surface

ENERGEN RESOURCES CORP

State I-2

Spud: 11/14/2002



GL Elevation: 4206'

KB Elevation: 4212'

