District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Fee

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

ces	R	E	С	E	h	F		r
ces				-	a 8		Control I	٩.,

FEB 2 3 2011

HOBBSOCD

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

	OPER	ATOR	🛛 Initial Repo	ort 🛛 Final Report
Name of Company	OGRID Number	Contact		
Yates Petroleum Corporation	25575	Robert Asher		
Address		Telephone No.		
104 S. 4 TH Street		575-748-1471		
Facility Name	API Number	Facility Type		
Gill BGJ #1	30-025-37103	Battery		
Surface Owner	Mineral Owner	r	Lease No.	

LOCATION OF RELEASE

Jnit Letter L	Section 29	Township 19S	Range 35E	Feet from the 1650	North/South Line South	Feet from the 660	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	--------------------	---------------------------	-------------------	------------------------	---------------

Latitude 33.50238 Longitude 103.38888

NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Oil 20 B/O 15 B/O Date and Hour of Occurrence Source of Release Date and Hour of Discovery **Production Tank** 2/8/2010, PM 2/8/2010, PM If YES, To Whom? Was Immediate Notice Given? Yes No X Not Required N/A Date and Hour By Whom? N/A N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. 🗌 Yes 🖾 No N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Equipment malfunction (knockout dumps not working properly) caused release on production tank. Vacuum truck called. Describe Area Affected and Cleanup Action Taken.* An approximate area of 15' X 40' (south side of battery) & 100' X 100' (overspray outside of fence on fee surface). Vacuum truck recovered oil inside bermed/lined battery, because of high winds at time of release approximately 5 B/O were not recovered and impacted area south of battery. Those soils were excavated at a depth of 6" and taken to an NMOCD approved facility. Initial samples taken and analysis ran for TPH & BTEX, based on results an additional 12" of impacted soils being excavated and taken to an NMOCD approved facility. Per the fee surface owner, Yates has been instructed to fence off overspray area, and microblaze applied, the area will be monitored and remediated per surface owner's request. Depth to Ground Water: >100' (approx. 135', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on enclosed analytical results, impacted soils excavated/removed, battery lined, Yates Petroleum Corporation requests closure. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Robert Asher Title: Environmental Regulatory Agent Approval Date: **Expiration Date:** E-mail Address: boba@yatespetroleum.com Conditions of Approval: Attached

1RP-

Date: Monday, February 21, 2011 Phone: 575-748-4217 * Attach Additional Sheets If Necessary

Latitude 33.50238 Longitu

	Well Head	R
		,
Lease Road		
	Battery (Bermed & Lined)	
Fence	X X Excavation/Sample Area	
	Overspray Area (Fenced off)	

Analytical Report- 407075	Sample Area	Sample Date	Sample Type	Depth	BTEX	GRO	DRO	TOTAL
Comp-00.5	Release Area	2/16/2011	Comp/Auger	6" (12" BSL)	5.650	930	1280	2210
Comp-01.0	Release Area	2/16/2011	Comp/Auger	12" (18" BSL)	0.300	1580	3610	5190
Comp-01.5	Release Area	2/16/2011	Comp/Auger	18" (24" BSL)	0.006	ND	20	20

Site Ranking is Zero (0). Depth to Ground Water >100' (approx. 135', per Trend Map).

All results are ppm. BSL - Below Surface Level. X - Sample Points

Released: 20 B/O; Recovered: 15 B/O. Release Date: 2/8/2011



Gill BGJ #1

30-025-37103

Section 29, T9S-R35E

Lea County, NM

SAMPLE DIAGRAM (Not to Scale)

Xenco Laboratories: #407075 Report Date: 2/18/2011

Prepared by Robert Asher Environmental Regulatory Agent

Analytical Report 407075

for Yates Petroleum Corporation

Project Manager: Robert Asher

Gill BGJ #1

30-025-37103

18-FEB-11

RECEIVED

FEB 2 3 2011 HOBBSOCD



Celebrating 20 Years of commitment to excellence in Environmental Testing Services



12600 West I-20 East Odessa, Texas 79765

Xenco-Houston (EPA Lab code: TX00122): Texas (T104704215-10-6-TX), Arizona (AZ0738), Arkansas (08-039-0), Connecticut (PH-0102), Florida (E871002) Illinois (002082), Indiana (C-TX-02), Iowa (392), Kansas (E-10380), Kentucky (45), Louisiana (03054) New Hampshire (297408), New Jersey (TX007), New York (11763), Oklahoma (9218), Pennsylvania (68-03610) Rhode Island (LAO00312), USDA (S-44102)

Xenco-Atlanta (EPA Lab Code: GA00046): Florida (E87429), North Carolina (483), South Carolina (98015), Utah (AALI1), West Virginia (362), Kentucky (85) Louisiana (04176), USDA (P330-07-00105)

> Xenco-Miami (EPA Lab code: FL01152): Florida (E86678), Maryland (330) Xenco-Tampa Mobile (EPA Lab code: FL01212): Florida (E84900) Xenco-Odessa (EPA Lab code: TX00158): Texas (T104704400-TX) Xenco-Dallas (EPA Lab code: TX01468): Texas (T104704295-TX) Xenco-Corpus Christi (EPA Lab code: TX02613): Texas (T104704370) Xenco-Boca Raton (EPA Lab Code: FL01273): Florida(E86240),South Carolina(96031001), Louisiana(04154), Georgia(917) North Carolina(444), Texas(T104704468-TX), Illinois(002295), Florida(E86349)

Xenco Phoenix (EPA Lab Code: AZ00901): Arizona(AZ0757), Texas(104704435-10-2), Nevada(NAC-445A), DoD(65816) Xenco-Phoenix Mobile (EPA Lab code: AZ00901): Arizona (AZM757) Xenco Tucson (EPA Lab code: AZ000989): Arizona (AZ0758)

Final 1.000



18-FEB-11



Project Manager: Robert Asher Yates Petroleum Corporation 105 South Fourth St. Artesia, NM 88210

Reference: XENCO Report No: 407075 Gill BGJ # 1 Project Address: Lea County

Robert Asher:

We are reporting to you the results of the analyses performed on the samples received under the project name referenced above and identified with the XENCO Report Number 407075. All results being reported under this Report Number apply to the samples analyzed and properly identified with a Laboratory ID number. Subcontracted analyses are identified in this report with either the NELAC certification number of the subcontract lab in the analyst ID field, or the complete subcontracted report attached to this report.

Unless otherwise noted in a Case Narrative, all data reported in this Analytical Report are in compliance with NELAC standards. Estimation of data uncertainty for this report is found in the quality control section of this report unless otherwise noted. Should insufficient sample be provided to the laboratory to meet the method and NELAC Matrix Duplicate and Matrix Spike requirements, then the data will be analyzed, evaluated and reported using all other available quality control measures.

The validity and integrity of this report will remain intact as long as it is accompanied by this letter and reproduced in full, unless written approval is granted by XENCO Laboratories. This report will be filed for at least 5 years in our archives after which time it will be destroyed without further notice, unless otherwise arranged with you. The samples received, and described as recorded in Report No. 407075 will be filed for 60 days, and after that time they will be properly disposed without further notice, unless otherwise arranged with you. We reserve the right to return to you any unused samples, extracts or solutions related to them if we consider so necessary (e.g., samples identified as hazardous waste, sample sizes exceeding analytical standard practices, controlled substances under regulated protocols, etc).

We thank you for selecting XENCO Laboratories to serve your analytical needs. If you have any questions concerning this report, please feel free to contact us at any time.

Respectfully,

BOR

Brent Barron, II Odessa Laboratory Manager

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America



Sample Cross Reference 407075



Yates Petroleum Corporation, Artesia, NM

Gill BGJ # 1

Sample Id	Matrix	Date Collected	Sample Depth	Lab Sample Id
Comp-00.5	S	Feb-16-11 10:19	6 - 6 In	407075-001
Comp-01.0	S	Feb-16-11 10:32	12 - 12 In	407075-002
Comp-01.5	S	Feb-16-11 10:47	18 - 18 In	407075-003

CASE NARRATIVE



Client Name: Yates Petroleum Corporation Project Name: Gill BGJ # 1



 Project ID:
 30-025-37103

 Work Order Number:
 407075

Report Date: 18-FEB-11 Date Received: 02/17/2011

Sample receipt non conformances and Comments: None

Sample receipt Non Conformances and Comments per Sample:

None

Analytical Non Conformances and Comments:

Batch: LBA-844211 BTEX by EPA 8021B SW8021BM

Batch 844211, Benzene, Ethylbenzene, Toluene, m_p-Xylenes, o-Xylene recovered below QC limits in the Matrix Spike. Samples affected are: 407075-002, -001, -003. The Laboratory Control Sample for Toluene, Benzene, Ethylbenzene, m_p-Xylenes, o-Xylene is within laboratory Control Limits

SW8021BM

Batch 844211, 1,4-Difluorobenzene recovered below QC limits . Matrix interferences is suspected; data confirmed by re-analysis Samples affected are: 407075-001. 4-Bromofluorobenzene recovered above QC limits . Matrix interferences is suspected; data confirmed by re-analysis Samples affected are: 407075-002,407075-001.

Batch: LBA-844225 TPH By SW8015B Mod



Certificate of Analysis Summary 407075

Yates Petroleum Corporation, Artesia, NM

Project Name: Gill BGJ # 1



Project Id: 30-025-37103 Contact: Robert Asher Project Location: Lea County

Date Received in Lab: Thu Feb-17-11 09:45 am

Report Date: 18-FEB-11

Project Manager: Brent Barron, II

	Lab Id:	407075-001	407075-002	407075-003		
	Field Id:	Comp-00.5	Comp-01.0	Comp-01.5		
Analysis Requested	Depth:	6-6 In	12-12 In	18-18 In		-
	Matrix:	SOIL	SOIL	SOIL		
	Sampled:	Feb-16-11 10:19	Feb-16-11 10:32	Feb-16-11 10:47		
BTEX by EPA 8021B	Extracted:	Feb-17-11 14:23	Feb-17-11 14:23	Feb-17-11 14:23		
	Analyzed:	Feb-17-11 19:54	Feb-17-11 18:00	Feb-17-11 16:52		
	Units/RL:	mg/kg RL	mg/kg RL	mg/kg RL		
Benzene		0.0880 0.0496	ND 0.00495	ND 0.000996		
Toluene		0.570 0.0992	ND 0.00990	ND 0.00199		
Ethylbenzene		2.84 0.0496	0.115 0.00495	0.00312 0.000996		
m_p-Xylenes	m_p-Xylenes		0.130 0.00990	0.00242 0.00199		
o-Xylene		0.810 0.0496	0.0549 0.00495	0.00109 0.000996		
Total Xylenes		2.15 0.0496	0.185 0.00495	0.00351 0.000996		
Total BTEX		5.65 0.0496	0.300 0.00495	0.00663 0.000996		
Percent Moisture	Extracted:					
	Analyzed:	Feb-17-11 17:00	Feb-17-11 17:00	Feb-17-11 17:00		
	Units/RL:	% RL	% RL	% RL		
Percent Moisture		11.6 1.00	10.4 1.00	9.54 1.00		
TPH By SW8015B Mod	Extracted:	Feb-17-11 11:00	Feb-17-11 11:00	Feb-17-11 11:00		
	Analyzed:	Feb-17-11 15:12	Feb-17-11 15:31	Feb-17-11 15:50	11	
	Units/RL:	mg/kg RL	mg/kg RL	mg/kg RL		
C6-C10 Gasoline Range Hydrocarbons		930 16.9	1580 166	ND 16.5		
C10-C28 Diesel Range Hydrocarbons		1280 16.9	3610 166	20.0 16.5		
Total TPH		2210 16.9	5190 166	20.0 16.5		

on stratysis Strandfra

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories. XENCO Laboratories assumes no responsibility and makes no warranty to the end use of the data hereby presented. Our liability is limited to the amount invoiced for this work order unless otherwise agreed to in writing.

Houston - Dallas - San Antonio - Atlanta - Tampa - Boca Raton - Latin America - Odessa - Corpus Christi

Brent Barron, II

Odessa Laboratory Manager

Final 1.000



Flagging Criteria

- X In our quality control review of the data a QC deficiency was observed and flagged as noted. MS/MSD recoveries were found to be outside of the laboratory control limits due to possible matrix /chemical interference, or a concentration of target analyte high enough to effect the recovery of the spike concentration. This condition could also effect the relative percent difference in the MS/MSD.
- **B** A target analyte or common laboratory contaminant was identified in the method blank. Its presence indicates possible field or laboratory contamination.
- **D** The sample(s) were diluted due to targets detected over the highest point of the calibration curve, or due to matrix interference. Dilution factors are included in the final results. The result is from a diluted sample.
- E The data exceeds the upper calibration limit; therefore, the concentration is reported as estimated.
- F RPD exceeded lab control limits.
- J The target analyte was positively identified below the MQL and above the SQL.
- U Analyte was not detected.
- L The LCS data for this analytical batch was reported below the laboratory control limits for this analyte. The department supervisor and QA Director reviewed data. The samples were either reanalyzed or flagged as estimated concentrations.
- **H** The LCS data for this analytical batch was reported above the laboratory control limits. Supporting QC Data were reviewed by the Department Supervisor and QA Director. Data were determined to be valid for reporting.
- K Sample analyzed outside of recommended hold time.

JN A combination of the "N" and the "J" qualifier. The analysis indicates that the analyte is "tentatively identified" and the associated numerical value may not be consistent with the amount actually present in the environmental sample.

BRL Below Reporting Limit.

RL Reporting Limit

MDL Method Detection Limit

PQL Practical Quantitation Limit

* Outside XENCO's scope of NELAC Accreditation.

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994. Certified and approved by numerous States and Agencies. A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Corpus Christi - Midland/Odes	sa - Tampa - Miami	- Latin America
	Phone	Fax
4143 Greenbriar Dr. Stafford, Tx 77477	(281) 240-4200	(281) 240-4280
9701 Harry Hines Blvd, Dallas, TX 75220	(214) 902 0300	(214) 351-9139
5332 Blackberry Drive, San Antonio TX 78238	(210) 509-3334	(210) 509-3335
2505 North Falkenburg Rd, Tampa, FL 33619	(813) 620-2000	(813) 620-2033
5757 NW 158th St, Miami Lakes, FL 33014	(305) 823-8500	(305) 823-8555
12600 West I-20 East, Odessa, TX 79765	(432) 563-1800	(432) 563-1713
842 Cantwell Lane, Corpus Christi, TX 78408	(361) 884-0371	(361) 884-9116

Final 1.000

Environmental Lab of Texas

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

A Xence	o Laboratories Compar	ту							-	500 ess																	2-563 2-563						
	Project Manager: Ro	obert Asher																Pro	ject	Na	me:	Gi	II B	BG.	J #1	1	-						
	Company Name Ya	ates Petroleum Corporat	ion																Pr	ojec	:t #:_	30-	025	5-37	103	3							
	Company Address: 10	05 South 4th Street																P	roje	ect L	.oc:	Lea	Cou	unty									_
	City/State/Zip: Ar	tesia, NM 88210														_				P) #: .	105	632										_
	Telephone No: 57	5748 4217				Fax No:		575	5-74	8-46	62						Re	por	t Foi	rmat	e	X	Star	ndar	d	[TRR	P		NP	DES	1
	Sampler Signature:	ture.	1	•		e-mail:		bo	ba	@)	ate	esp	etr	ole	um	.CO	m	_	_			-	-	An	alyz	e Fr	or:						1
(lab use o																			E			TO	LP:		alyz		1	Τ	Τ	Τ	Т	48, 72 hrs	
ORDER	x#: 40707	5								Prese	rvatio	on &	# of (Conta	iners	1	Ma	rix	8015B					g Se			260					24, 48, 7	
LAB # (lab use only)	FIELD	CODE	Beginning Depth	Ending Depth	Date Sampled	Time Sampled	Field Filtered	Total #. of Containers	Ice	HNO ₃	HCI	H ₂ SO ₄	NaOH	Na ₂ S ₂ O ₃	None	scify)	DW=Drinking Water SL=Sludge GW = Groundwater S=Sol/Solid	e	TPH: 418.1 8015M 80	TPH: TX 1005 TX 1006	Cations (Ca, Mg, Na, K)	Anions (Cl, SO4, Alkalinity)	SAR / ESP / CEC	Metals: As Ag Ba Cd Cr Pb Hg	Volatiles	Semivolatiles	BTEX 8021B/5030 or BTEX 8260	RCI	N.O.R.M.	Chlorides		RUSH TAT (Pre-Schedule) 2-	Standard TAT
01	Comp		6"	6"	2/16/2011	10:19 AM	u	Ē	х								S	-	х								х			T	T	x	
20	Comp	-01.0	12"	12"	2/16/2011	10:32 AM			х								S	;	x				_				X	-	-	-	+	X	-
03	Comp	-01.5	18"	18"	2/16/2011	10:47 AM			X						-		S	;	X				_			_	X	_	+	+	+	X	
								_			_				-	+										_			_	+	\pm		
-							_				_	-										_						_	-	\pm	+	E	
				-			_	_	-	_	_		_	-	-	+		_	\vdash			-	-	_	-	-	+	+	+	+	+	┝	-
Relinquish Robert As	ther LENIARC	TPH 8015M & B Date 02/16/11	Ti 2:30	me D PM	Received by:	in mg/kg.										Date			Tim	e	Cus	els (tody	Cor ree on co sea sea	of H onta als o	leads liner(on co	Inta space (s) ontai ooler	iner(s)	<u>(</u> S)		ABARAR -)	2 2 2 2 2 2	
Relinquist Relinquist		Date		me	Received by: Received by ELC	ua Ela	w	n								Date	e	9	Time Time	e	San	by S	amo	lock	lient	t Re	ap. ? 5 (ceipt:	DHL	(*	edE		N ne St °C	ar



XENCO Laboratories

Atlanta, Boca Raton, Corpus Christi, Dallas Houston, Miami, Odessa, Philadelphia

Phoenix, San Antonio, Tampa

Document Title: Sample Receipt Checklist Document No .: SYS-SRC Revision/Date: No. 01, 5/27/2010

Effective Date: 6/1/2010 Page 1 of 1

Prelogin / Nonconformance Report - Sample Log-In

Client:	Yates Petroleum	
Date/Time:	2.17 11 9:45	e
Lab ID # :	407075	
Initials:	AZ	

Sample Receipt Checklist

1. Samples on ice?	Blue	Water	No	
2. Shipping container in good condition?	(Yes)	No	None	
3. Custody seals intact on shipping container (cooler) and bottles?	Yes	No	N/A	
4. Chain of Custody present?	Yes	No		
5. Sample instructions complete on chain of custody?	Yes	No		
6. Any missing / extra samples?	Yes	No		
7. Chain of custody signed when relinquished / received?	(Lee	No		
8. Chain of custody agrees with sample label(s)?	Tes	No		
9. Container labels legible and intact?	Nes	No		
10. Sample matrix / properties agree with chain of custody?	Yes	No		1.7.
11. Samples in proper container / bottle?	(Tes)	No		
12. Samples properly preserved?	(Yes)	No	N/A	
13. Sample container intact?	Tes	No	1	
14. Sufficient sample amount for indicated test(s)?	Tes	No		
15. All samples received within sufficient hold time?	(Yes)	No		
16. Subcontract of sample(s)?	Yes	No	NA	
17. VOC sample have zero head space?	(Yes)	No	N/A	
18. Cooler 1 No. Cooler 2 No. Cooler 3 No.	Cooler 4 No	0.	Cooler 5 No.	
Ibs / °C Ibs °C ibs °C	lbs	°C	lbs	°C

Nonconformance Documentation

Contact:	Contacted by:	Date/Time:	
Regarding:			
Corrective Action Taken:			

condition acceptable by NELAC 5.5.8.3.1.a.1. Initial and Backup Temperature confirm out of temperature conditions

Client understands and would like to proceed with analysis