	·				
Form 3160-5 (April2004)	UNITEDSTATES		FORMAPPROVED OM B No. 1004-0137		
	DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGE	GD-HOBBS	Expires: March 31, 2007 5. Lease Serial No.		
	NOTICES AND REPORTS		LC - 063458		
Do not use th abandoned w	nis form for proposals to drill ell. Use Form 3160-3 (APD) fo	or to re-enter an or such proposals.	6. If Indian, Allottee or Tribe Name		
	PLICATE - Other instructions	on reverse side.	7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well []	8. Well Name and No.				
2. NameofOperator ConocoPhillips Compa	Warren Unit Blinbry Tubb #64 9. API Well No.				
3a. Address					
4001 Penbrook Street C 4. Location of Well (Footage, Se	10. Field and Pool, or Exploratory Area Warren Blinbry Tubb O&G				
4. Location of Wein (Footage, Se 660 FNL & 660 FEL	11. County or Parish, State				
UL."A", Sec.26, T20S, R	Lea New Mexico				
12. CHECK AI	PPROPRIATE BOX(ES)TO INDICA	ATE NATURE OF NOTICE.			
TYPE OF SUBMISSION		TYPEOF ACTION	· · · · · · · · · · · · · · · · · · ·		
X Noticeof Intent	Acidize Deep	·	Start/Resume) Water Shut-Off		
Subsequent Report		Construction Recomplete	Other		
Final Abandonment Notice	Change Plans Pluga	and Abandon X Temporarily Back Water Dispo	······································		
determined that the site is ready ConocoPhillips reques		bandon the well refere	clamation, have been completed, and the operator has		
(See attached procedu	res)		- · · · · · · · · · · · · · · · · · · ·		
APPROVAL SUB General Requ And Special S Attached	JIREMENTS		APPROVED MITONLY MAR 15 2006 LES BABYAK PETROLEUM ENGINEER		
14. I hereby certify that the foreg Name (Printed/Typed)	going is true and correct		· · · · · · · · · · · · · · · · · · ·		
John Abney		Title SHEaR Spec	ialist		
Signature	Almen	Date 03/03/2006			
- Just	THIS SPACE FOR FEDER	AL OR STATE OFFICI	EUSE		
	· · ·				
Approved by Conditions of approval, if any, are a certify that the applicant holds lega which would entitle the applicant	attached. Approval of this notice does not v l or equitable title to those rights in the sub to conduct operations thereon.	Title warrant or ject lease Office	Date		
Title 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraud	le 43 U.S.C. Section 1212, make it a crime foulent statements or representations as to a	or any person knowingly and willfu any matter within its jurisdiction.	Ily to make to any department or agency of the United		
(Instructions on page 2) GWW					

(

ConocoPhillips

Job Setup

WARREN UNIT 064

A CONTRACTOR OF THE OWNER				STATISTICS STATISTICS STATISTICS					
Well Setup									
Legal WellName	Common WellName	Operator	Country	BU/JV Lower 48 - MA	Region/Division	District PERMIAN			
WARREN UNIT 064 Lat/Long Datum	64 Latitude (DMS)	CONOCOPHILLIPS	USA Field Name	Well Type	Hole Type				
Laveong Datam	32° 32' 58.02" N	103° 6' 44.28" E	BLINEBRY	ROD PUMP	The Type	HOBBS			
Orig KB Elev (ft)	Ground Elevation (ft)	CF Elev (ft)	TH Elev (ft)	Mud Line Elevation (ft)	Water Depth (ft)	ConocoPhillips WI (%)			
3,575.00	3,564.00	0.00	0.00						
API/Bottom Hole UWI	Drillsite	Platform	Slot / Conductor	Spud Date	Rig Release Date	Abandon Date			
300252620600	<u> </u>			4/12/1979	4/27/1979				
Directions To Well									
Hot Notes					1.0				
	Туре	100		Comment.					
					6. ja 19. ja				
Job Setup Job Category	Primary Job Type	Secondary Job	Type Planned S	tart Date Start D	ato	End Date			
COMPLETIONS	ABANDONMENT		rype Flanned S		30/2006 00:00				
AFE / RFE / Maint#	Est Payout,days	MaxWell Job N	umber Network N			Producer or Injector Type			
					-				
Objective									
ConocoPhillips Co. Warren Unit Blinebry Tubb #64									
API # 30-025-26206-0000									
Sec.26-T20S-R38E									
Lea County, New Mex	kico								
PROPOSED TEMPORARY ABANDONMENT PROCEDURE TO ANALYZE OPPORTUNITIES:									
				•					
1. Prior to temp	orary abandonment, sn	oot static fluid level an	d record static surfac	e pressures in order to a	aid in reservoir ana	IYSIS.			
2. MIRU pulling	unit. ND weilhead, NU	BOP							
 POOH with production equipment and send in for inspections to evaluate cost to put well back on production, convert to injection or P&A. 									
4. RIH with working tubing string, bit & scraper to PBTD at ± 6844'. POOH w/tubing, bit & scraper.									
5. RIH w/ RBP & Packer for 7", K55, 23 lb/ft casing, set RBP within 50' above top perforation at 6012'.									
6. POOH with one joint of tubing and set Packer and pressure test PBP by pressuring up on tubing; follow by pressure testing the backside above									
packer.	no joint of tabing and s	cer acter and pressure	c test i by pressu	ing up on tubing, ionow	by pressure testing	g the backside above			
. If the casing does not hold pressure, proceed to pull up the hole with the tubing and packer, pressure testing to isolate any casing leak.									
. POOH w/Tubing and Packer.									
9. Circulate inhibited fluid including Biocide. POOH, LD tubing.									
10. Pressure test casing to 500 psi for 30 min. Release pressure.									
11. Send chart to John Abney to finalize TA. Change status of well to TA. Temporarily Abandoned.									
12. ND BOP, NU wellhead, RDMO.									
ejl									
•									