

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
En Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28817
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CrownQuest Operating, LLC		6. State Oil & Gas Lease No. B-10076
3. Address of Operator P.O. Box 53310, Midland, TX 79710		7. Lease Name or Unit Agreement Name New Mexico -AT- State
4. Well Location Unit Letter E : 1980 feet from the N line and 660 feet from the W line Section 15 Township 14S Range 33E NMPM County Lea		8. Well Number 13
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4212' GL		9. OGRID Number 213190
		10. Pool name or Wildcat Sauders Permo Upper Penn 55120

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT

REMEDIAL WORK
COMMENCE DRILLING OPNS
CASING/CEMENT JOB

INT TO P&A PM
P&A NR
P&A R

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @ 9740'. Circulate hole w/ mud laden fluid. Spot 25 sx cmt on top of CIBP. Pressure test csg.
2. Spot 25 sx @ 7045-6945'. (DV Tool) TAG
3. Spot 25 sx @ 4216-4116'. (Shoe) WOC & TAG
4. Spot 25 sx @ 2650-2500'.
5. Spot 25 sx @ 1750-1600'. WOC & TAG.
6. Spot 100 sx @ 575-surface.
7. Verify cmt to surface, cut off Well Head, weld on Dry Hole Marker.

Spud Date:

Rig Re

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ben Montgomery
Ben Montgomery

TITLE

Agent

DATE

12/14/16

Type or print name

Ben Montgomery

E-mail address:

BenM@Bemandassociates.com

PHONE:

432-580-7161

For State Use Only

APPROVED BY:

Maria C. Litala

TITLE

Petroleum Engr. Specialist

DATE

12/14/2016

Conditions of Approval (if any):

Wellbore Schematic (From Surface to TD)

Printed: 12/9/2016

Page 3

New Mexico AT State # 13



