

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Er. y, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-28819
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-9380
7. Lease Name or Unit Agreement Name New Mexico -AQ- State NCT 11
8. Well Number 3
9. OGRID Number 213190
10. Pool name or Wildcat Baum, Wolfcamp, South (04967)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
CrownQuest Operating, LLC

3. Address of Operator
P.O. Box 53310, Midland, TX 79710

4. Well Location
Unit Letter **K** : **1980** feet from the **S** line and **1980** feet from the **W** line
Section **3** Township **14S** Range **33E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4225' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐	

SUBSEQUENT

REMEDIAL WORK	INT TO PA PM
COMMENCE DRILLING OPNS	P&A NR
CASING/CEMENT JOB	P&A R

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @ 9165' w/ 25 sxs cmt. Circulate hole w/ mud laden fluid. Pressure test csg.
2. Spot 35 sx cmt @ 7165-6865'. DV Tool, TAG.
3. Spot 25 sx cmt @ 4210-4109. TAG (Shoe)
4. Spot 25 sx cmt @ ~~2200-2100~~ **2600'** spot 25 sx cmt @ 1700'
5. Spot 150 sx cmt @ 577-Surface.
6. Verify cmt to surface, cut off Well head, Weld on Dry Hole Marker.

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING
PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE **Ben Montgomery** TITLE **Agent** DATE **12/14/16**
Type or print name **Ben Montgomery** E-mail address: **BenM@Bumandassociates.com** PHONE: **432-580-7161**
For State Use Only
APPROVED BY: **Mark Whetstone** TITLE **Petroleum Engr. Specialist** DATE **12/14/2016**
Conditions of Approval (if any):

Wellbore Schematic (From Surface to TD)

Printed: 12/9/2016

Page 2

New Mexico AQ State NCT 11 # 3



Wellbore Schematic (From Surface to TD)

Printed: 12/9/2016

Page 2

