

DEC 14 2016

Form C-103

Revised July 18, 2013

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
District II - (575) 748-1283
District III - (505) 334-6178
District IV - (505) 476-3460

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form with fields: 1. Type of Well: Oil Well [X] Gas Well [ ] Other [ ]; 2. Name of Operator: Resolute Natural Resources Co., LLC; 3. Address of Operator: 1700 Lincoln St, Ste 2800 Denver, CO 80203; 4. Well Location: Unit Letter C, Section 1, Township 15S, Range 37E, NMPM, County Lea; 5. Indicate Type of Lease: STATE [ ] FEE [X]; 6. State Oil & Gas Lease No.; 7. Lease Name or Unit Agreement Name: Priest; 8. Well Number: 3; 9. OGRID Number: 295770; 10. Pool name or Wildcat: Devonian; 11. Elevation: 3808' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [X]
TEMPORARILY ABANDON [ ] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ] MULTIPLE COMPL [ ]
DOWNHOLE COMMINGLE [ ]
CLOSED-LOOP SYSTEM [ ]
OTHER: [ ]

SUBSEQUENT RE
REMEDIAL WORK [ ]
COMMENCE DRILLING OPNS. [ ]
CASING/CEMENT JOB [ ]
OTHER: [ ]

INT TO PA [X]
P&A NR
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Resolute proposes to plug and abandon the subject well by the following:

- 1. Tag bottom @ ±5,023' and circulate hole with mud. Pressure test csg to 500psi
2. Perf @ 4,800' and squeeze 8 5/8" shoe with 30 sacks. Wait on cement and tag.
3. Perf @ 3,100' and squeeze with 30 sacks. Wait on cement and tag.
4. Perf @ 2,200' and squeeze with 30 sacks. Wait on cement and tag.
5. Perf @ 397' and circulate cement to surface.
6. Remove wellhead and confirm cement to surface on all strings.
7. Install dry hole marker and remove anchors 3' below ground level.
8. Restore surface to condition prior to drilling.
9. Have NMOCD inspect P & A location

Spud Date: [ ]

Rig Release Date: [ ]

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sherry Glass TITLE Sr Regulatory Analyst DATE 12-13-16

Type or print name Sherry Glass E-mail address: sglass@resoluteenergy.com PHONE: 303-573-4886


For State Use Only

APPROVED BY: Mark Witzke TITLE Petroleum Engr. Specialist DATE 12/15/2016

Conditions of Approval (if any):

Priest # 3 - 660' FNL & 1650' FWL of Sec. 1, T-15S, R-37E, Unit Letter "C"  
 API # 30-025-09863

Spud: 9/28/52  
 Compl:  
 KB: 3809'



Priest # 3 - 660' FNL & 1650' FWL of Sec. 1, T-15S, R-37E, Unit Letter "C"  
 API # 30-025-09863

Spud: 9/28/52  
 Compl:  
 KB: 3809'

