

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21924	✓
5. Indicate Type of Lease STATE ☒ FEE ☐	✓
6. State Oil & Gas Lease No. B-9560	
7. Lease Name or Unit Agreement Name New Mexico -BG- State NCT 1	✓
8. Well Number 3	✓
9. OGRID Number 213190	✓
10. Pool name or Wildcat Sauders; Perm Upper Penn	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ **HOBBS OCD**

2. Name of Operator
CrownQuest Operating, LLC

3. Address of Operator
P.O. Box 53310, Midland, TX 79710

4. Well Location
Unit Letter **K** : **1980** feet from the **S** line and **1651** feet from the **W** line
Section **14** Township **14S** Range **33E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4295' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING/CEMENT JOB

INT TO PA **Dr. ✓**
P&A NR
P&A R

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- SQUEEZE 9754'**
1. Tag Top of Fish @ 7918'. Spot 135 sx cmt @ 7910-10,000'.
 2. Circulate hole w/ mud laden fluid. Pressure test csg. **SPOT 25 sx on top of fish. Perf at 6000'. Sg 2 w/ 30 sx. WOC & TAG (Spacer plug)**
 3. Cut 4 1/2 csg @ **4150' POH 4200'**
 4. Spot 50 sx cmt @ **4200-4100' WOC & TAG. 4250'-4050'**
 5. Spot 50 sx @ **2650-2550'**
 6. Spot 50 sx @ **1750-1600' WOC & TAG (Salt). 1850'-1700'**
 7. Spot 60 sx @ 415 to surface.
 8. Cut off Well Head, verify cmt to surface, weld on Dry Hole Marker.

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

Spud Date:

Rig Release

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 12-15-16

Type or print name Ben Montgomery E-mail address: Benm@Bcmandassociates.com PHONE: 432-580-7116

For State Use Only

APPROVED BY: Mable Whitaker TITLE Petroleum Engr. Specialist DATE 12/22/2016


Conditions of Approval (if any):

mw

Wellbore Schematic (From Surface to TD)

Printed: 12/14/2016

Page 1



New Mexico BG State NCT 1 # 3

