

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-01139	✓
5. Indicate Type of Lease STATE ☒ FEE ☐	✓
6. State Oil & Gas Lease No. B-9385	
7. Lease Name or Unit Agreement Name New Mexico AN State	✓
8. Well Number 4	✓
9. OGRID Number 213190	✓
10. Pool name or Wildcat Saunders	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ ✓

2. Name of Operator
CrownQuest Operating, LLC

3. Address of Operator
P.O. Box 53310, Midland, TX 79710

4. Well Location
Unit Letter **P** : **660** feet from the **South** line and **660** feet from the **East** line
Section **22** Township **14S** Range **33E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4,201 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT I

REMEDIAL WORK [**INT TO PA** ✓
COMMENCE DRILLING OPNS. [**P&A NR** _____
CASING/CEMENT JOB [**P&A R** _____

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag CIBP w/ cmt @ 8440'. ~~If cannot tag, attempt to clean out to 8440'.~~ (Possible fish @ 6201') **Circ mud laden**
2. Perf & Sqz 45 sxs cmt @ 6200-6100'. WOC & TAG **SPOT 255x @ 4950'** **fluid & pressure test**
3. Spot 25 sxs cmt @ 4200-4100'. WOC & TAG **4200'** **WOC & TAG**
4. Spot ~~55~~ sxs cmt @ 2600-2500'.
5. Cut & POH 5 1/2 csg +/- @ 2100'. **SPOT 305x @ 2150' WOC & TAG**
6. Spot 45 sxs cmt @ 1600-1500'.
7. Spot 45 sxs cmt @ 413-313'. WOC & TAG
8. Spot 30 sxs cmt @ 100-Surface.
9. Cut off well head, weld on Dry Hole Marker.
Verify cement to surface all strings.

Spud Date:

**NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben mts TITLE Agent DATE 1-12-17
Type or print name Ben Montgomery E-mail address: Benm@bcmadassociates.com PHONE: 432-580-7161
For State Use Only


APPROVED BY: Mah Whittaker TITLE Petroleum Engr. Specialist DATE 01/12/2017
Conditions of Approval (if any):

mw

Wellbore Schematic (from Surface to TD)

Printed: 1/9/2017

Page 1



Wellbore Schematic (From Surface to TD)

Printed: 1/9/2017

Page 1

