Office	State of New Me			Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	WELL ADIN	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	49 1292		WELL API NO. 30-025-25855	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease FEDERAL	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	io Brezos Rd Aztes NM 87410		STATE FEE	
District IV - (505) 476-3460			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Glenn Ryan	
PROPOSALS.)		8. Well Number 17		
1. Type of Well: Oil Well Gas Well X Other		1.7		
2. Name of Operator BLM for Patterson Operating & Pumping Inc. DBA/Penergy			9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat	
NMOCD 1625 N. French Drive Hobbs, NM 88240		Leonard:Queen, South		
4. Well Location				
Unit Letter L: 1980 feet from the South line and 660 feet from the West line				
Section 14 Township 26S Range 37E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12 Charle	Anneanriata Pay to Indicate M	atura of Nation	Danaut on Ot	har Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUEN				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				INT TO PA &.X
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNI				P&A NR
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	I JOB	P&A R
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				TOAK
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
SEE ATTACHED PROCEDURE AND SCHEMATIC				
SEL ATTACHED I ROCEDORE AND SCHEMATIC				
CONTACT NIMOCD 24 HOURS DRIOD TO DECININING DI LICCINIC ODED ATIONS				
CONTACT NMOCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS				
HOBBS OCD				
			JA	N 2 5 2017
			07	
Spud Date:	Rig Release Da	ite:	R	CEIVED
			1/1	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
Thereby certify that the information above is true and complete to the best of my knowledge and benefit.				
SIGNATURE Malbulalum TITLE Petroleum Engineering Specialist DATE 1/25/2017				
Type or print name Mark Whitaker E-mail address: marka.whitaker@state.nm.us PHONE: 575-393-6161				
For State Use Only				
APPROVED BY: Maley Stown TITLE AD/II DATE 1/25/2017 Conditions of Approval (if arty):				
V				

Patterson Operating & Pumping Inc DBA as Penergy Glenn Ryan No. 17 30-025-25855 UL – L, Sec. 14, T26S, R37E

8 5/8" @ 520' w/ 500 sx cmt 5 1/2" @ 3700' w/ 750 sx cmt Perforations 2699'-3020'

- 1. MIRU. POOH w/ production equipment.
- 2. Set CIBP at 2600'. Circulate hole with mud laden fluid. Spot 40 sx cement on CIBP. WOC and tag. Pressure test casing to 500 psi.
- 3. Perforate at 1150'. Squeeze w/ 30 sx cement. WOC and tag.
- 4. Perforate at 570'. Pump sufficient cement to circulate to surface inside/outside 5 1/2" casing.
- 5. Cut off wellhead 3' below ground level and verify cement to surface all strings.
- 6. Install below ground P&A marker. Photos should be taken prior to and after welding on plate. OCD should be notified prior to cut off so it can be witnessed.

NOTES: Mud laden fluid consists of 9.5 ppg brine with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

## Patterson Operating Pumping Inc DBA/Penergy Glenn Ryan # 17

