Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

٥.	Lease Sellal 140.
	NMNM0766

SUNDRY NOTICES AND REPO	RIS ON WELLS
Do not use this form for proposals to	drill or to re-enter an
abandoned well. Use form 3160-3 (AP	

SUNDRY	INIVITATIVIO / OO						
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	TRIPLICATE - Other inst	ructions on pag	e 2 50	00	7. If Unit or CA/Agre	eement, Name and/or No.	
Type of Well ☐ Gas Well ☐ Oth	7. If Unit or CA/Agreement, Name and/or No. Well Name and No. SOUTH JUSTIS UNIT D 22						
Name of Operator LEGACY RESERVES OPERA	Contact: ATING LRE-Mail: jsaenz@le	JOHN SAENZ gacylp.com	V	ò	9. API Well No. 30-025-11701		
3a. Address PO BOX 10848 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-689-5200			10. Field and Pool or Exploratory Area JUSTIS			
4. Location of Well (Footage, Sec., T	i)			11. County or Parish, State			
Sec 23 T25S R37E-SESE 660			Ŀ	LEA COUNTY,	NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE	NATURE O	F NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION			TYPE OF ACTION				
Notice of Intent ■ Notice of Intent	☐ Acidize	□ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing		☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction		Recom		Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon			rarily Abandon		
13. Describe Proposed or Completed Op-	Convert to Injection	n Plug Back		☐ Water l			
subseque	pandonment Notices must be fil inal inspection. edure to run a liner in the using test to BLM. nt report with detai	ed only after all requi well and RTP. Submit	rements, includ	ing reclamation	ACHED FO	and the operator has	
and ceme	nt job.						
14. I hereby certify that the foregoing is Name (Printed/Typed) JOHN SA	Electronic Submission # For LEGACY RES Committed to AFMSS for p	SERVES OPERATI	NG LP, sent BORAH MCKI	to the Hobb	s /13/2017 ()		
				A	PPROWED		
Signature (Electronic S		Dat	02/10/2		THORLD		
	THIS SPACE FO	OR FEDERAL C	OR STATE	OFFICE U	ATG 2 9 2017		
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of the con	not warrant or subject lease	tle		OF LAND MANAGEN			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	otatements or representations as	to any matter within	its jurisdiction.	willfully to m	ake to any department of	ragency or the United	

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

PROCEDURE Run Liner and RTP South Justice Unit D # 22 API: 30-025-11701 Lea County, New Mexico 1/25/2017

PROCEDURE

- Hold pre job safety meeting and MIRU PU.
- 2. Kill well. NU BOP.
- 3. Pick up work string and 6-1/8" mill tooth bit and drill out CIBP @ 4853'.
- **4.** TOOH and RIH with EZ drill BP and set at 5000'. Trip in hole with 7" packer and pressure test BP. Trip out of hole and stand work string back.
- **5.** Remove BOP and add new liner hanger spool piece to well head to hang off liner with. Re-install BOP with 5-1/2" rams.
- **6.** MIRU casing crew. Pickup 5000' 5-1/2" flush joint 15.5# J-55 liner coated with CLS Glass Wrap with float shoe, float collar and run in the hole to 4998'.
- 7. MIRU cement company. Establish injection rate and pump 350 sx class C cement, flush with 118 bbl fresh water. Shut in casing. Wash up BOP, wellhead, and casing valves. Rig down cement company. Remove BOP. Cut off casing and install well head slips and seal. Install BOP with 2-7/8" rams.
- 8. Notify Hobbs BLM of pressure test. Pressure test casing to 400# and chart for 30 minutes. Turn chart in to Midland office, if BLM takes chart take picture of chart and send picture in.
- 9. RIH with a 4-3/4" mill tooth bit, 4 drill collars, and work string. Tag cement 4940'. Drill out and clean out to PBTD @ 5855'.
- 10. TOH with bit and drill collars and lay down.
- **11.** RIH with production tubing per Production Superintendent.
- **12.** ND BOP and NU wellhead. RIH with rod string per Production Superintendent. Hang well on and RTP.

John Saenz

Operations Engineer

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.