Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals 1 8 2017					NMLC069276 6. If Indian, Allottee or Tribe Name		
OUDINIT IN 1	RIPLICATE - Other inst	4 4	REC	17	7. If Unit or CA/Agree	ement, Name and/or No.	
SUBMIT IN I	RIPLICATE - Other ins	truction	s on page CEIVE	7	7. It olik of cranges	inent, I talle and of I to.	
Type of Well	8. Well Name and No. WEST CORBIN 19 02						
					9. API Well No. 30-025-33508-00-S1		
3a. Address 6488 SEVEN RIVERS HIGHWAY ARTESIA, NM 88211 3b. Phone No. (include area code Ph: 405-552-7970					10. Field and Pool or Exploratory Area S CASS		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	i)			11. County or Parish, State		
Sec 19 T18S R33E NWSW 2173FSL 660FWL				LEA COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INI	DICATE NATURE OF	NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize		Deepen	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing		Hydraulic Fracturing	☐ Reclamation		■ Well Integrity	
Subsequent Report	□ Casing Repair		New Construction	Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans		Plug and Abandon	☐ Tempor	□ Temporarily Abandon		
	☐ Convert to Injection ☐ Plug Back		Plug Back	☐ Water Disposal			
13. Describe Proposed or Completed Op If the proposal is to deepen directions Attach the Bond under which the won following completion of the involved testing has been completed. Final At determined that the site is ready for f In response to the COA for thi Production Company, LP resp recomplete to the Bone Spring	ally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices must be final inspection. s well on 04/18/2017 apprectfully requests approve	give subset the Bond esults in a reled only after the Boroved by all to pluce	surface locations and measur l No. on file with BLM/BIA. multiple completion or reco fter all requirements, including	ed and true ve Required su impletion in a ing reclamation	ertical depths of all pertin bsequent reports must be new interval, a Form 316 n, have been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once	
Attached: Procedures Current & Proposed Wellbore Approved Sundry			CT TO LIKE OVAL BY STATI	3	APPRO	VED	

Thank you!

WITNESS

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the	e foregoing is true and correct. Electronic Submission #381989 verifie For DEVON ENERGY PRODUCT Committed to AFMSS for processing by PRI	ON CO	M LP. sent to the Hobbs			
Name (Printed/Typed)	ERIN WORKMAN	Title	REGULATORY COMPLIANCE PROF.			
Signature	(Electronic Submission)	Date	07/20/2017			
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By	PK Swark	Title	TPET	09/01/17 Date		
Conditions of approval, if ar certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease icant to conduct operations thereon.	Office	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE			
	and Title 43 U.S.C. Section 1212, make it a crime for any peor fraudulent statements or representations as to any matter w			gency of the United		

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

DVN: Corbin West 19 Fed # 2

API #30-025-33508 Sec 19-T18S-R33E-1 Lea County, NM 7/18/2017

Purpose: Recomplete 1st Bone Spring

T.D. - 11,350' PBTD - 10,2858'; CIBP to be SET @ ~10,290' w/ 25' cmt on top (10,265')

Wellbore fluid: Formation oil, natural gas and formation water.

Casing and Tubing Data:

Size	Wt. lb/ft	Grade	Interval	(.80 S. F.) Collapse	(.80 S. F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	48	H-40	0 - 460'	600	1,375	12.559"	
8-5/8"	32	J-55	0 - 2,860'	2,000	3,100	7.796"	
5-1/2"	17	N-80	0 - 11,350'	5,000	6,175	4.767"	0.0232
2-7/8"	6.5	N-80	0 - 8,600'	8,925	8,450	2.347"	0.00579

2-7/8" by 5-1/2" – 0.0152 bbls/ft.

5-1/2" - 0.1305 ft3/ft

Top of Cement: To be validated via Cement Bond Log during procedure

Current Perfs:

Wolfcamp


11,102' - 11,106' (4')

10,343' - 10,354' (11')

Corbin West 19 Fed # 2 Procedure:

- 1. Remove PR and Stuffing Box. Install Rod rams. Unseat pump and T.O.H. with rods and pump.
- 2. ND wellhead. NU 5,000 psi BOPE, w/1 set of blind rams on bottom plus 1 set of 2-7/8" tbg rams on top. Test BOPE to Devon specifications. Have 10,000 psi tubing valve(s) for frac.
- 3. Unset TAC @ ~10,464'. T.O.H.
- 4. TIH and set CIBP at 10,290'. Cap CIBP with 35' cement for a PBTD of 10,255'. Wait on cement.

- 5. MIT the 5-1/2" csg to 500 psi at surface for 30 min with a 1000 psi chart recorder and submit results to BLM.
- 6. Run casing integrity log and CBL. Submit results to BLM and verify top of cement above proposed perforated interval. Do not proceed until casing integrity and cement bond accepted by BLM.
- 7. RU frac crew, iron, and tubing isolation valves rated for > 5,000 psig service. TIH frac string and packer. Set packer at 8,300'. Test CIBP and cement plug to max treating pressure. Test annulus to 1,000 psig to verify packer integrity.
- 8. R.U. Wireline Service Company and full lubricator. Test lubricator to Devon specifications. RIH with slick guns. Perforate the 1st Bone Spring Sand between 8,574' and 8,504' MD.
- 9. RD Wireline. RU frac crew. Test iron and stimulate perforated interval in the 1st Bone Spring Sand.
- 10. RD frac. Flow well back immediately.
- 11. Once well dies. Unset treating packer, drop down and reverse circ. out fluid to PBTD of 10,255'. TOOH frac string. RDMO frac stack and additional equipment.
- 12. T.I.H. with production tubing detail as before but place T.A.C. @ \sim 8,600' (below bottom perf).
- 13. N.D. BOPE and N.U. wellhead. Install rod rams.
- 14. T.I.H. with pump and rod design.
- 15. R.D.M.O. DDCU and release all rentals. Return well to production.



Vell Name: WEST CORBIN 19 FEDERAL #2	Field: CORBIN SOUTH
ocation: 2173' FSL & 660' FWL; SEC 19-T185-R33E	
levation: 3810' KB; 3797' GL; 13' KB to GL	Spud Date: 4/27/97 Compl Date: 8/30/97
Pl#: 30-025-33508 Prepared by: Ronnie Slack	Date: 7/19/17 Rev:
Tropared by. Rolling Stack	9 999
17-1/2" hole 13-3/8", 48#, H40, 8RD, STC, @ 460' Cmt'd w/400 sx to surface 11" Hole 8-5/8", 32#, J55, 8RD, STC, @ 2,860' Cmt'd w/750 sx to surface	
Proposed: <u>1ST BONE SPRING</u> 8,504' - 8,534' 8,556' - 8,574'	STOCKERS OF BANKSTANK
WOLFCAMP (10/19/08) 10,343' - 10,354' 2 spf, 120° 10/22/08: acidized 10343-50' w/1500 gal 15% HCl	Proposed: 2. Cap CIBP w/35' cmt. 10,255' PBD. 1. Set CIBP @ 10,290'
WOLFCAMP (8/97) 11,080' - 11,086' WOLFCAMP (8/97) 11,102' - 11,106' Sqzd w/50 sx Cl H @ 3500 psi	SECOND SCHOOL SECONDS
7-7/8" Hole 5-1/2", 17#, N80, 8RD, LTC, @ 11,350' Cmt'd w/1950 sx to surface	11,350' TD

Conditions of Approval

Devon Energy Production Co. West Corbin - 02, API 3002533508 T18S-R33E, Sec 19, 2173FSL & 660FWL August 30, 2017

- 1. Within 90 days of these conditions of approval for the processed Electronic Submission #381989 notice of intent begin wellbore operations.
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.
- 3. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 4. Subject to like approval by the New Mexico Oil Conservation Division.
- 5. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Surface disturbance beyond the existing pad shall have prior BLM approval.
- 8. Functional H₂S monitoring equipment shall be on location.
- 9. Blow Out Prevention Equipment (3M) to be used. Establish fail safe well control for BOPE and workover procedures. Blind ram(s) and pipe ram(s) designed to close on all workstring diameters used is required equipment. A manual BOP closure system (hand wheels) shall be available for use regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Employ choke manifolds, kill trucks, gas vent or flare lines, etc. when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations.
- 11. Notify BLM 575-393-3612 Lea Co as work begins. Some procedures witnessed. If there is no response, leave a voice mail with the API#, workover purpose, and a call back phone number.
- 12. **Perform a charted casing integrity test** of 500psig minimum from the CIBP to set at 10290' to surface. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 75 per cent of its full range. **Verify all annular casing vents are open at the surface during this pressure test.** Call BLM 575-393-3612 Lea Co and arrange for a BLM witness of that pressure test. Include a copy of the chart in the subsequent sundry for this workover.

- 13. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from the proposed 10,290' CIBP taken with 0psig casing pressure to TOC above the DV Tool (of unknown depth). Attach the CBL to a pswartz@blm.gov email.
- 14. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. A Class "H" plug tag requires WOC of 8 hours. Formation isolation plugs of Class"H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 15. Set a Class H (>7500ft) cement plug on the 10290' CIBP. WOC and tag the plug with tbg at 10033' or above, isolating the Wolfcamp formation top.
- 16. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures.
- 17. Submit a (BLM Form 3160-5 subsequent report describing (dated daily) all wellbore activity and the Mechanical Integrity Test. File intermediate Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 18. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation.
- 19. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 20. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval date.
- 21. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

