Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HODDS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires: January 31, 2018
Lease Serial No.

HORRS OCH

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals.

3 0 2017

6. If Indian, Allottee or Tribe Name

NMNM053434

SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No. NM70976 a								
Type of Well	ner /				8. Well Name and No. LEA UNIT 14				
Name of Operator LEGACY RESERVES OPERA	Contact: [ATING LPE-Mail: pdarden@le	D. PATRICK egacylp.com	DARDEN, PE		9. API Well No. 30-025-30138	/			
3a. Address 303 W WALL ST STE 1800 MIDLAND, TX 79701			. (include area code) 9-5200 Ext: 5237		10. Field and Pool or I LEA; DELAWAF	xplorato RE, NO	ory Area RTHEAST		
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County or Parish, S	State			
Sec 14 T20S R34E NENE 660	LEA CO COUNTY, NM								
,		4	2						
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ER DA	ATA		
TYPE OF SUBMISSION									
Notice of Intent	☐ Acidize	Acidize		pen Product		tion (Start/Resume)			
_	☐ Alter Casing	☐ Hydraulic Fracturing ☐ F		☐ Reclam	☐ Reclamation		■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	□ Nev	Construction	☐ Recomp	lete	☑ Ot	her		
☐ Final Abandonment Notice	☐ Change Plans	Plug	g and Abandon	☐ Tempor	arily Abandon				
4	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal				
testing has been completed. Final Ab determined that the site is ready for fi Legacy Reserves Operating, L These perfs were blanked off	nandonment Notices must be file inal inspection. P will be re-opening and t with a CIBP and cement in	d only after all testing Delay the past (se	requirements, including vare perfs on the	ing reclamation	have been completed a 4.	0-4 must nd the op	be filed once perator has		
		APPROVED							
SEE ATTACHED FOR CONDITIONS OF APPROVAL SUBJECT TO LIKE APPROVAL BY STATE									
	Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Legacy Reserves Operating, LP will be re-opening and testing Delaware perfs on the Lea Unit #14. These perfs were blanked off with a CIBP and cement in the past (see attached Wellbore Diagrams). This work will start as soon as approval is granted from the BLM. SEE ATTACHED FOR CONDITIONS OF APPROVAL. SUBJECT TO LIKE								
Name (Printed/Typed) D. PATRICK DARDEN, PE			TITLE SR. ENGINEERING ADVISOR						
Signature (Electronic S	Signature (Electronic Submission) Date 10/17/2017								
^ ^	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE				
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to conduct the applicant the applican	uitable title to those rights in the		Title Office		LAND MANAGEME BAD FIELD OFFICE	NT I	Date		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c statements or representations as t	crime for any pe	erson knowingly and ithin its jurisdiction.	willfully to ma	ke to any department or	agency o	of the United		

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

M&B/OCD 11/30/2017

Wellbore Schematic (From Surface to TD)

Printed: 8/23/2017


Page 1

ea Unit # 14			BOLO ID: 300	0033.11.14	API# 30025	30138
		660 FNL & 660 FEL		GL Elev: 3,649.00	KOP:	
		Section 14, Townshi	p 20S, Range 34E		EOC:	
		County, State: Lea,			Fill Depth:	7,803
		Aux ID: 23300			PBTD:	
	13-3/8"	'KB' correction: 16.5	All Denths Corr To).	TD:	10,400.0
4 000		The same of the sa	A CONTRACTOR OF THE PARTY OF TH		BOP:	10,400.0
1,000	48 # H-40	(URREA	IT WELLBO	DRE CONDITION	BOF.	
-		00.11101	41			
2,000 -						
1						
3,000						
4,000						
	FZ					
5,000	-5/8" 3th (-55 e 5387	+				
	(-55 e 5387					
	(30 0 3001					
6,000			•			
X						
7,000						
					•	
-						
CHANNEY SHADOW			,			
8,000						
X X X						
				*		
9,000						
- Contract Contract						
					,	
10,000						
X STANDARD CONTROL X	16" i7#					
	1/2" 17#					
TD @ , K-5	ساراه در					
10,400						
1 ' /						
11,000 ^J		1				

Wellbore Schematic (From Surface to TD)

Printed: 8/23/2017

Page 1



Conditions of Approval Legacy Reserves Operating LP Lea Unit - 14, API 3002530138 T20S-R34E, Sec 14, 660FNL & 660FEL October 31, 2017 1. Begin wellbore operations within 90 days of these conditions of approval for the processed Electronic Submission #392273 notice of intent or request an extension. 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location during this workover operation. 3. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. 4. Subject to like approval by the New Mexico Oil Conservation Division. 5. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5. 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits. 7. Surface disturbance beyond the existing pad shall have prior BLM approval. 8. Functional H₂S monitoring equipment shall be on location. 9. Blow Out Prevention Equipment 3000 (3M) to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels or automatic locking devices) equipment installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements. 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations. 11. Notify BLM 575-393-3612 Lea Co as work begins. Some procedures witnessed. If there is no response, leave a voice mail with the API#, workover purpose, and a call back phone number. 12. The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness. 13. This procedure is subject to the next three numbered paragraphs. Page 1 of 2

14. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 1/2" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft. 15. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water. 16. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine. 17. Tag the 9480 CIBP cmt cap and set a 25sx Class "H" balanced plug on the tag depth. WOC, and tag the plug with tbg at 9270' or above. 18. Set a 25sx Class "H" balanced plug across the Bone Spring formation top from 8900' or below. WOC, and tag the plug with tbg at 8712' or above. 19. File subsequent sundry Form 3160-5 within 30 days of workover procedures. Include (dated daily) descriptions of the well work, i.e. procedure descriptions and include depths of the previously unreported Delaware perfs that are indicated by the attached Legacy wellbore diagram. 20. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures. 21. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation. 22. File intermediate subsequent sundry Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in paying quantities or of service use. 23. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval 24. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment. Page 2 of 2

