
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD District II	WELL API NO. 30-025-22017
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 FEB 1912098South St. Francis Dr.	STATE 🔽 FEE 🗌 🖌
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 RECEIVED	K-2654
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	CHRISTENSEN STATE
PROPOSALS.) 1. Type of Well: Oil Well \checkmark Gas Well \square Other	8. Well Number 1
2. Name of Operator JAY MANAGEMENT COMPANY, LLC	9. OGRID Number 247692
3. Address of Operator	10. Pool name or Wildcat
1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027	BAGLEY; PERMO PENN, NORTH
4. Well Location	
Unit Letter L : 1980 feet from the SOUTH line and 6	660feet from theline
Section 16 Township 11S Range 33E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4264.7' GR	
4204.7 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORK PLUG AND ABANDON I REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	D&A ND
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE	P&A R
OTHER: OTHER:	· · · · · · · · · · · · · · · · · · ·
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
RIH w/ workstring open ended and circulate hole w/ required plug mud	
Spot plug 1: 15 sx @ 8600' (8600' - 8420') to cover perforations	
Spot plug 2: 11 sx @ 3800' (3800' - 3670') to cover the 8.625" casing shoe	
Spot plug 3: 8 sx @ 375' (375' - 275') to cover the 13.375" casing shoe Spot plug 4: 4 sx @ 50' (50' - 3') to load casing	
Spot plug 4: 4 sx @ 50 (50' - 3') to load casing	See Attached
Dig approximately 3' and cut off casing and wellhead	ditions of Approval
Install plate showing Dry Hole Marker information	See Attached Conditions of Approval
Wellbore diagram with proposed plugs is attached.	
Snud Date: NOTIFY OCD 24 HOUF	
Spud Date: BEGINNING PLUGGING OPERATIONS	
DEGINING TECCOMO OF ERATIONS	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
ALL XIII.	
SIGNATURE	DATE 02/15/2018
Type or print name Clay Griffin E-mail address: cgriffin@jaymg	t.com PHONE: 574-707-5691
For State Use Only	
APPROVED BY: Mallitate TITLE Petroleum Engr. Specialist DATE 02/19/2018 Conditions of Approval (if any):	
C103 INTENT TO P&A EXPIRES	
0	2-19-2019



SA 3720

CONDITIONS OF APPROVAL

- Set CIBP within 100' of top perforation at 8618'.
- Circulate MLF (9.5 ppg brine mixed with 25 sacks of salt gel per 100 bbls of fluid).
- Pressure test casing and report results.
- Spot 25 sx of Class H cmt on top of CIBP. No tag required if casing tests.
- Perforate 4 ½" casing at 6200'.
- Squeeze w/ 30 sx of Class C cmt. Displace to 6050'. WOC & Tag.
- Perforate 4 ½" casing at 3800'.
- Squeeze w/ 30 sx of Class C cmt. Displace to 3650'. WOC & Tag.
- Perforate 4 ½" & 8 5/8" csg at 2400'. Sqz w/ 60 sx cmt. Displace to 2300'.
 WOC & Tag.
- Perforate 4 ½" & 8 5/8" csg at 1700'. Sqz w/ 60 sx cmt. Displace to 1600'.
 WOC & Tag.
- Perforate 4 ½" & 8 5/8" csg at 375'. Sqz w/ 80 sx cmt. Displace to 275'.
 WOC & Tag.
- Perforate 4 ½" & 8 5/8" csg at 100′. Circulate cmt to surface out all bradenheads.
- Cut off wellhead 3' below ground level. Verify cement to surface all strings. Install upright P&A marker.