Office	Form C-103
District I = (575) 393-6161 Energy Minerals and Natural Re	sources Revised August 1, 2011
Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 APR 12 Only CONSERVATION DIV	SION 30-025-44396
District I = (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II = (575) 748-1283 811 S. First St., Artesia, NM 88210 District III = (505) 334-6178 1220 South St. Francis D	f. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 8 TECEIVED Santa Fe, NM 87505 District IV - (505) 476-3460	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	6. State Off & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	
PROPOSALS.)	8. Well Number: 23-654
1. Type of Well: Oil Well Gas Well Other: Injector	
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	10. Pool haine of whicat Hobbs (0/3A)
4. Well Location	
	1072 Fast from the East line
Unit Letter H : 1541 feet from the North line and	
Section 23 Township 18S Rang	
11. Elevation (Show whether DR, RKB, 3683' (GL)	RI, GR, etc.)
3003 (GL)	
12. Check Appropriate Box to Indicate Nature	of Nation Report on Other Date
12. Check Appropriate Box to Indicate Nature	of Notice, Report of Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	EDIAL WORK ALTERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COM	MENCE DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL CAS	NG/CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER: Initial Completion	_
	-n.
13 Describe proposed or completed operations. (Clearly state all pertine	ER:
 Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For 	nt details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For	nt details, and give pertinent dates, including estimated date
	nt details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD)	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD)	Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel wank and haul contents to the required
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7.	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date:	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date:	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date:	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of response to the set of resp	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart DATE 1/12//6
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date: Title Pad. E. Type or print nameRick Reeves E-mail address rick	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart DATE 1/2//E reeves@oxy.com_PHONE: 713-215-7653
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date: TITLE Pod. Entire Line For State Use Only A A COLUMN C	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart The procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart The procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion. 1. Drillout DV tools @ 3786' and cleanout to PBTD (Float Collar at 5282' MD) 2. Run CBL 3. Selectively perforate San Andres ROZ and TZ targets between POWC (estimated at 4327' MD) and Base of Unit @ 4530' MD. 4. Acid treat new perforations. 5. RIH with injection equipment 6. Turn well to injection 7. 8. Spud Date: Rig Release Date: Title Pad. E. Type or print nameRick Reeves E-mail address rick	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart DATE 1/12//6