AUG Do not use the abandones we		6. If Indian, Allottee or Tribe Name
SUBMIT IN	TRIPLICATE - Other instructions on page 2 AUG 06 2018	7. If Unit or CA/Agreement, Name and/or No.
 Type of Well Oil Well S Gas Well Oth 	RECEIVE	B. Well Name and No. EL MAR 21 W2NC FED COM 5H
2. Name of Operator MEWBOURNE OIL COMPAN	Contact: JACKIE LATHAN Y E-Mail: jlathan@mewbourne.com	9. API Well No. 30-025-44750-00-X1
3a. Address P O BOX 5270 HOBBS, NM 88241	3b. Phone No. (include area code) Ph: 575-393-5905	10. Field and Pool or Exploratory Area SALADO DRAW
4. Location of Well (Footage, Sec., 7	, R., M., or Survey Description)	11. County or Parish, State
Sec 21 T26S R33E SESW 21 32.022327 N Lat, 103.577652		LEA COUNTY, NM
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	

THE OF BODMISSION	THE OF ACTION						
□ Notice of Intent	🗖 Acidize	Deepen	Production (Start/Resume)	□ Water Shut-Off			
_	□ Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	🛛 Other			
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	Well Spud			
	Convert to Injection	🗖 Plug Back	Water Disposal				

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

06/01/18 Spud 17 1/2" hole @ 885'. Ran 875' of 13 3/8" 54.5# J55 ST&C Csg. Cemented with 550 sks Class C w/additives. Mixed @ 13.5#/g w/1.74 yd. Tail w/200 sks Class C w/1% CaCl2. Mixed @ 14.8 #/g w/1.34 yd. Displaced w/128 bbls of BW. Plug down @ 6:30 PM 06/02/18. Circ 322 sks of cmt to the pits. Test BOPE to 10000# & Annular to 5000#. At 6:00 A.M. 06/04/18, tested csg to 1500#, held OK. FIT test to 10.8 PPG EMW. Drilled out with 12 1/4" bit.

Charts & Schematic attached.

Bond on file: NM1693 nationwide & NMB000919

	······································	-			
14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #428296 verific For MEWBOURNE OIL CO Committed to AFMSS for processing by PR	MPÁNY	. sent to the Hobbs		SE)
Name(Printed/Typed)	RUBY O CABALLERO	Title	REGULATORY		
Signature	(Electronic Submission)	Date	07/24/2018		
	THIS SPACE FOR FEDER	1466 <u>-</u>	stateloffice NSE(JRD	
Approved By		Title	111 0 5 2010		Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Offic]	Ionathon Shepard
Title 18 U.S.C. Section 100 States any false, fictitious	1 and Title 43 U.S.C. Section 1212, make it a crime for any p or fraudulent statements or representations as to any matter w	erson kno eithin its	MARYSBAD HELD OFFICE	any der	artment or agency of the United
(Instructions on page 2)	BLM REVISED ** BLM REVISED ** BLM R				· · · ·











ine a de	1				· · · ·	(1,1,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2
	R				• BOP TEST	
1			NIPPLE	UP SERVICE	E • BOP LIFT AS SÉPARA	rs • TANDEM TORS Pa
9	50	y welding services	Lor	vington, NM	• 575-3	96-4540 P
د بند ^{رز} ا C	ompany :	Mewbanne		Date: 6	-3-18	invoice # 42.520
		Mar 21 WINC 4				- PLot 147500 Rig # 231
Р	lug Size 8	Type: 12 672	Drill Pipe Siz	e <u>(07-</u>	34-41	Tester: TOPU & ADAM
	lequired l			Install	ed BOP:	
* Ap	opropriate Ca	sing Valve Must Be Open During BOP Test •				* Check Valve Must Be Open/Disabled To Test Kill Line Valves *
- : · ·	-			A1 7.17 : :		Dart -
: • • • • •		00000	Mud Ga	uge		Valve #19
•	•			#6	· · · · · · · · · · · · · · · · · · ·	Stand Pipe
	•	Annular #15	IL ING	0-000	A	Kelly/ Top #24
						Drive #22 #23
· ;;	e	Pipe Rams #12	#3	#4 #2		IBOP S
		Blind Rams #13	Ĕ.	#48 #28		
·	លាភិ		اللر ۲ 🞯 🗤		#26 بينا يو	IBOP Pump Pump
	#11 #10	#9]			#16 Valve Valve Valve #20 #21
		Pipe Rams #14	#25 Super Choke			
	• • •					
:		Casing			1	
•	TEST #	ITEMS TESTED	TEST LENGTH	1-1-1-1-1-1		and the second
	11	and the second		LOW PSI	HIGH PSI	REMARKS
-		12,9,96,345	10-10	LOW PSI	HIGH PSI	Failed Doys on Blinds
å,	2	12, 9, 86, 3, 45	10-10 10-10	20		Failed Dors of Islands Passed
	2	12, 9, 86, 3, 45 14 12, 9, 86, 3, 45	10-10 10-10 10-10	2170 2770 2770	10000 10000	Parley Dors of Islands Passed Robst Dors Passol
	2 3 4	12,9,86,3,45 14 12,9,86,3,45 19	10-10 10-10 10-10 10-10	270 270 270 270 270	10000 10000 10000 5000	Failted Doys of Islands Passed Rotest work Passol Rassiel (IT-39
	2.3	19 13	10-10 10-10 10-10 10-10 10-10	270 270 270 270 270 270	(10000 10000 10000 5000	Failed Dows on Blands Passed Robst Dows Pissol Robst Dows Pissol Rossied (IT-39 Rossied (IT-39
	23	12, 9, 86, 3, 45 14 12, 9, 86, 3, 45 19 18 14	10-10 10-10 10-10 10-10 10-10 10-10	-212 212 210 210 210 256 210	10000 10000 5000 5000 5000	Failed Days on Blands Passed Robst Days Passed Passed 1 T-39 Rossed (1 T-39 Rossed (1 T-39 Rossed (1 T-39 Rossed (1 T-39
	234	19 18 19 19 18	10-10 10-10 10-10 10-10 10-10 10-10 10-10	-210 210 210 210 210 256 210 210	10000 10000 5000 5000 5000	Failed Days on Islands Passed Robst Nave Pessol Robst Nave Pessol Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39) Rossed (17-39 Rossed (17-39) Rossed (17-39) Ro
	2344	19 13	10-10 10-10 10-10 10-10 10-10 10-10	-270 270 270 270 270 258 2.70 2.80 2.80 2.50	10000 10000 5000 5000 5000 5000	Failed Days of Islands Passed Robst Days Pessel Robst Days Pessel Rossed (IT-39 Rossed (IT-
	2344	19 18 18 12,10,8 12,10,7	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	270 270 270 270 270 276 270 276 270 270 270	10000 10000 5000 5000 5000 5000 5000	Failed Days on Blands Passed Robst Days Pessed Robst Days Pessed Robst Days Pessed Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed Rossed Rossed Rossed Rossed
	2 3 4 7 6 7 8 9 1()	19 18 19 19 18	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	-270 270 270 270 270 256 200 2.10 2.10 2.10 2.10 2.10 2.10 2.10	10000 10000 5000 5000 5000 5000 5000 50	Failed Days on Blinds Passed Robst Nave Pessel Robst Nave Pessel Robst Nave Pessel Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed Passed Passed Passed
	2 3 4 7 6 7 8 9 11) 11) 11)	19 18 18 12,10,8 12,10,7 20, 21, 22, 23 24	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	-270 270 270 270 270 256 2.70 2.80 2.50 2.50 2.50	10000 10000 5000 5000 5000 5000 5000 50	Failed Doys on Blinds Passed Robst Dove Pessed Robst Dove Pessed Robst Dove Pessed Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed (17-39 Rossed Rosse
	2 3 4 7 6 7 8 9 10 11 12	19 18 18 12,10,8 12,10,7	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	-210 210 210 210 210 256 200 200 200 200 200 200 256 256 256 256	10000 10000 5000 5000 5000 5000 5000 50	Fulled Doys of Blinds Passed Robst Nour Pessol Robst Nour Pessol Robst Nour Pessol Rossed (17-39 Rossed (17-39) Rossed (17-39) Rossed (17-39) Rossed (17-39) Rossed (17-39) Ros
	2 3 4 7 6 7 8 9 1() (1 12 13	19 18 18 12,10,8 12,10,7 20, 21, 22, 23 24	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	250 250 250 250 250 256 250 250 250 250 250 250 250	10000 10000 5000 5000 5000 5000 5000 50	Failed Doys of Blands Passed Robst Dovis Pissol Passed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed Po
	2 3 4 5 6 7 8 9 11) 12 12 13 14 12	19 18 12,10,8 12,10,7 20,21,22,23 24 15,10,7 15,10,7 15,10,7 14,11,6,2,1	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	270 270 270 270 270 276 276 256 257 257 257 257 257 257 257 257 257 257	10000 10000 5000 5000 5000 5000 5000 5000 5000 5000 5000 10000 10000 10000	Failed Doys or Blinds Passed Robst Dovis Pissol Passed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed P
	2 3 4 5 7 8 9 10 11 12 13 14 13 14 13	19 18 14 18 12,10,8 12,10,7 20,21,22,23 24 15,10,7 15,10,7 15,10,7 15,10,7 15,10,7 14,11,6,2,1 13,11,6,56,254,264	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	250 250 250 250 250 250 250 250 250 250	10000 10000 5000 5000 5000 5000 5000 5000 5000 5000 10000 10000 10000 10000	Tailed Days on Blands Passed Robst Days Pressol Robst Days Pressol Robst Days Pressol Rossed (17-39 Rossed (17-39 Rosse
	2 3 4 7 6 7 8 9 10 11 12 12 12 15 16	19 18 12,10,8 12,10,7 20,21,22,23 24 15,10,7 15,10,7 15,10,7 14,11,6,2,1	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	250 250 250 250 250 250 250 250 250 250	10000 10000 5000 5000 5000 5000 5000 5000 5000 5000 5000 10000 10000 10000	Failed Doys or Blinds Passed Robst Dovis Pissol Passed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed (IT-39 Possed P
	1	19 18 14 18 12,10,8 12,10,7 20,21,22,23 24 15,10,7 15,10,7 15,10,7 15,10,7 15,10,7 14,11,6,2,1 13,11,6,56,254,264	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	250 250 250 250 250 250 250 250 250 250	10000 10000 5000 5000 5000 5000 5000 5000 5000 5000 10000 10000 10000 10000	Tailed Days on Blands Passed Robst Days Pressol Robst Days Pressol Robst Days Pressol Rossed (17-39 Rossed (17-39 Rosse
	1	19 18 14 18 12,10,8 12,10,7 20,21,22,23 24 15,10,7 15,10,7 15,10,7 15,10,7 15,10,7 14,11,6,2,1 13,11,6,56,254,264	10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10 10-10	250 250 250 250 250 250 250 250 250 250	10000 10000 5000 5000 5000 5000 5000 5000 5000 5000 10000 10000 10000 10000	Tailed Days on Blands Passed Robst Days Pressol Robst Days Pressol Robst Days Pressol Rossed (17-39 Rossed (17-39 Rosse

1 1.1

,

NA WELDING SERVICES, WC

· · ·	bany Mouburne		Date 6-3-18		<u></u>
	Elma, 21 WINC L			· · · · · · · · · · · · · · · · · · ·	
Drilli	ng Contractor Patterson	231	Plug & Drill Pipe Si	ne 12'222- (P	T: 39- 4
Accu	nulator Pressure: 2000	Manifold I	Pressure: 1500	Annular Pressure	. 900
			tion Test - C		·
To Cl	neck - USABLE FLUID IN T				
		· · · · · · · · · · · · · · · · · · ·			
	Make sure all rams and annu				· · ·
••••••••••••••••••••••••••••••••••••••	Ensure accumulator is pump	ed up to working	g pressure! (Shut off	all pumps).	
	1: Open HCR Valve. (If app	licable)			
	2. Close annular.				
· · · · ·	3. Close all pipe rams.				
				· · ·	
	4: Open one set of the pipe r	• • • •			
	4: Open one set of the pipe r 5. For 3 ram stacks, open the	e annular to achie	eve the 50+ % safety	factor. (5M and grea	
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press 	e annular to achie ure <u>/400</u> psi	eve the 50+ % safety . Test Fails if press	factor. (5M and greating the second s	quired.
an et ander a	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500) 	e annular to achie ure <u>/ 400</u> psi psi system} b .	eve the 50+ % safety . Test Fails if press {1200 psi for a 200	factor. (5M and greating the second s	quired.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press 	e annular to achie ure <u>/ 400</u> psi psi system} b .	eve the 50+ % safety . Test Fails if press {1200 psi for a 200	factor. (5M and greating the second s	quired.
ст. (Докало) 	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open 	e annular to achi ure <u>/ 400</u> psi psi system} b. i it at this time ar	eve the 50+ % safety . Test Fails if press {1200,psi for a 200 id close HCR.	factor. (5M and grea ure is lower than re 0.& 3000 psi system	quired.
To Ch	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500) 	e annular to achi ure <u>/ 400</u> psi psi system} b. i it at this time ar	eve the 50+ % safety . Test Fails if press {1200,psi for a 200 id close HCR.	factor. (5M and grea ure is lower than re 0.& 3000 psi system	quired.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO 	e annular to achi ure <u>[400</u> psi psi system} b. i it at this time ar OTTLES OR SP	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR.	factor. (5M and grea ure is lower than ree 0 & 3000 psi system .d.)	quired.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure 	e annular to achi ure <u>//00</u> psi psi system} b. i it at this time ar DTTLES OR SP at, or above, ma	eve the 50+ % safety . Test Fails if press {1200,psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr	factor. (5M and great are is lower than read 0.& 3000 psi system .d.) e-charge pressure:	quired.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO 	e annular to achi ure <u>//00</u> psi psi system} b. i it at this time ar DTTLES OR SP at, or above, ma	eve the 50+ % safety . Test Fails if press {1200,psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr	factor. (5M and great are is lower than read 0.& 3000 psi system .d.) e-charge pressure:	quired.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. [950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. [800 psi for a 150 1. Open bleed line to the tan 	e annular to achi ure // 00 psi psi system} b. i it at this time ar OTTLES OR SP at, or above, ma 0 psi system} k, slowly (gaug	eve the 50+ % safety . Test Fails if press {1200,psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a	factor. (5M and great are is lower than read 0 & 3000 psi system .d.) re-charge pressure: 1 and 3000 psi system at the lowest bottle p	quired. } a} pressure)
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. {950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. {800 psi for a 150 1. Open bleed line to the tan 2. Close bleed line. Barely,1 	e annular to achi ure // 00 psi psi system} b. i it at this time ar DTTLES OR SP at, or above, ma 0 psi system} l k, slowly (gauge bump electric pu	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a mp and see what pre	factor. (5M and great ure is lower than ree 0 & 3000 psi system .d.) re-charge pressure: 1 and 3000 psi system at the lowest bottle p ssure the needle jump	quired. } pressure) ps up to.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. (800 psi for a 150 1. Open bleed line to the tan 2. Close bleed line. Barely: 3. Record pressure drop/0 	e annular to achi ure //00 psi psi system} b. i it at this time ar OTTLES OR SP at, or above, ma 0 psi system} k, slowly. (gaug bump electric pu 00 psi. Test	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a mp and see what pre t fails if pressure dr	factor. (5M and great ure is lower than ree 0 & 3000 psi system .d.) re-charge pressure:) and 3000 psi system at the lowest bottle p ssure the needle jum ops below minimum	quired. } pressure) ps up to.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. {950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. {800 psi for a 150 1. Open bleed line to the tan 2. Close bleed line. Barely,1 	e annular to achi ure //00 psi psi system} b. i it at this time ar OTTLES OR SP at, or above, ma 0 psi system} k, slowly. (gaug bump electric pu 00 psi. Test	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a mp and see what pre t fails if pressure dr	factor. (5M and great ure is lower than ree 0 & 3000 psi system .d.) re-charge pressure:) and 3000 psi system at the lowest bottle p ssure the needle jum ops below minimum	quired. } pressure) ps up to.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. (800 psi for a 150 1. Open bleed line to the tan 2. Close bleed line. Barely: 3. Record pressure drop/0 	e annular to achi ure //00 psi psi system} b. i it at this time ar OTTLES OR SP at, or above, ma 0 psi system} k, slowly. (gaug bump electric pu 00 psi. Test	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a mp and see what pre t fails if pressure dr	factor. (5M and great ure is lower than ree 0 & 3000 psi system .d.) re-charge pressure:) and 3000 psi system at the lowest bottle p ssure the needle jum ops below minimum	quired. } pressure) ps up to.
	 4: Open one set of the pipe r 5. For 3 ram stacks, open the 6. Record remaining press a. (950 psi for a 1500 7. If annular is closed, open neck - PRECHARGE ON BO Start with manifold pressure a. (800 psi for a 150 1. Open bleed line to the tan 2. Close bleed line. Barely: 3. Record pressure drop/0 	e annular to achi ure //00 psi psi system} b. i it at this time ar OTTLES OR SP at, or above, ma 0 psi system} k, slowly. (gaug bump electric pu 00 psi system 1500 psi system	eve the 50+ % safety . Test Fails if press {1200 psi for a 200 id close HCR. HERICAL (III.A.2 ximum acceptable pr b. {1100 psi for 2000 ge needle will drop a mp and see what pre t fails if pressure dr } b. {900 psi for a	factor. (5M and great ure is lower than red 0 & 3000 psi system .d.) re-charge pressure:) and 3000 psi system at the lowest bottle p ssure the needle jump ops below minimum 2000 & 3000 psi system 2000 & 3000 psi system 200 & 300 psi system	quired. } pressure) ps up to.

1. Open the HCR valve, {if applicable}

- 2. Close annular
- 3. With pumps only, time how long it takes to regain the required manifold pressure.
- 4. Record elapsed time 1. 499. Test fails if it takes over 2 minutes.
 a. {950 psi for a 1500 psi system}
 b. {1200 psi for a 2000 & 3000 psi system}