CD	
Submit I Copy To Appropriate District State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	30-025-36130
	5. Indicate Type of Lease
Bit S. First St., Artesia, NM 88210 OTE CONSERVATION District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 -	STATE FEE 🔀
District IV - (505) 476-3460 Santa Fe, NM 8751	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	34639
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Brabant
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well 🚺 Gas Well 🗌 Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
The Redmon Oil Company	232186
3. Address of Operator 3315 Silverstone Dr. Ste A, Plano, Texas 75023	10. Pool name or Wildcat
	Brunson Drinkard - Abo, South
4. Well Location Unit Letter G : 1980 feet from the North line and 1980 feet from the East line	
Section 8 Township 225 S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Lea
G.R. 3,389'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Dox to indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO: SUBSEQUE!	
	P&A R
CLOSED-LOOP SYSTEM	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. SET CIBP@7140', Pressure test Casing*	
MIRU Plugging Contractor on or about 10/1/2018/ Current completion interval in Abo @ 7240'-7355'. POOH with	
rods, pump and tubing. GHH with tubing to 7400 ⁴ and circulate well with 9.5# mud. Pump 50 sx cement plug to 3764	
3260° 6950'. POOH to 6200' and spot 25 sx plug to 5900'. POOH to 5500' and spot 25 sx plug to 5200'. POOH to 3200°	
and spot 25 sx plug to 2900'. POOH to 1300 and spot 35 sx to 900. Spot surface plug from 120' to surface.	
Install dry hole marker, remove equipment and restore location. WOL & TAG (Shoe Plug) VERIEV CMT TO SURFACE ALLS TRINKS	
VENIFY UNIT TO BUILTINGS	
* TAG CMT IF CSG DOES NOT TEST	
AG LIVIT IF LJG DOZS INOT IZJ	
Spud Date: Rig R NOTIFY OCD 24 HOURS PRIOR TO	
space states	GGING OPERATIONS
I hereby certify that the information above is true and complete to the best of my knowledge	and belief
1.1.1.7	
SIGNATURE Ullen /- ma TITLE President	DATE 8/29/2018
	Imonoil.com PHONE: 214-244-4852
For State Use Only	
APPROVED BY: Marhentitaten TITLE PES	DATE 09/04/2018
Conditions of Approval (if any):	α το προστρατικό τη μαρική τη μα
C103 INTENT TO P&A EXPIRES	
1 YEAR FROM DATE OF APPROVAL	

