

Submit 1 Copy To Appropriate District		Earry C 102		
Office	State of New Mexico	Form C-103 Revised July 18, 2013		
<u>District I</u> (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO.		
<u>District II</u> - (575) 748-1283	OIL CONSERVATION DIVISION	30-025-01033		
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, NM 87525 2018	STATE FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTIO	CES AND REPORTS ON WERESCEIVED	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		State BD		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number 003		
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator Pogo Oil and Gas Operating, Inc		9. OGRID Number 372000		
3. Address of Operator 1515 Calle Sur, Suite 174		10. Pool name or Wildcat		
Hobbs, NM 88240		SWD Devonian		
4. Well Location				
Unit LetterI:	_1980feet from theSOUTHline and	_660feet from theEASTline		
Section 2 Township 12S Range 33E NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
2. 人名法法法法 合理系 经清楚接触的数据 等等的				
12 Check A	ppropriate Box to Indicate Nature of Notice,	Report or Other Data		
		-		
		SEQUENT REPORT OF:		
	PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON PLUG REMEDIAL WOR CHANGE PLANS COMMENCE DR			
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DR			
OTHER:				
	eted operations. (Clearly state all pertinent details, an k). SEE RULE 19.15.7.14 NMAC. For Multiple Co			
proposed completion or reco		inprotions. Auton wonoore augrain of		
Made 2 attempts for 9 days to fish corroded/parted tbg. All attempts have failed. Recovered both pieces of tbg and csg during fishing.				
Notify NMOCD 24 hours before oper	ations begin			
had				
Set steel pit. MIRU PU. NU BOP. RIH w/ wireline and set CIBP @ 1,750'. RIH w/ tbg and tag CIBP. PU and circulate well w/ gelled brine Circulate hole w/ Class "C" cmt to surface. POOH, RD plugging unit. See Attached Conditions of Approval				
RIH w/ tbg and tag CIBP. PU and circulate well w/ gelled brine Circulate hole w/ Class "C" cmt to surface.				
POOH, RD plugging unit.	Cona	luone :		
Clear off wellsite, cut off wellhead and anchors, set DHM, remediate location per OCD requirements.				
Saud Data				
Spud Date:	Rig Release Date:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
- Λ				
$\frac{1}{2} \frac{1}{2} \frac{1}$				
SIGNATURE La TITLE Michon Manger DATE 11 22 18				
Type or print name M. Y. (Merch) Merchante-mail address: mymerch penrocoil. comPHONE 575)492-1236				
APPROVED BY: Mahlulihum TITLE P.E.S. DATE 11/27/2018				
APPROVED BY: Manuel	ITILE (, , , c)	DATE TITE TOTOL		

Conditions	of Approval	(if any):

r,





Conditions of Approval

Pogo Oil and Gas Operating, Inc State BD #3 30-025-01033

Load hole and pressure test.

If casing will not test. Locate hole(s) in 7" casing and contact NMOCD.

If 7" casing test, perforate 5' above top of fish.

Set cement retainer 200' above perforation.

Squeeze with 50 sacks Class C cement.

Displace to 100' below cement retainer.

Sting out of retainer and circulate clean.

WOC 4 hours.

Sting into retainer and pressure test.

If test fails, repeat squeeze until test holds.

Spot 25 sacks cement on retainer.

Circulate mud laden fluid up to 370' in 7" casing.

Perforate 7' casing at 376'.

Circulate cement to surface inside/outside 7" casing.

Cut off wellhead 3' below ground level.

Verify cement to surface all strings.

Install upright P&A marker.

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.