Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office Energy Minerals and Natural Descurses	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr.	30-025-35318 /
1220 South St. Flancis Di.	5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM DEC 2 0 2018 Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPERATE TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	South Hobbs (G/SA) Unit
1. Type of Well: Oil Well Gas Well fther:	8. Well Number 241
2. Name of Operator Occidental Permian Ltd.	9. OGRID Number: 157984
3. Address of Operator	10. Pool name or Wildcat: Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location (Surface)	
Unit Letter M: 1063 feet from the North line and 498	· /
Section 4 Township 19S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, etc.,	NMPM Lea County
3630' (KB)	
	programme destruction and the second
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WOR	·
TEMPORARILY ABANDON	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	TJOB 🔲
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PRTD of 4360'. 	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' 	npletions: Attach wellbore diagram of graph of graph of graph of this procedure we plan to use
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Durin Acid stimulate completion interval from 4126-4338' 	g this procedure we plan to use osed-loop system with a steel
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. RDMO PU. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU PU. NDWH. NU BOP. POOH with ESP and production tubing. Trip bit and scraper to PBTD of 4360'. Densify perforations from 4325-4338' Acid stimulate completion interval from 4126-4338' Run new ESP. 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. disposition 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. disposition 	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Spud Date: Rig Release Date:	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge.	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Spud Date: Rig Release Date:	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Production Engineer Type or print name Jake Perry E-mail address: Jake Perry@oxy.com	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Production Engineer Type or print name Jake Perry E-mail address: Jake Perry@oxy.com For State Use Onty	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 e and belief. DATE 12/18/2018 PHONE: 713-215-7546
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) MIRU PU. NDWH. NU BOP. 2) POOH with ESP and production tubing. 3) Trip bit and scraper to PBTD of 4360'. 4) Densify perforations from 4325-4338' 5) Acid stimulate completion interval from 4126-4338' 6) Run new ESP. 7) RDMO PU. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Production Engineer Type or print name Jake Perry E-mail address: Jake Perry@oxy.com	g this procedure we plan to use osed-loop system with a steel and haul contents to the required sal per ODC Rule 19.15.17 e and belief. DATE 12/18/2018 PHONE: 713-215-7546