Submit 1 Copy To Appropriate District State of New Me	xico	Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natu	ral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-23568
811 S. First St., Artesia, NM 88210 OIL CONSERVATION		5_Indicate Type of Lease
District III - (505) 334-6178         1220 South St. France           1000 Rio Brazos Rd., Aztec, NM 87410         South St. France	icis Dr.	
District IV         – (505) 476-3460         Santa Fe, NM 87           1220 S. St. Francis Dr., Santa Fe, NM         5000         5000	HOBBS O	6. State Oil & Gas Lease No.
87505	HOP	312479
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO		7. Lease Name or Unit Agreement Name
	JG BACKATO'A DR SUCH RECE	NEVACUUM ABO UNIT
PROPOSALS.)         1. Type of Well: Oil Well         Gas Well         Other	RECE	8. Well Number 145
2. Name of Operator		9. OGRID Number
CROSS TIMBERS ENERGY, LLC		298299
3. Address of Operator		10. Pool name or Wildcat
400 W 7TH STREET, FORT WORTH, TX 76102 4. Well Location		VAC; ABO, NORTH
Unit Letter P : 660 feet from the S	line and	860 feet from the E line
······································	unge 34-E	NMPM County LEA
11. Elevation (Show whether DR)		
4035 GR		
12. Check Appropriate Box to Indicate N	ature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:	SUB	SEQUENT REPORT OF:
	REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRI	
DOWNHOLE COMMINGLE	CASING/CEIVIEN	
		_
13. Describe proposed or completed operations. (Clearly state all j	pertinent details, and	
	pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.	oertinent details, and C. For Multiple Cor	mpletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F</li> </ul>	oertinent details, and C. For Multiple Cor	mpletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.	oertinent details, and C. For Multiple Cor	mpletions: Attach wellbore diagram of
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> </ul>	C. For Multiple Con BOP. RIH W 5 1/	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/</li> </ul>	SOP. RIH W 5 1/ 8", 10' x 2 3/8" J	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr</li> </ul>	SOP. RIH W 5 1/ 80P. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD,</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J rom o/o tool. Cir ok to test witho	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J rom o/o tool. Cir ok to test witho	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD,</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J rom o/o tool. Cir ok to test witho	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD,</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J rom o/o tool. Cir ok to test witho	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD,</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J. om o/o tool. Cir ok to test witho ac trk	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J. om o/o tool. Cir ok to test witho ac trk	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi
<ul> <li>13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970
<ul> <li>13. Describe proposed or completed operations. (Clearly state all j of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU F RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970 Rig Release Da SIGNATURE SIGNATURE SIGNATURE TITLE Regulation</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J form o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970 e and belief. DATE_04/15/2019
<ul> <li>13. Describe proposed or completed operations. (Clearly state all j of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970 Rig Release Da</li> <li>I hereby certify that the information above is true and complete to the backside signantha Avarello E-mail address</li> </ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J form o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970
<ul> <li>13. Describe proposed or completed operations. (Clearly state all j of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970 Rig Release Da</li> <li>I hereby certify that the information above is true and complete to the beside SIGNATURE Summerflae defauellos TITLE Regulation Title Regulation of the state of t</li></ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970 e and belief. DATE 04/15/2019 partners.com PHONE: 817-334-7747
<ul> <li>13. Describe proposed or completed operations. (Clearly state all j of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970 Rig Release Da</li> <li>I hereby certify that the information above is true and complete to the beside SIGNATURE Summerflae defauellos TITLE Regulation Title Regulation of the state of t</li></ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J om o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970 e and belief. DATE 04/15/2019 partners.com PHONE: 817-334-7747
<ul> <li>13. Describe proposed or completed operations. (Clearly state all j of starting any proposed work). SEE RULE 19.15.7.14 NMAC proposed completion or recompletion.</li> <li>04/01/19 - MIRU PU, RU vac truck, NDWH, NU H RD tbg tester &amp; vac trk.</li> <li>04/02/19 - Cont to test RIH w 43 jts 2 3/8", 4' x2 3/ trk. test backside 360 psi for 30 min. Held ok. Rel fr tool. ND BOP, NU WH. RU MIT (contacted OCD, for 35 mins, end at 360 psi. Held ok. RD pmp trk, v</li> <li>Spud Date: 09/22/1970 Rig Release Da</li> <li>I hereby certify that the information above is true and complete to the beside SIGNATURE Summerflae defauellos TITLE Regulation Title Regulation of the state of t</li></ul>	bertinent details, and C. For Multiple Con BOP. RIH W 5 1/ 8", 10' x 2 3/8" J form o/o tool. Cir ok to test witho ac trk te:	mpletions: Attach wellbore diagram of /2" Baker Arrowset Prk, tested 220 jts, 55 PIC tbg. Set Pkr @ 8468'. RU pump c 200 bbl of pkr fluid. Latch on to o/o ut OCD present). Run MIT at 360 psi 0/22/1970 e and belief. DATE 04/15/2019 partners.com PHONE: 817-334-7747