UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

_	
5.	Lease Serial No.
	NMI C032104

SUNDRY N	OTICES AND	REPORTS OF	N WELLS
Do not use this	form for propo	sals to drill or	to re-enter an
abandoned well.	Use form 3160)-3 (APD) for so	ich proposals.

6. If Indian, Allottee or Tribe Name	•
--------------------------------------	---

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on pattobbs ocd					7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Gas Well □ Oth		-		·	8. Well Name and No.			
2. Name of Operator Contact: NICK GLANN CHEVRON USA INCORPORATED E-Mail: NGLANN@CHEVRON.COM					9. API Well No. 30-025-20924-00-C1			
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706 3b. Phone No Ph: 661-59			(include area cout	IVED	10. Field and Pool or Exploratory Area BLINEBRY OIL & GAS TUBB OIL & GAS			
4. Location of Well (Footage, Sec., T	C., R., M., or Survey Description	n)	-		11. County or Parish,	State		
Sec 20 T22S R38E NWSW 19	980FSL 660FWL				LEA COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE (F NOTICE	REPORT, OR OTH	HER DATA		
TYPE OF SUBMISSION		_	ТҮРЕ С	F ACTION	·			
Notice of Intent	☐ Acidize	Dee	pen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	Hyd □ Hyd	raulic Fracturing	Reclam	ation	■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	New	Construction	☐ Recom	plete	Other		
☐ Final Abandonment Notice	☐ Change Plans	✓ Plug	and Abandon	☐ Tempo	rarily Abandon			
	Convert to Injection	☐ Plug	Back	■ Water 1	Disposal			
following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notices must be filed only after all redetermined that the site is ready for final inspection. 8-5/8" 24# @ 1286' w/ TOC @ surface, Dual 2 7/8" 6.5# @ 7245' (ea w/ TOC @ ~3000' Chevron respectfully requests to abandon this well as follows: 1. Notify BLM 24 hrs. prior to starting work, utilizing phone number in 2. MIRU single rig, pull rods, pull 2 1/16" tubing from west string, RDM 3. Run CBL in both strings rigless 4. MIRU coil, spot 95 sx CL C cmt in each tubing string f/ 6486' t/ ~30 results on TOC - match internal TOC to external TOC. (Drinkard, Tub Andres, Queen). WOC & tag. Pressure test each string to 500 psi / 10			COA's MO 000', depending bb, Blineberry, 0	on CBL Glorieta, San	SEE ATTA(CONDITIO	·		
& one string fails, plug failed s 14. I hereby certify that the foregoing is Commit Name (Printed/Typed) NICK GLA	true and correct. Electronic Submission # For CHEVRON itted to AFMSS for proces	462253 verifie	d by the BLM Wo DRATED, sent t RAH MCKINNEY	ell Informatio	•			
Name (17/mea/1)/pea/ NICK GEF	1111		THE FOAL	NGINEER				
Signature (Electronic S	Submission)		Date 04/22/2	2019				
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE			
Approved By Anne	a A. Amrs	<i>-</i>	Title 57	ET		6-1-19 Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office CFC					
Title 8 U.S. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations a	s to any matter w	rson knowingly an thin its jurisdiction	d willfully to m	ake to any department or	agency of the United		
(T								

(Instructions on page 2) ** BLM REVISED ** BLM REVI 27 NMOCD 6-12-19

Additional data for EC transaction #462253 that would not fit on the form

32. Additional remarks, continued

Salt). WOC & tag. If both pass, plug one of the strings as detailed. If both strings fail, discuss with Chevron engineer & BLM engineer for plan forward. RDMO coil.

5. MIRU double rig, perf & squeeze remaining string w/ 410 sx CL C cmt f/ ~3000' t/ 1336' (Yates, B. Salt, T. Salt). WOC & tag. Cut & pull tubing that did not pass pressure test @ 1336'. Cut & pull tubing that did pass pressure test @ 1336' and use it to spot 455 sx CL C cmt f/ 1336' t/ surface (Shoe, Fresh Water). RDMO

6. Cut off wellhead 3' below grade, Verify Cement To Surface, install required dry hole marker as per COA's, turn over to reclamation.

All cement plugs will be class "C" with a closed loop system used.

Well: A. H. Blinebry Federal NCT-1 #17

Field: Tubb Oil & Gas

Reservoir: DHC - TUBB/Blinebry

Location:

1980' FSL & 660' FWL Section: 20 Township: 22S Range: 38E Unit: L County: Lea State: NM


Elevations:

GL: 3393'

Log Formation Tops			
Rustler	2195		
Salt	1380		
B/Salt	2510		
Yales	2642		
Queen	3460		
San Andres	4276		
Glorieta	5188		
Blinebry	5614		
Tubb	6153		
Drinkard	6436		

bg Detail: (WEST STRING) 96 JTS 2 1/16 2.66# INTEGRAL 1.751ID 1.657 PRIFT 6197'

- Bull Plug Mud Anchor 15' EOT



String 1: 2 7/8" 6.5# J-55 @ 7245 (east) String 2: 2 7/8" 6.5# J-55 @ 7248 (west) Cmt: 1000 sx each string

Hole Size: 7 7/8" to 7250 Circ: No TOC: 3000 TOC By:

Proposed Wellbore Diagram





Chevno: FB4397 API No: 30-025-20924

Spud Date: 6/23/64

Compl. Date: 8/10/64

Surface Csg: 8 5/8" 24# J-55 Set: w/ 600 sx cmt

Hole Size: 11" TO 1286' Circ: Yes TOC: Surface TOC By: Circulation

Cut tubing string that did pass the pressure test @ 1336' & use to lay 455 sx CL C cmt fl 1336' tl surface (Shoe, Fresh Water)

Cut & pull tubing string that did not pass pressure test @ 1336'

Perf & squeeze 410 sx CL C cmt into tubing string that did pass pressure test f/ \sim 3000' t/ 1336'. WOC & tag (Yates, B. Salt, T. Salt)

Spot 45 sx CL C cmt Into tubing string that did not pass pressure test ff ~3000' t/ 1336'. WOC & tag (Yates, B. Salt, T. Salt)

Spot 95 sx CL C cmt in each tubing string f/ 6486' t/ ~3000', depending on CBL results on TOC - match it to external TOC. (Drinkard, Tubb, Blineberry, Glorieta, San Andres, Queen). WOC & tag. Pressure test each string t/ 500 psi

Perfs

Status

5628' - 5718' 5708' - 5718'

Blinebry - open Commingled perfs


6155'-6228'

Tubb - open

TD: 7000' COTD: 6995' PBTD: 6988' COTD: 6993' PBTD: 6986'

Updated: 5/3/2018

By: EWRS



TD: 7000' COTD: 6995' PBTD: 6988' COTD: 6993' PBTD: 6986'

Updated: 5/3/2018

By: EWRS

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

- "Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.
 - 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.