

| Submit I Copy To Appropriate District State of New Mexico | Form C-103 |
|--|--|
| District I – (575) 393-6161 Energy, Minerals and Natural Resources | Revised August 1, 2011 WELL API NO. |
| 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 811 S. First St. Arteria NM 88210 OIL CONSERVATION DIVISION | 30-025-24254 |
| 811 S. First St., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III - (505) 334-61781220 South St. Francis Dr. | 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | STATE X FEE 6. State Oil & Gas Lease No. Image: Contract of the state of |
| District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON 1003 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK AND DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | B-934 |
| SUNDRY NOTICES AND REPORTS ON TO BE | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK THAT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | NEW MEXICO M STATE |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other | 8. Well Number |
| DELL' | 065 |
| 2. Name of Operator GP II ENERGY, INC. | 9. OGRID Number 8359 |
| 3. Address of Operator | 10. Pool name or Wildcat |
| P.O. BOX 50682, MIDLAND, TEXAS 79710 | LANGLEY MATTIX 7-R, QN., GYBR. |
| 4. Well Location | |
| | et from the WEST line |
| | 37E NMPM EDDY County |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,368' – GR | |
| | |
| 12. Check Appropriate Box to Indicate Nature of Notice, | Report or Other Data |
| | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON X | |
| TEMPORARILY ABANDON 🗍 CHANGE PLANS 🔲 COMMENCE DRI | |
| PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN | ГЈОВ 🔲 |
| | |
| | |
| OTHER: OTHER: | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and | |
| | |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Cor proposed completion or recompletion. | npletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). | npletions: Attach wellbore diagram of WELL W/ M.L.F. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SH0 PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'- | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHG PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SH0 PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'- | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHC PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO CSGS. X INSTALL DRY HOLE MARKER. | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. OE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHC PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OF PLATE TO CSGS. X INSTALL DRY HOLE MARKER. | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. OE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHC PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO CSGS. X INSTALL DRY HOLE MARKER. | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. OE); WOC X TAG CMT. PLUG. 3'. ON ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHC PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO CSGS. X INSTALL DRY HOLE MARKER. | NPIETIONS: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W 4) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SH(6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. (PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. | NPIETIONS: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approximate |
| Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHC PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO CSGS. X INSTALL DRY HOLE MARKER. | NPIETIONS: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approximate |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W 4) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SH(6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. (PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. | NPIETIONS: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approximate |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W 4) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 372'-272' (8-5/8" CSG.SH(6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. (PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. | NPIETIONS: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approximate |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. N 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W 4) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHG 6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OF PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. OE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approval e and belief. DATE: 07/05/19 |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. N 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 2,400'-2,280' (B/SALT); W 4) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 372'-272' (8-5/8" CSG.SHG 6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OF PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approval e and belief. |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 6) PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 3,72'-272' (8-5/8" CSG.SHI 6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OF PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE SIGNATURE I hereby a print name: DAVID A. EYLER For State Use Only | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. DE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approval e and belief. DATE: 07/05/19 RO-RES.COM PHONE: 432.687.3033 |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1) SET 5-1/2" CIBP @ 3,450'; PUMP 25 SXS. CMT. @ 3,450'-3,320'; CIRC. V 2) PUMP 25 SXS. CMT. @ 2,710'-2,590' (T/YATES). 3) PERF. X ATTEMPT TO SQZ. 45 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 5) PERF. X ATTEMPT TO SQZ. 100 SXS. CMT. @ 1,425'-1,074' (T/SALT, T 6) PERF. X ATTEMPT TO SQZ. 35 SXS. CMT. @ 3,72'-272' (8-5/8" CSG.SHI 6) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 20 SXS. CMT. @ 63'-7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OF PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYST CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17. I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE SIGNATURE I hereby a print name: DAVID A. EYLER For State Use Only | npletions: Attach wellbore diagram of WELL W/ M.L.F. /OC X TAG CMT. PLUG. /ANHY.); WOC X TAG CMT. PLUG. OE); WOC X TAG CMT. PLUG. 3'. DN ALL ANNULI; WELD ON STEEL EM W/ A STEEL TANK AND HAUL See Attached Conditions of Approval e and belief. DATE: 07/05/19 |





DAE 07/04/19

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class
 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.