

	Form C-103
Office District I - (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St. Artesia NM 88210 OIL CONSERVATION	WELL API NO. 30-025-29169
	5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV - (505) 476-3460 Santa Fe, NN (87900)	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	312820
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	_
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	BRIDGES STATE SEC 24
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 198
2. Name of Operator	9. OGRID Number
CROSS TIMBERS ENERGY, LLC 3. Address of Operator	298299 10. Pool name or Wildcat
•	
400 W 7TH STREET, FORT WORTH, TX 76102 4. Well Location	VACUUM;GRAYBURG-SAN ANDRES
Unit Letter M: 1310 feet from the S line and	1320 feet from the W line
	NMPM County LEA
Section 24 Township 17-S Range 34-E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	, 2211
4011 GR	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
/ w ·	•
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	
	<u> </u>
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins.	mpletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class F	mpletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class F TOC @ 4,235')	mpletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class F TOC @ 4,235')	mpletions: Attach wellbore diagram of I cement on top. WOC. Tag TOC (est'd
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class F TOC @ 4,235') 3. Circulate hole w/ mud laden fluid	mpletions: Attach wellbore diagram of H cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Woldship to the start of the s	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Woldship to the start of the s	mpletions: Attach wellbore diagram of H cement on top. WOC. Tag TOC (est'd OC. Tag TOC. OC. Tag TOC. OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. We 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. We 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. We 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h	mpletions: Attach wellbore diagram of H cement on top. WOC. Tag TOC (est'd OC. Tag TOC. OC. Tag TOC. OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Woldship to the start of the s	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. We 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. We 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. We 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. We 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. We 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. We 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground).	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry hard ground).	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry hard ground).	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground). Spud Date: O5/03/1985 Rig Release Date:	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry hard ground).	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground). Spud Date: O5/03/1985 Rig Release Date:	I cement on top. WOC. Tag TOC (est'd OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. We 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. We 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. We 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground). Spud Date: O5/03/1985 Rig Release Date: O5 I hereby certify that the information above is true and complete to the best of my knowledge.	Attach wellbore diagram of the cement on top. WOC. Tag TOC (est'd to C). Tag TOC. OC. Tag TOC. OC. Tag TOC. OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Work 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Work 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Work 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry by ground). Spud Date: O5/03/1985 Rig Release Date: O5/03/1985 TITLE Regulatory Technicia	Attach wellbore diagram of the cement on top. WOC. Tag TOC (est'd to C). Tag TOC. OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Wo 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Wo 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Wo 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground). Spud Date: O5/03/1985 Rig Release Date: O5 I hereby certify that the information above is true and complete to the best of my knowledge. SIGNATURE Title Regulatory Technicia Type or print name Samanntha Avarello E-mail address: savarello@mss	Attach wellbore diagram of the cement on top. WOC. Tag TOC (est'd to C). Tag TOC. OC. Tag TOC. OC. Tag TOC. OC. Tag TOC.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class H TOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Wo 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Wo 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Wo 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry H ground). Spud Date: O5/03/1985 Rig Release Date: O5/03/1985 TITLE Regulatory Technician Type or print name Samanntha Avarello E-mail address: savarello@mssFor State Use Only	Attach wellbore diagram of the cement on top. WOC. Tag TOC (est'd to the control of the cement on top. WOC. Tag TOC (est'd to the control of the cement on top. WOC. Tag TOC (est'd to the cement on top. WOC. Tag Toc. Tag Toc. Tag Toc. Tag To
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 1. Test casing to 500 psi for 15 mins. 2. TIH and tag top of cmt on CIBP @ est'd 4,445'. Spot 25 sx Class FTOC @ 4,235') 3. Circulate hole w/ mud laden fluid 4. Spot 25 sx Class H cement balanced plug from 2,775' - 2,985'. Wo 5. Spot 25 sx Class H cement balanced plug from 2,100' - 2,310'. Wo 6. Spot 25 sx Class H cement balanced plug from 1,555' - 1,765'. Wo 7. Spot 30 sx Class H cement from 250' to surface. 8. Cut off wellhead. Verify cmt to surface on all strings. Install dry h ground). Spud Date: O5/03/1985 Rig Release Date: O5 I hereby certify that the information above is true and complete to the best of my knowledge. SIGNATURE Title Regulatory Technicia Type or print name Samanntha Avarello E-mail address: savarello@mss	Attach wellbore diagram of the cement on top. WOC. Tag TOC (est'd to C). Tag TOC. OC. Tag TOC.



UPDATED: 10/14/2019



UPDATED: 10/14/2019

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.