

Submit I Copy To Appropriate District	State of Ne	w Mexico	Form C-1	03
Office	Energy, Minerals an		Revised July 18, 20	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, winteruis un		WELL API NO. 30-025-26065	
<u>District II</u> - (575) 748-1283	OIL CONSERVA	TION DIVISION		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South S		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE	
<u>District IV</u> $-$ (505) 476-3460	Santa Fe, 1	NM 8/505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPE DIFFERENT RESERVOIR. USE "APPL PROPOSALS.) 1. Type of Well: Oil Well	ICES AND REPORTS ON V	WELLS	7. Lease Name or Unit Agreement Name	e
(DO NOT USE THIS FORM FOR PROPO	DSALS TO DRILL OR TO DEEPEN	OR PHORETOA	STATE 32	
PROPOSALS)	ICATION FOR PERMIT" (FORM C	C-IOI) FOR SUMPO	D	
1. Type of Well: Oil Well	Gas Well 🔲 SWD 🗌	NOV 9 -	8. Well Number #001	
2. Name of Operator	KEVIN O BUTLER & ASS		9. OGRID Number 12627	
		REAL		
3. Address of Operator		RECEIVED	10. Pool name or Wildcat	
P.O. Box 1171 Midland TX, 7970	12		MALJAMAR; CISCO	
4. Well Location	· · ·		<b>***</b>	
Unit Letter K	: 1980 feet from	theSOUTH	line and1980feet from t	he
WEST line				
Section 32	Township	16S Range 33	E NMPM LEA Count	
	11. Elevation (Show wheth	······································		2
	11. Elevation (Briow when	4222		
12. Check Appropriate Box	to Indicate Nature of No		Data	
12. Check Appropriate Dox			2444	
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🗍		🛛 ┢   REMEDIAL WOR	K 🛛 ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. 🗍 PAND A [	
PULL OR ALTER CASING	] MULTIPLE COMPL [		Т ЈОВ 🔲	
DOWNHOLE COMMINGLE	- <u>-</u>		_	
OTHER:			Ĩ	
			d give pertinent dates, including estimated	date
of starting any proposed w	1) OPE DUILE 10 VEG 14	NMAC For Multiple Con	malational Attach wallband discuss of	
		NMAC. For Multiple Col	mpletions: Attach wellbore diagram of	
proposed completion or re		NMAC. For Multiple Col	mpletions: Attach wellbore diagram of	
proposed completion or re 1. Test anchors	completion.	NMAC. For Multiple Col	mpletions: Attach welloore diagram of	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr	completion. and TOH w/ tubing.			
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031	0' w/WL dump 35' class F	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole	0' w/WL dump 35' class F	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole '', WOC & tag.	0' w/WL dump 35' class F	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole i', WOC & tag. rod csg 2 squeeze holes @ 44	0' w/WL dump 35' class F	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole I', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole I', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole i', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 v/50sxs class C cmt. 50 in & 5	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry b	completion. and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole i', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 v/50sxs class C cmt. 50 in & 5 hole marker.	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry 1 11. Cut the well head, RD, cut anch	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole l', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. nors, clean location, and move	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry b	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole l', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. nors, clean location, and move	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry l 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole i', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag w/50sxs class C cmt. 50 in & 5 hole marker. tors, clean location, and move OCD & surface owners require	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface e out. ements.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry 1 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will 1	and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole ', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. hors, clean location, and move OCD & surface owners required be contained in steel pit & have	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface e out. ements. uled off to approved dispos	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry 1 11. Cut the well head, RD, cut anch	and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole ', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. hors, clean location, and move OCD & surface owners required be contained in steel pit & have	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface e out. ements.	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry 1 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will 1	and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole ', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. hors, clean location, and move OCD & surface owners required be contained in steel pit & have	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface e out. ements. uled off to approved dispos	t cement on top of CIBP. WOC 4 hrs. Tag. T 25 5x CLOSSC 1500 T/S Conditions Altached	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry 1 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will 1	and TOH w/ tubing. 0'. Run and set CIBP @1031 g, come up and circulate hole ', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag v/50sxs class C cmt. 50 in & 5 hole marker. hors, clean location, and move OCD & surface owners required be contained in steel pit & have	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50 out. Circulate to surface e out. ements. uled off to approved dispos	I cement on top of CIBP. WOC 4 hrs. Tag.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date:	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 50 in & 5 hole marker. 10 cms, clean location, and move 10 CD & surface owners required be contained in steel pit & han Rig Rele	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50' 60 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5X CLOSS C 1500 T/S CONDISONS OF AND Sal facility.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry l 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will l Spud Date:	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 50 in & 5 hole marker. 10 cms, clean location, and move 10 CD & surface owners required be contained in steel pit & han Rig Rele	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50' 60 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5x CLOSSC 1500 T/S Concise Altached sal facility. ge and belief.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry l 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will l Spud Date:	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1'50sxs class C cmt. 50 in & 5 1'50sxs class C cmt. 50 in & 5 hole marker. 1'ors, clean location, and move 1'CD & surface owners required be contained in steel pit & hat Rig Rele 1'' above is true and complete t	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug. 50' 60 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5x CLOSSC 1500 T/S Concise Altached sal facility. ge and belief.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATURE	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 hole marker. 10ors, clean location, and move 10CD & surface owners required the contained in steel pit & hav Rig Release 1 above is true and complete to 11TLE	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:  o the best of my knowledg Production Manage	H cement on top of CIBP. WOC 4 hrs. Tag. 1 25 5x CLOSS C 1500 T/S Conditions of Altechad sal facility. ge and belief. parte_11[22[19]	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATUREM.Y. Me	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 hole marker. 10ors, clean location, and move 10CD & surface owners required the contained in steel pit & hav Rig Release 1 above is true and complete to 11TLE	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:  o the best of my knowledg Production Manage	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5x CLOSSC 1500 T/S Concise Altached sal facility. ge and belief.	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATUREM.Y. Me For State Use Only	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 5 1/50sx	0' w/WL dump 35' class F w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispose ease Date:  o the best of my knowledg Production Manage	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5X CLOSS C 1500 T/S Convisions of Altechast sal facility. The and belief. TrDATE 11/22/19 HONE: _575-492-1236_	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATUREM.Y. Me For State Use Only	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 5 1/50sx	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispos ease Date:  o the best of my knowledg Production Manage s:mymerch@penrocod	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5X CLOSS C 1500 T/S Convisions of Altechast sal facility. The and belief. TrDATE 11/22/19 HONE: _575-492-1236_	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATUREM.Y. Me For State Use Only	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 5 1/50sx	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispos ease Date:  o the best of my knowledg Production Manage s:mymerch@penrocod	H cement on top of CIBP. WOC 4 hrs. Tag. 1 25 5x CLOSS C 1500 T/S Conditions of Altechad sal facility. ge and belief. parte_11[22[19]	
proposed completion or re 1. Test anchors 2. RU WSU. NU BOP. Unseat pkr 3. RU WL. Run gauge ring to 1010 4. TIH w/pkr & 2-3/8" tbg, tag plug 5. Spot 35sxs Class H cmt, @ 7300 6. TOH, RU wireline, perf 5 1/2" P 7. TIH w/pkr&tbg. Pump 50sxs Cla 8. Perf 2 holes @ 2650', Squeeze w 9. Perf 2 holes @ 1000', Squeeze w 10. Put 5sxs @ surface. Install dry I 11. Cut the well head, RD, cut anch 12. Rehab within 90 days per NMC P.S. No earthern pit, all fluids will I Spud Date: I hereby certify that the information SIGNATUREM.Y. Me	and TOH w/ tubing. 10'. Run and set CIBP @1031 g, come up and circulate hole 1', WOC & tag. 1'rod csg 2 squeeze holes @ 44 ass C cmt, 50 in & 50 out. Tag 1/50sxs class C cmt. 50 in & 5 1/50sxs class C cmt. 5 1/50sx	0' w/WL dump 35' class H w/ 10# gelled brine. 10'. g plug. 50 out. Tag plug 50 out. Circulate to surface e out. ements. uled off to approved dispos ease Date:  o the best of my knowledg Production Manage s:mymerch@penrocod	A cement on top of CIBP. WOC 4 hrs. Tag. T 25 5X CLOSS C 1500 T/S Convisions of Altechast sal facility. The and belief. TrDATE 11/22/19 HONE: _575-492-1236_	





## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.