
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resources	Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, winicials and Watural Resources	WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-025-04216
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
<u>District IV</u> (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH _	Eunice Monumnet South Unit B
PROPOSALS.)	TOBBS	
1. Type of Well: Oil Well X	Gas Well Other OCD-HOBBS	8. Well Number 865
2. Name of Operator	Gas Well Other OCD -12020 04/15/2020 04/15/2020	9. OGRID Number
XTO Energy, Inc	04/15/2020 01iday Hill, Rd #5 RECEIVED	005380
·····	-	10. Pool name or Wildcat
Midland, Tx 79707		
4. Well Location		
Unit Letter N	: 990 feet from the South line and	2310 feet from the <u>West</u> line
Section 11	Township 20S Range 36E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, et	<i>c.)</i>
3508' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		
PULL OR ALTER CASING	MULTIPLE COMPL	
	] [	
CLOSED-LOOP SYSTEM		_
OTHER:		
	upleted operations. (Clearly state all pertinent details, a	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of R	completion.	
XTO Energy, Inc. respectfully submits a subs	sequent report of PA operations on the above referenced well.	
XTO Energy, Inc. respectfully submits a subs 1. MIRU PU;	sequent report of PA operations on the above referenced well.	
1. MIRU PU; 2. NDWH, INSTALL BOP. Functio	n and pressure test as per XTO guidelines;	ondition of Approval: notify
MIRU PU;           2.         NDWH, INSTALL BOP. Function           3.         POOH & LD 2-7/8" TBG & ESP	n and pressure test as per XTO guidelines;	ondition of Approval: notify
MIRU PU;           NDWH, INSTALL BOP. Functio           POOH & LD 2-7/8" TBG & ESP           MIRU WL;           SET A CIBP @~3,665";	n and pressure test as per XTO guidelines;	ondition of Approval: notify OCD Hobbs office 24 hours
MIRU PU;           NDWH, INSTALL BOP. Function           POOH & LD 2-7/8" TBG & ESP           MIRU WL;           S.           SET A CIBP @~3,665";           6.           POOH LD SETTING TOOL;	n and pressure test as per XTO guidelines; C	OCD Hobbs office 24 hours
MIRU PU;           NDWH, INSTALL BOP. Function           POOH & LD 2-7/8" TBG & ESP           MIRU WL;           S.           SET A CIBP @~3,665';           6.           POOH LD SETTING TOOL;           7.           RIH WBAILER & SPOT 35' OF           8.           POOH LD BAILER. RD WL;	n and pressure test as per XTO guidelines; C ; : : CMT FROM 3,665'. CALCULATED TOC @~3,630'; <b>Prio</b>	OCD Hobbs office 24 hours r of running MIT Test & Chart
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665';</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35' OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> </ol>	n and pressure test as per XTO guidelines; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	OCD Hobbs office 24 hours r of running MIT Test & Chart
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665';</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35' OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> </ol>	n and pressure test as per XTO guidelines; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665';</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35' OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> </ol>	n and pressure test as per XTO guidelines; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665';</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35' OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> </ol>	n and pressure test as per XTO guidelines; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665";</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35" OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> <li>IF TEST FAILS RIH WPKR &amp; F</li> </ol>	n and pressure test as per XTO guidelines; ; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665';</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35' OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> </ol>	n and pressure test as per XTO guidelines; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
<ol> <li>MIRU PU;</li> <li>NDWH, INSTALL BOP. Function</li> <li>POOH &amp; LD 2-7/8" TBG &amp; ESP</li> <li>MIRU WL;</li> <li>SET A CIBP @~3,665";</li> <li>POOH LD SETTING TOOL;</li> <li>RIH WBAILER &amp; SPOT 35" OF</li> <li>POOH LD BAILER. RD WL;</li> <li>RU PUMP AND PRESSURE TI</li> <li>IF TEST HOLDS RDMO ALL E</li> <li>IF TEST FAILS RIH WPKR &amp; F</li> </ol>	n and pressure test as per XTO guidelines; ; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS;
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @~3,665';         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35' OF         8.       POOH LD BAILER. RD WL;         9.       RU PUMP AND PRESSURE TH         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date:	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; AN FORWARD.
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @~3,665';         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35' OF         8.       POOH LD BAILER. RD WL;         9.       RU PUMP AND PRESSURE TH         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; ; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; AN FORWARD.
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; AN FORWARD.
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date:	OCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; AN FORWARD.
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG ANDCMT TO 500 PSI PUMP PRESSURE. MONTOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled	DCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; AN FORWARD. Ige and belief. DATE04/15/2020
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665". CALCULATED TOC @-3,630"; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled DOMO	DCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MINOF 30 MINS; ANFORWARD. Ige and belief. DATE04/15/2020
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIEP @~3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RD WL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL EI         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665". CALCULATED TOC @-3,630"; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled TITLE Regulatory Analyst	DCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MIN OF 30 MINS; ANFORWARD. Ige and belief. DATE04/15/2020
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIEP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST HOLDS RDMO ALL E         12.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled AMO	DCD Hobbs office 24 hours         r of running MIT Test & Chart         ART TEST FOR MIN OF 30 MINS;         ANFORWARD.         Ige and belief.         DATE       04/15/2020         DATE       432.218.3671         Date       04/15/2020
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIBP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL EI         11.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665". CALCULATED TOC @-3,630"; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled TITLE Regulatory Analyst	DCD Hobbs office 24 hours r of running MIT Test & Chart ART TEST FOR MINOF 30 MINS; ANFORWARD. Ige and belief. DATE04/15/2020
1.       MIRU PU;         2.       NDWH, INSTALL BOP. Function         3.       POOH & LD 2-7/8" TBG & ESP         4.       MIRU WL;         5.       SET A CIEP @-3,665";         6.       POOH LD SETTING TOOL;         7.       RIH WBAILER & SPOT 35" OF         8.       POOH LD BAILER. RDWL;         9.       RU PUMP AND PRESSURE TI         10.       IF TEST HOLDS RDMO ALL E         11.       IF TEST HOLDS RDMO ALL E         12.       IF TEST FAILS RIH WPKR & F         Spud Date:	n and pressure test as per XTO guidelines; CMT FROM 3,665'. CALCULATED TOC @~3,630'; EST PLUG AND CMT TO 500 PSI PUMP PRESSURE. MONITOR AND CH QUIPMENT; PLUG TO ISOLATE SOURCE OF LEAK NOTIFY ENGINEERING FOR PLA Rig Release Date: n above is true and complete to the best of my knowled AMO	DCD Hobbs office 24 hours         r of running MIT Test & Chart         ART TEST FOR MIN OF 30 MINS;         ANFORWARD.         Ige and belief.         DATE       04/15/2020         DATE       432.218.3671         Date       04/15/2020



## Eunice Monument South Unit B #865 (API 30-025-04216) - WELL CLASSIFICATION II