OCD-HOBBS				
Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.	
		WELLS	LC 058699	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
	reverse side.	7. If Unit or CA/Agreement, Name and/or No. 8920003410		
1. Type of Well Oil Well Gas Well		8. Well Name and No.		
2. Name of Operator ConocoPhillips Company	(MCA Unit #201 9. API Well No. 30-025-00710		
3a Address 4001 Penbrook, Odessa, Texas 79762	36. Phone No. 432-368-12	(include area code) 44	10. Field and Pool, or Exploratory Are	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Maljamar Grayburg-San And 11. County or Parish, State	<u>res</u>
1,295 FSL & 1,370 FWL, Section 26, T-17-5		Lea, New Mexico		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent	Casing Fracture Tre	at Production (Sta	Well Integrity	
	Repair New Constr Plans Plug and Ab		Other	
Einel Abandonment Nictice	rt to Injection	Water Disposal		
GENERAL AND SPECI ATTACHEI	nt Notices shall be filed only after al etion.) ure & wellbore diagrams SUBJECT TO REQUIREMENTS AL STIPULATS	I requirements, including reclama	ation, have been completed, and the open	√ED 2006
 I hereby certify that the foregoing is true a Name (Printed/Typed) 	and correct	Time trapte N Ser		
James F. Newman, P.E.	/	Title English Propie N Ser	rvices, Inc. 432-687-1994	
Signature		Date 0.	3/18/2006	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by Conditions of approval, if any, are attached. Appr certify that the applicant holds legal or equitable t which would entitle the applicant to conduct oper	tle to those rights in the subject least ations thereon.	se Office	Date	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Sec States any false, fictitious or fraudulent statements	ion 1212, make it a crime for any p or representations as to any matter	person knowingly and willfully twithin its jurisdiction.	to make to any department or agency o	f the United
(Instructions on page 2) GWW				

ķ

1

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: January 20, 2006 RKB @ 3957' -DF @ 3956' 3947 Subarea : Maljamar GL @ Lease & Well No. : MCA Unit No. 201 Lea State: New Mexico Maljamar (Grayburg-San Andres) Aug. 7, 1948 Rin Port 1295' FSL & 1370' FWL, Sec. 26, T-17-S, R-32-E Legal Description : County : Field : CSG LEAK 104' TO 907' Date Spudded : Oct. 10, 19948 30-025-00710 API Number : SQZ'D W/ 273 SX Status: **Temporarily Abandoned** TOC @ N/A Stimulation History: 12-1/4" Hole Lbs. Max Max Press ISIP <u>interval</u> Date <u>Type</u> Gals Sand <u>Rate</u> 10/9/48 Shoot 4076'-4131' w/140 quarts Nitro DEEPEN TO 4310' 8/5/71 4005-4043 8/9/71 Gel Wtr Frac 20,000 35,000 3300 1300 17.0 4255-4310 8/12/71 15% NE HCI 3,000 3000 1900 4005-4133 Trtd Prod Wtr 20,000 30,000 3800 13.9 8/14/71 1500 9/12/89 Set RBP @ 3863', csg leak 104' to 907' Squeeze w/273 sacks cement; retrieve RBP 8-5/8" 28# csg @ 1,187' w/ 75 sx 3896-4310 9/13/89 Frac 543 Bbis 36,600 16.0 Casing leak 856' to 862'. Top Salt @ 1,187 10/11/05 10/27/05 Set CIBP @ 2230'-2235' 10/28/05 Tubing leak in hole from 2249' to 3989' Rods left in hole 2257' to 3989' TEMPORARILY ABANDONED Removal of rods and tubing is required by NMOCD prior NOTE: to any plugging operation. There is approximately 1925' of rods and 1918' of tubing remaining to be recovered. वर्षे ता संच ते हुपु व करणणवीष्ट्रक 👘 Base Salt @ 2,210' 1. N. N. N. \geq CIBP @ 2,230 TOC @ 2,300 1743 TBG & RODS LEFT IN HOLE F/ 2,249 - 3,989' Formation Tops: Top Salt 1187 6-3/4" Hole Base Salt 2210 5-1/2" 14.4# Csg @ 3896" Cmt'd w/100 sx TOC @ 2,300' 4-1/2" Hole 4076'-4131' - Shot w/140 Qts Nitro OH 3896' - 4310' PBTD @ 2230 OTD @ 4135 NTD @ 4310



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #201 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

Casings: 8⁵/₈" 28# casing @ 1,187' cmt'd w/ 75 sx 5¹/₂" 14# casing @ 3,896' cmt'd w/ 100 sx, TOC 2,300'

- TA'd w/ CIBP set @ 2,230' (10/27/05) after unsuccessful multi-day fishing attempt to recover tubing & rods 2,257 – 3,989'
- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- **1.** Set steel pit and flow down well as needed. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.
- 2. RIH w/ four 1-11/16" link-jet perforating charges on wireline, tag CIBP @ 2,230', PU and perforate four squeeze holes @ 2,230'. POOH w/ wireline.
- POOH w/ AD-1 packer to 2,000'. Load hole w/ mud, set packer, and establish rate into perforations at 1,000 psi or less. Squeeze 75 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 99.0 ft³ slurry volume, calculated fill 292' in 7¹/₈" open hole) 2,230 2,130'. WOC & tag this plug no deeper than 2,130'. Base of salt plug
 - RIH w/ four 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 1,237'. POOH w/ wireline. POOH w/ Ad-1 packer to 900'. Set packer and establish rate into perforations at 1,000 psi or less. Squeeze 60 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 79.2 ft³ slurry volume, calculated fill 234' in 7%" open hole) 1,237 1,137'. WOC & tag this plug no deeper than 1,137'. Top of Salt & surface casing shoe plug
 - RIH w/ four 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 400'. POOH w/ wireline. RIH w/ AD-1 packer to 30'. Set packer and establish rate. Squeeze 80 sx C cmt (1.32 ft³/sk yield, 106 ft³ slurry volume, calculated fill 129' in 12¼" open hole) 400 300'. *freshwater plug*
 - 6. RIH w/ four 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 50'. POOH w/ wireline. ND BOP, NU wellhead. Circulate 40 sx C cement (1.32 ft³/sk yield, 52.8 ft³ slurry volume, calculated fill 64' in 12¼" open hole) 50' to surface. surface plug
 - 7. RDMO location. Clean steel pit & haul fluids to disposal. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

