Submit 3 Copies To Appropriate District	State of New Mexico		I	Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240		W	ELL API NO.	
District II	istrict II CONCEDIA TION DIVICIONI		30-025-36458	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Proves Dd. Artee NIM 97410		STATE 🛛 FEE	
District IV Santa Fe, NIVI 8/303		6.	State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	•		33037	
87505 SLINDRY NOT	ICES AND REPORTS ON WELLS	7	Lease Name or Unit Agree	ment Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BA		Lease Name of Omit Agree	ment rame
	CATION FOR PERMIT" (FORM C-101) FOR S U	Н	Rawhide 29 State	
PROPOSALS.)	Gas Well Other 22021222324	25. 8.	Well Number	
1. Type of Well: Oil Well	Gas Well Other	"CE3/	1	
2. Name of Operator	/ 🔊 🗸		OGRID Number	
Samson Resources Company	229	2)	20165	
3. Address of Operator		ီ မို့ 10	D. Pool name or Wildcat	
200 N. Loraine St., Ste. 1010; Mid	land, TX 79701 910 feet from the South lin Township 215 68 4 Ra	50/	Gramma Ridge East	
4. Well Location	/6.	11		
Unit Letter N	910 feet from the South lin	e and 1980	feet from the West	line
Section 29	Township 215 68 L Rai			County
Section 23	11. Elevation (Show whether DR, RKB		NIVITIVI Eca C	Jounty
1992	3638' GR	, K1, UK, etc.)		
Pit or Below-grade Tank Application				
Pit type Depth to Groundw		all Distance	e from nearest surface water	
			'	
Pit Liner Thickness: mil			uction Material	
12. Check	Appropriate Box to Indicate Nature	of Notice, Re	port or Other Data	
NOTICE OF IN	ITENTION TO	CLIDOE	OUTNE DEDODE OF	- .
	ITENTION TO:		QUENT REPORT OF	
PERFORM REMEDIAL WORK		MEDIAL WORK		CASING
TEMPORARILY ABANDON	<u> </u>	MMENCE DRILLI		
	MILLE TO LE COMOL II I CA	SING/CEMENT JO	OB 🖂	
PULL OR ALTER CASING	· · · · · · · · · · · · · · · · · · ·			⊠
OTHER:	ОТ	HER: Temp	orarily Abandon	<u> </u>
OTHER:	OT OT OT OT	HER: Temperature T	orarily Abandon ve pertinent dates, including	g estimated date
OTHER: 13. Describe proposed or composed or starting any proposed w	ОТ	HER: Temperature T	orarily Abandon ve pertinent dates, including	g estimated date
OTHER: 13. Describe proposed or composed or starting any proposed wor recompletion.	OT OT OT OT	HER: Temperature T	orarily Abandon ve pertinent dates, including	g estimated date
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06	OT letted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Co	HER: Temper ent details, and gi empletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo	g estimated date osed completion
OTHER: 13. Describe proposed or composed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a	OT OT OT OT	HER: Temper ent details, and gi empletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo	g estimated date osed completion
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'.	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w	HER: Tempent details, and gimpletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R	g estimated date used completion
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'.	OT letted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Co	HER: Tempent details, and gimpletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R	g estimated date used completion
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4%	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w	HER: Tempent details, and gimpletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R	g estimated date used completion
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Connd 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of	HER: Temper details, and gimpletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R BOP. NU wellhead.	g estimated date used completion
OTHER: 13. Describe proposed or composed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w	HER: Temper details, and gimpletions: Attach	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R BOP. NU wellhead.	g estimated date used completion
OTHER: 13. Describe proposed or compostarting any proposed was or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the cond at the	HER: Temper details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD	orarily Abandon ve pertinent dates, including n wellbore diagram of propo d JB to 12,535'. R BOP. NU wellhead.	g estimated date osed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L.	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperate details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD	orarily Abandon ve pertinent dates, including a wellbore diagram of propod d JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 %	g estimated date osed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L.	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperate details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD	orarily Abandon ve pertinent dates, including a wellbore diagram of propod d JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 %	g estimated date osed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L.	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the cond at the	HER: Temperate details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD	orarily Abandon ve pertinent dates, including a wellbore diagram of propod d JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 %	g estimated date osed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of %" bar. Tag @ 12,460'. POGRIH w/3.75" GR and JB to 1: '. POOH. Left 30' cmt on top of the state of the s	HER: Temperate details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD 2,450'. POO	orarily Abandon ve pertinent dates, including a wellbore diagram of propod d JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L.	g estimated date seed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperate details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD 2,450'. POO	orarily Abandon ve pertinent dates, including a wellbore diagram of propod d JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L.	g estimated date seed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Connd 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the wild before the w	HER: Temperature details, and gimpletions: Attach 73.72" GR and 6f CIBP. ND 6H. SWI. RD 60,450'. POO 600 of plug. 80 psi for 4	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressu	g estimated date seed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Connd 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the wild before the w	HER: Temperature details, and gimpletions: Attach 73.72" GR and 6f CIBP. ND 6H. SWI. RD 60,450'. POO 600 of plug. 80 psi for 4	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressu	g estimated date seed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key.	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Connd 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the wild before the w	HER: Temperature details, and gimpletions: Attach 73.72" GR and 6f CIBP. ND 6H. SWI. RD 60,450'. POO 600 of plug. 80 psi for 4	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressu	g estimated date seed completion
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the wind and with the wind and wind and with the wind and with the wind and with the wind and	HER: Tempent details, and gimpletions: Attach 73.72" GR and of CIBP. ND OH. SWI. RD 2,450'. POO cop of plug. 30 psi for 4 Temporary pires	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressu	g estimated date seed completion RIH w/10K 2" 13.5#
OTHER: 13. Describe proposed or compost of starting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the large of	HER: Temperated the sent details, and gimpletions: Attach and gimpletions: Attach and a sent and a sent a s	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 ½ RD E/L. 5 min. Rlse pressured belief. I further certify that	g estimated date osed completion RIH w/10K 2" 13.5# are. RD
OTHER: 13. Describe proposed or compost of starting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Connd 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the wild before the w	HER: Temperated the sent details, and gimpletions: Attach and gimpletions: Attach and a sent and a sent and a sent	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 ½ RD E/L. 5 min. Rlse pressured belief. I further certify that	g estimated date osed completion RIH w/10K 2" 13.5# are. RD
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of the	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperated the Temperated the Temporary pires Temporary pires Temporary present the Temporary pires Temporary pires Temporary present the Temporary pires	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-ap	g estimated date osed completion RIH w/10K 2" 13.5# are. RD any pit or below- proved plan
OTHER: 13. Describe proposed or compost of starting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperated the sent details, and gimpletions: Attach and gimpletions: Attach and a sent and a sent and a sent	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 ½ RD E/L. 5 min. Rlse pressured belief. I further certify that	g estimated date osed completion RIH w/10K 2" 13.5# are. RD any pit or below- proved plan
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	Deleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w. KCl. Dump 35' cmt on top of the condition of the co	HER: Temperated the second of CIBP. ND OH. SWI. RD OH.	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-ap	g estimated date psed completion RIH w/10K 2" 13.5# are. RD any pit or below- proved plan
OTHER: 13. Describe proposed or compost of starting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name J. L. Farrell,	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the work. Tag @ 12,460'. Pool RIH w/3.75" GR and JB to 1: '. POOH. Left 30' cmt on the work of the pump truck. Test casing 5. This Approval of Abandonment Examples above is true and complete to the best of relosed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and	HER: Temperated the second of CIBP. ND OH. SWI. RD OH.	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-appropriate to CD-appropriate to CD-appropri	g estimated date osed completion RIH w/10K 2" 13.5# are. RD any pit or below- proved plan
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name J. L. Farrell, For State Use Only	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the work. Tag @ 12,460'. Pool RIH w/3.75" GR and JB to 1: '. POOH. Left 30' cmt on the work of the pump truck. Test casing 5. This Approval of Abandonment Examples above is true and complete to the best of relosed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and	HER: Temperated the second of CIBP. ND OH. SWI. RD OH.	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-appropriate to CD-appropriate to CD-appropri	g estimated date osed completion RIH w/10K G" 13.5# are. RD any pit or below- proved plan 06 (432) 683-7063
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name J. L. Farrell, For State Use Only	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the work. Tag @ 12,460'. Pool RIH w/3.75" GR and JB to 1: '. POOH. Left 30' cmt on the work of the pump truck. Test casing 5. This Approval of Abandonment Examples above is true and complete to the best of relosed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and	HER: Temperated the second of CIBP. ND OH. SWI. RD OH.	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-appropriate to CD-appropriate to CD-appropri	g estimated date psed completion RIH w/10K 2" 13.5# are. RD any pit or below- proved plan
OTHER: 13. Describe proposed or compostarting any proposed work or recompletion. 3/16/06 MIRU E/L. ND wellhead a CIBP and set @ 12,510'. Loaded csg w/15 bbls, 4% 3/28/06 MIRU slickline. RIH w/1 5/15/06 ND WH. NU BOP. MIRU E/L. CIBP. Set CIBP @ 12,440 6/8/06 Bled down csg. MIRU Key Key. Chart attached I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name J. L. Farrell, For State Use Only	oleted operations. (Clearly state all pertinork). SEE RULE 1103. For Multiple Cond 1 jt tbg. NU BOP RIH w., KCl. Dump 35' cmt on top of the work. Tag @ 12,460'. Pool RIH w/3.75" GR and JB to 1: '. POOH. Left 30' cmt on the work of the pump truck. Test casing 5. This Approval of Abandonment Examples above is true and complete to the best of relosed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and complete to the best of the closed according to NMOCD guidelines Agriculture and	HER: Temperated the second of CIBP. ND OH. SWI. RD OH.	orarily Abandon ve pertinent dates, including a wellbore diagram of proposed JB to 12,535'. R BOP. NU wellhead. slickline H. PU and RIH w/4 % RD E/L. 5 min. Rlse pressured belief. I further certify that an (attached) alternative OCD-ap DATE 6/12/0 com Telephone No.	g estimated date osed completion RIH w/10K G" 13.5# any pit or below- proved plan 06 (432) 683-7063

