

+Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C 103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

P.O. Drawer DD, Artesia, NM 88210

DISTRICT II
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-08827
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	State 'A' A/C 2
8. Well No.	21
9. Pool name or Wildcat	Eunice: Seven Rivers-Queen, South (24130)
10. Elevaon (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> OTHER	2. Name of Operator Raptor Resources Inc
3. Address of Operator 901 Rio Grande, Austin, Tx 78701	4. Well Location Unit Letter K 1980 Feet From The South Line and 2316 Feet From The West Line Section 7 Township 22S Range 36E NMPM Lea County


11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/18/03 RU Start Well Service. Set CIBP @ 3150', GIH W/ dump bailer & dumped 5 sks cmt on top of CIBP, POOH. Load hole W/ gelled 10# brine, POOH. Perf 5 1/2" csg @ 1650'. GIH W/ tby & pkr, squeeze perf @ 1650' W/ 35 sks cmt, POOH W/ tbg & pkr. GIH and tagged plug @ 1575', Perf 5 1/2" csg @ 350'. GIH W/ tbg pumped 100 sks cmt & curculate to surface, POOH. RD Start Well Service.

7/8/03 Weld on P&A marker, cleaned location and notified OCD for final inspection.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



12. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE Agent For Raptor Resources DATE 7/28/03

TYPE OR PRINT NAME Bill R. Keathly TELEPHONE NO. 915-697-1609

(this space for State Use)

APPROVED BY Hayward Wink TITLE OC FIELD REPRESENTATIVE 1/STAFF MANAGER DATE AUG 05 2003

CONITIONS OF APPROVAL, IF ANY: