Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C 102
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Form C-103  Revised March 25, 1999
District [[		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION	30-025-35981 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	OTD A CONT.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505	。 <b>"你你我我你你</b> 你你,你你你你你你你你你	distribution of the state of th
SUNDRY NOTICE	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	2005 Name of Ont Agreement Name:
I. Type of Well: Oil Well ☐ Gas Well 図	Other	Markham 33
2. Name of Operator		8. Well No.
Chesapeake Operating,  3. Address of Operator	Inc.	001
P.O. Box 18496, OKlaho	na City OF 7215/ 0/06	9. Pool name or Wildcat
4. Well Location	ud 011y; 0K /3134-0496	Morton Mississippian
Unit Letter L :  Section 33	1650 feet from the South line and 660  Township 14S Range 35E  10. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM - Country
	GR: 4019	1. 是含字是"多"的,如果这是"是",是"是"的是"是"的是是"是"的"是"。
11. Check A	ppropriate Box to Indicate Nature of Notice,	Report or Other Data
NO HOE OF IN	ENTION TO: SUB!	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON   REMEDIAL WORK	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS   COMMENCE DRI	LLING OPNS. PLUG AND
PULL OR ALTER CASING	MULTIPLE CASING TEST AN CEMENT JOB	ABANDONMENT
OTHER:	OTHER: Perf;	Acidize Austin Lime
recompilation.  06/20/03 RU Schlumber w/guns, FL @surface 06/23/03 RU Cudd pur tbg @2 BPM @900#, d: 13,449', ND BOP, NU v @3 BPM @6500#, 06/24/03 Acidize Aust 06/25/03 finish batt sales @1:30 p.m. on	operations. (Clearly state all pertinent details, and give RULE 1103. For Multiple Completions: Attach well ager, RIH w/perf gun to perf Austin Line RD Schlumberger aping Services, pull 1 jt tbg, pump 50 asplace w/53 bbls 2%, pull 4 jts tbg, wellhead tree, start breakdown w/2% Ko ain Lime perfs 13541-561' w/7300 gal 1 arry & flowline, turn thru production 6/25/03 to Agave, leave flow hand on attion to perforate Brunson Sands 12998	ime 1354,-561' w/4 spf, POOH  00 gals 15% NE-FE acid down reverse acid up in tbg, set pkr CL, pump acid into formation  15% NE-FE acid equipment, had first gas location to monitor weld
hereby certify that the information al-	ove is true and complete to the best of my knowledge	
IGNATURE Barbara J.	TITLE Regulatory Ana	
ype or print name Barbara J. B		DINI
This space for State use)		Telephone No. (405) 848-8000
PPPROVED BY Jacque onditions of approval, if any:	). W. TITLE FIELD REPRESENTATIV	DATEAUC
Lk. a . mr. rr mr. h.	•	