Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	N <u>30-025-37698</u> 5. Indicate Type of Lease
District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 11
2. Name of Operator	9. OGRID Number
Marathon Oil Company	1402122
3. Address of Operator P.O. Box 3487 Houston, TX 77253-3487	10. Pool name or Wildcat $3$ Paddocko (49210)
4. Well Location	
Unit Letter	and 2135 g feet from the East line
Section 29 Township 21-S Range 3	7-E NMPNE County Lea
11. Elevation (Show whether DR, RKB, RT,	$\overline{GR, etc.}$ $Q_{c}$ $Q_{c}$
Bit or Below-grade Tank Application or Closure	
Bit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:	-
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	SUBSEQUENT REPORT OF: VORK
	VORK  ALTERING CASING    DRILLING OPNS.  PLUG AND
	VORK     ALTERING CASING       DRILLING OPNS.     PLUG AND       ABANDONMENT
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE       CASING TES	VORK     ALTERING CASING       DRILLING OPNS.     PLUG AND       ABANDONMENT
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TES CEMENT JO	WORK       ALTERING CASING         E DRILLING OPNS.       PLUG AND         ST AND       ABANDONMENT         B       Image: Comparison of the second sec
<ul> <li>PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CE</li> <li>PULL OR ALTER CASING CHANGE PLANS COMMENCE</li> <li>PULL OR ALTER CASING MULTIPLE COMPLETION</li> <li>OTHER:</li> <li>OTHER:</li> <li>OTHER:</li> <li>OTHER:</li> <li>Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.</li> <li>Marathon 0il Company has completed operations to drill, set, ar Turner No. 11</li> <li>O5/21/2006 Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosity sweep, short trip to 80', pump high viscosity 1245.</li> <li>1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats holdition</li> </ul>	WORK       ALTERING CASING         IDRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       ABANDONMENT         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         and test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ty sweep. P00H w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @ 6.36 gal/sk. Drop plug displaced w/ 75 ng. Pick up BHA RIH t/ tag float collar.
<ul> <li>PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CENTREPORARILY ABANDON CHANGE PLANS COMMENCE</li> <li>PULL OR ALTER CASING MULTIPLE CASING CEMENT JO</li> <li>OTHER: OTHER: OTHER: OTHER:</li> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.</li> <li>Marathon 0il Company has completed operations to drill, set, ar Turner No. 11</li> <li>05/21/2006 Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosity sweep, short trip to 80', pump high viscosity sweep, short trip to 80', pump high viscosity 1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats hold wait on cement 9 1/2 hrs. Test casing to 1000 psi and held for Thereby certify that the information above is true and complete to the best of my km</li> </ul>	WORK       ALTERING CASING         IDRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       B         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         and test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ty sweep. P00H w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @         6.36 gal/sk. Drop plug displaced w/ 75         ng. Pick up BHA RIH t/ tag float collar.         30 minutes. No bleed off.
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL W         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE       CASING TES         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.         Marathon 0il Company has completed operations to drill, set, ar Turner No. 11       05/21/2006 Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosity 05/23/2006 RIH w/ 29 jts 8 5/8",24#, J-55, ST&C casing to 1245' 1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats hold wait on cement 9 1/2 hrs. Test casing to 1000 psi and held for         I hereby certify that the information above is true and complete to the best of my km grade tank has been/will be constructed or closed according to NMOCD guidelines	WORK       ALTERING CASING         DRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       B         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         ad test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ity sweep. POOH w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @         6.36 gal/sk. Drop plug displaced w/ 75         ng. Pick up BHA RIH t/ tag float collar.         30 minutes. No bleed off.         Dwledge and belief. I further certify that any pit or below-         permit or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL W         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE       CASING TES         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.         Marathon 0il Company has completed operations to drill, set, ar Turner No. 11       05/21/2006 Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosity 05/23/2006 RIH w/ 29 jts 8 5/8",24#, J-55, ST&C casing to 1245' 1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats hold wait on cement 9 1/2 hrs. Test casing to 1000 psi and held for         I hereby certify that the information above is true and complete to the best of my km grade tank has been/will be constructed or closed according to NMOCD guidelines	WORK       ALTERING CASING         IDRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       ABANDONMENT         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         and test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ity sweep. POOH w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @         6.36 gal/sk. Drop plug displaced w/ 75         ng. Pick up BHA RIH t/ tag float collar.         30 minutes. No bleed off.         owledge and belief. I further certify that any pit or below-         permitor an (attached) alternative OCD-approved plan         tory Compliance Rep
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TES CEMENT JO         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.       Marathon 0il Company has completed operations to drill, set, ar Turner No. 11         05/21/2006       Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosi 05/23/2006 RIH w/ 29 jts 8 5/8",24#, J-55, ST&C casing to 1245' 1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats hold wait on cement 9 1/2 hrs. Test casing to 1000 psi and held for         Thereby certify that the information above is true and complete to the best of my km grade tank has been/will be constructed or closed according to NMOCD guidelines, agenera         SIGNATURE       Casher & Multipe         SIGNATURE       Casher & E. Kendrix	WORK       ALTERING CASING         DRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       B         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         ad test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ty sweep. POOH w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @         6.36 gal/sk. Drop plug displaced w/ 75         ng. Pick up BHA RIH t/ tag float collar.         30 minutes. No bleed off.         owledge and belief. I further certify that any pit or below-         permitor an (attached) alternative OCD-approved plan         tory Compliance Rep
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TES CEMENT JO         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.       Marathon 0il Company has completed operations to drill, set, ar Turner No. 11         05/21/2006       Drill 12 1/4" open hole f/ 52' to 312'. 05/22/2006 pump high viscosity sweep, short trip to 80', pump high viscosi 05/23/2006 RIH w/ 29 jts 8 5/8",24#, J-55, ST&C casing to 1245' 1243.82. Pumped 800 sks Premium Plus, 14.8 Density, 1.35 Yield, bbls fresh water. Bump plug w/ 980 psi. Release w/ floats hold wait on cement 9 1/2 hrs. Test casing to 1000 psi and held for         Thereby certify that the information above is true and complete to the best of my km grade tank has been/will be constructed or closed according to NMOCD guidelines, agenera         SIGNATURE       Casher & Multipe         SIGNATURE       Casher & E. Kendrix	WORK       ALTERING CASING         IDRILLING OPNS.       PLUG AND ABANDONMENT         ST AND       ABANDONMENT         and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion         and test the surface casing on the William         Drill 2 1/4" open hole f/ 312' to 1275'         ity sweep. POOH w/ dp, collars, & bit         . Top of FC @ 1199.82, top of shoe @         6.36 gal/sk. Drop plug displaced w/ 75         ng. Pick up BHA RIH t/ tag float collar.         30 minutes. No bleed off.         owledge and belief. I further certify that any pit or below-         permitor an (attached) alternative OCD-approved plan         tory Compliance Rep

•