State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

	OIL CONSERVATION DIVISIO	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505	WELL API NO. 30-025-28885
DISTRICT II	Salita Fe, INIVI 87303	5. Indicate Type of Lease
811 S. 1st Street, Artesia, NM 88210		FED STATE FEE X
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NO	TICES AND REPORTS ON WELLS	
	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
OIFFERENT RESE	ERVOIR. USE "APPLICATION FOR PERMIT"	
<u> </u>	4 C-101 FOR SUCH PROPOSALS.)	NORTH HOBBS (G/SA) UNIT
Type of Well: Oil Well	Gas Well Other INJECTOR	Section 29
2. Name of Operator	Gas Well Other INJECTOR	8. Well No. 442
Occidental Permian Ltd		0. Wen 110. 442
3. Address of Operator		9. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/397-8200	
4. Well Location		
Unit Letter P : 1230	Feet From The SOUTH Line and 220	Feet From The EAST Line
Section 29	Township 18S Range	38E NMPM LEA County
566.63 23	10. Elevation (Show whether DF, RKB, RT GR, etc.)	36E RUITM EEA County
	3643 GL	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG & ABANDONMENT
		<u> </u>
PULL OR ALTER CASING	L CASING TEST AND C	EMENT JOB
PULL OR ALTER CASING OTHER:	CASING TEST AND CI	
OTHER:	OTHER: Stimulate	San Andres perfs X
OTHER:	I	San Andres perfs X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103.	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, incli	San Andres perfs X
OTHER: 12. Describe Proposed or Completed Operati SEE RULE 1103. 1. RUPU. Pull injection equipment.	ons (Clearly state all pertinent details, and give pertinent dates, incli	San Andres perfs X uding estimated date of starting any proposed work)
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, incli 1, and 4189-4211 w/550 g 15% NEFE HCL acid.	San Andres perfs X uding estimated date of starting any proposed work)
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, inclining and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg.	San Andres perfs X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, inclining and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg.	San Andres perfs X uding estimated date of starting any proposed work)
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, inclination). 1, and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'.	San Andres perfs X uding estimated date of starting any proposed work)
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs X uding estimated date of starting any proposed work)
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39. 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min and	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs X uding estimated date of starting any proposed work) San Andres perfs X X X X X X X X X X X X X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min and 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs X uding estimated date of starting any proposed work)
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min and 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs Walding estimated date of starting any proposed work) San Andres perfs X X X X X X X X X X X X X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min and 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs X uding estimated date of starting any proposed work) San Andres perfs X X X X X X X X X X X X X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, inclining 1, and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03.	San Andres perfs X uding estimated date of starting any proposed work) San Andres perfs X X X X X X X X X X X X X
OTHER: 12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. action.	San Andres perfs X uding estimated date of starting any proposed work) San Andres perfs X X X X X X X X X X X X X
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003 I hereby certify that the information above is SIGNATURE	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03.	San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs X San Andres perfs Adding estimated date of starting any proposed work)
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39. 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/200 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003 I hereby certify that the information above is SIGNATURE TYPE OR PRINT NAME Robert Gilb	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03.	San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs X San Andres perfs Adding estimated date of starting any proposed work)
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003 I hereby certify that the information above is SIGNATURE	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, included). 1, and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03. true and complete to the best of my knowledge and belief. TITLE SR. ENGR.	San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) Adding estimated date of starting any proposed work)
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39. 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min an 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/200 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003 I hereby certify that the information above is SIGNATURE TYPE OR PRINT NAME Robert Gilb	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, including and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03.	San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) San Andres perfs Adding estimated date of starting any proposed work) Adding estimated date of starting any proposed work)
12. Describe Proposed or Completed Operation SEE RULE 1103. 1. RUPU. Pull injection equipment. 2. Stimulate perfs 4147-54, 4164-7 3. RIH w/7" G-6 PC pkr on 119 jts 4. Set pkr @3950'. Bot of tbg @39 5. Circ csg w/pkr fluid. 6. Test csg to 550 psi for 30 min and 7. NU wellhead. RDPU. Clean Local Return to injection 07/18/20 Rig Up Date: 07/11/2003 Rig Up Date: 07/11/2003 Rig Down date: 07/17/2003 I hereby certify that the information above is SIGNATURE TYPE OR PRINT NAME Robert Gilbs (This space for State Use)	OTHER: Stimulate ons (Clearly state all pertinent details, and give pertinent dates, included). 1, and 4189-4211 w/550 g 15% NEFE HCL acid. 3.5" Duoline tbg. 50'. d chart for the NMOCD. ation. 03. true and complete to the best of my knowledge and belief. TITLE SR. ENGR.	San Andres perfs Adding estimated date of starting any proposed work) A TECH DATE DATE DATE 08/03/2003 TELEPHONE NO. 505/397-8206

