Submit 3 Copies To Appropriate District	State of New Mex	kico	Form C-103
Office Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240	3		WELL API NO.
District II ON CONCERNATION DIVISION		30-025-27493	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Die Denros Dd. Arten NM 97410		STATE FEE X	
District IV	Santa Fe, NM 87	วบว	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		·	
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPZIGN TRONFORDER PROPOSALS.") FOR SUCH		Byars #1	
PROPOSALS.)		8. Well Number 1	
1. Type of Well: Oil Well X Gas Well Other Re-entry		O CORIDAL	
2. Name of Operator Plotinum Exploration Inc.		9. OGRID Number 227103	
Platinum Exploration Inc		10. Pool name or Wildcat	
3. Address of Operator 550 W. Texas, Suite 500 Midland, TX 79701 432-687-1664		Gladiola; Devonian (27740)	
	17 /9/01 432-08/-1004		Gladiola, Devolitali (27/40)
4. Well Location			
Unit Letter A : 660'	feet from the North line	and <u>660</u>	feet from theEastline
Section 8	Township 12S Ra	nge 38E	NMPM Lea County
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	
	3862'	GR	
Pit or Below-grade Tank Application 🔲 o	r Closure		189 10 11 15 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16
Pit typeDepth to Groundw	aterDistance from nearest fresh wa	nter well Dista	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls: Cor	ance from nearest surface water
12 Check Appropriate Roy to Indicate Nature of Notice Report or Other Data			
	Appropriate Box to Indicate Na		Report or Other Date
12. Check A		ature of Notice,	Report or Other Data
12. Check A	TENTION TO:	ature of Notice, SUBS	Report or Other Data (SEQUENT REPORT, OF:
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON	ature of Notice, SUBS REMEDIAL WORK	Report of Other Data SEQUENT REPORT OF: ALTERING CASING
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	TENTION TO: PLUG AND ABANDON CHANGE PLANS	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIE	Report or Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS. PAND A
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON	ature of Notice, SUBS REMEDIAL WORK	Report of Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS PAND A
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	Report of Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF THE PARTY A DOB JOB LING OPNS D PARTY A DOB
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	Report of Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF THE PARTY A JOB Pump Report of Other Data Data Pump Report of Other Data Pump Report of Other Data Pump Report of Other Data Report of Other Da
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detection of the control of the co	SUBSTANDED TO SU	Report of Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF DATE OF DEPARTMENT A DEPARTMENT OF
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF DATE
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE: LING OPNS. DEPOSE DATE: JOB PARTY A give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed woor recompletion. MIRU. Dr. Drill out cmt. plugs to TD (TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE: LING OPNS. DEPOSED A
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE: LING OPNS. DEPOSE DATE: JOB PARTY A give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE: LING OPNS. DEPOSED A
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 20 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr GO, 3527 BW, and 12 MCF est. in 24	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF DATE OF DEPARTMENT A DEPARTMENT OF DATE OF D
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr 30, 3527 BW, and 12 MCF est. in 24 above is true and complete to the beserved.	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF THE PORT OF
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr 30, 3527 BW, and 12 MCF est. in 24 above is true and complete to the beserved.	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE: LING OPNS. DEPOSED A
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 20 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr BO, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines.	SUBSTANDED AND TO SUBSTANDED A	Report or Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS. PARTY A pump give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt and test csg. to 1000 psi. tested good. Acid of sub 4-13-06 pump. RDMOPU. Potential and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr 30, 3527 BW, and 12 MCF est. in 24 above is true and complete to the beserved.	SUBSTANDED TO SU	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE OF THE PORT OF
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr 10, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000 hrs. st of my knowledge l, a general permit central complete complet	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE DATE LING OPNS. DATE PARTY A DUMP give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt and test csg. to 1000 psi. tested good. Acid D sub 4-13-06 pump. RDMOPU. Potential and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE DATE 5/04/06
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 20 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr BO, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines.	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000 hrs. st of my knowledge l, a general permit central complete complet	Report or Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS. PARTY A pump give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt and test csg. to 1000 psi. tested good. Acid of sub 4-13-06 pump. RDMOPU. Potential and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 20 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr BO, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines TITLE E-mail address: Ras @t3	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000 hrs. st of my knowledge l, a general permit ENG.	Report or Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS. PARTY A give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt and test csg. to 1000 psi. tested good. Acid of sub 4-13-06 pump. RDMOPU. Potential and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE 5/04/06 Telephone No. 432-687-1664
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Greg Rasmussen For State Use Only	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL letted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr 100, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines TITLE E-mail address: Ras @t3	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000 hrs. st of my knowledge l, a general permit central complete complet	Report or Other Data SEQUENT REPORT OF: ALTERING CASING DATE DATE LING OPNS DE PART A DESCRIPTION A DESCRIPTION DESCRIPTION DE PART A DESCRIPTION DE PART A DESCRIPTION DE PART DE
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. MIRU. Dr Drill out cmt. plugs to TD (with 2500 gal. acid 15%NE test 4-16-06, pumped 129 E I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL leted operations. (Clearly state all pork). SEE RULE 1103. For Multiple ill out cmt. plugs to 4600'. Tie back 20 11,991'. Reperf Dev. 11981' to 11 FE HCL. ISIP Vac. POOH with pkr BO, 3527 BW, and 12 MCF est. in 24 above is true and complete to the best closed according to NMOCD guidelines TITLE E-mail address: Ras @t3	SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: run ertinent details, and e Completions: Att 5 ½" 17# K55 csg. 1985'. RIH with pkr RIH with TD3000 hrs. st of my knowledge l, a general permit ENG.	Report or Other Data SEQUENT REPORT OF: ALTERING CASING LING OPNS. PARTY A give pertinent dates, including estimated date ach wellbore diagram of proposed completion to surface. Circ to surface w/ 105 sx. cmt and test csg. to 1000 psi. tested good. Acid of sub 4-13-06 pump. RDMOPU. Potential and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE 5/04/06 Telephone No. 432-687-1664