Office		tate of New Mexico	Form C-103
District I		inerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, N District II			WELL API NO.
1301 W. Grand Ave., Artesia,	110100210	<b>ISERVATION DIVISION</b>	30-025-03457
District III 1000 Rio Brazos Rd., Aztec, N	JM 97410	) South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
District IV	Sa	anta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa 1 87505			NM B-1399
(DO NOT USE THIS FORM I	DRY NOTICES AND REPO FOR PROPOSALS TO DRILL OR USE "APPLICATION FOR PERMI	TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name State A
1. Type of Well: Oil W	rell 🔲 Gas Well 🛛 Of	ther	8. Well Number 3
2. Name of Operator	Citation Oil & Gas Corr	n	9. OGRID Number 004537 /
3. Address of Operator	Chanon On & Oas Cor	ų	10. Pool name or Wildcat
	P O Box 690688, Houst	ton, Texas 77269	Eumont Yates Seven Rivers Queen
4. Well Location			
		e <u>North</u> line and <u>2515</u> fe	et from the <u>East</u> line
Section	12 Township 21S		NMPM Lea County
	11. Elevation (S	Show whether DR, RKB, RT, GR, etc	
	3585' DF	· · · · · · · · · · · · · · · · · · ·	
it or Below-grade Tank App	lication  or Closure		
it typeDepth	to GroundwaterDistance	from nearest fresh water well Dis	stance from nearest surface water
it Liner Thickness:	mil Below-Grade Ta		Construction Material
TEMPORARILY ABAND	ON CHANGE PLAN	IS COMMENCE DR	RK     ALTERING CASING       RILLING OPNS.     P AND A
TEMPORARILY ABAND PULL OR ALTER CASIN <u>OTHER: Recomplete to</u> 13. Describe propose	ON CHANGE PLAN IG MULTIPLE CON Yates Seven Rivers ed or completed operations.	IS COMMENCE DR MPL CASING/CEMEN OTHER: (Clearly state all pertinent details, ar	RK     ALTERING CASING       RILLING OPNS.     P AND A       IT JOB     IT
of starting any pr or recompletion.	ON CHANGE PLAN IG MULTIPLE CON Yates Seven Rivers ed or completed operations. ( oposed work). SEE RULE 1	IS COMMENCE DR MPL CASING/CEMEN OTHER: (Clearly state all pertinent details, ar 1103. For Multiple Completions: A	RK     ALTERING CASING       RILLING OPNS.     P AND A       IT JOB     IT
<ul> <li>TEMPORARILY ABANDA PULL OR ALTER CASIN</li> <li><u>OTHER: Recomplete to</u> 13. Describe propose of starting any pr or recompletion.</li> <li>Stattion Oil &amp; Gas Corp. p 5-04.</li> </ul>	ON CHANGE PLAN IG MULTIPLE COM Yates Seven Rivers ed or completed operations. ( oposed work). SEE RULE 1 proposes to recomplete this w	IS COMMENCE DR MPL CASING/CEMEN OTHER: (Clearly state all pertinent details, ar 1103. For Multiple Completions: A well to the Yates Seven Rivers per at	ALTERING CASING ALLERING CASING ALLERING OPNS. PAND A ALTERING CASING ALLENG OPNS. PAND A ALLENG OPNS. PAND A ALLENG OPNS. PAND A ALLENG PORTECTION AND A ALLENG PORTECTION AND
TEMPORARILY ABANDO PULL OR ALTER CASIN OTHER: Recomplete to 13. Describe propose of starting any pr or recompletion. itation Oil & Gas Corp. p 5-04.	ON CHANGE PLAN IG MULTIPLE COM Yates Seven Rivers ed or completed operations. ( oposed work). SEE RULE 1 proposes to recomplete this w	COMMENCE DR MPL CASING/CEMEN OTHER: (Clearly state all pertinent details, ar 1103. For Multiple Completions: A well to the Yates Seven Rivers per at	ALTERING CASING ALLERING CASING ALLERING OPNS. PANDA
<ul> <li>TEMPORARILY ABANDOR</li> <li>PULL OR ALTER CASIN</li> <li>OTHER: Recomplete to</li> <li>13. Describe propose of starting any pror recompletion.</li> <li>itation Oil &amp; Gas Corp. p</li> <li>5-04.</li> </ul>	ON CHANGE PLAN IG MULTIPLE COM Yates Seven Rivers ed or completed operations. ( oposed work). SEE RULE 1 proposes to recomplete this w	COMMENCE DR MPL CASING/CEMEN OTHER: (Clearly state all pertinent details, ar 1103. For Multiple Completions: A well to the Yates Seven Rivers per at	ALTERING CASING ALLERING CASING ALLERING OPNS. PANDA
TEMPORARILY ABANDA PULL OR ALTER CASIN OTHER: Recomplete to 13. Describe propose of starting any pr or recompletion. itation Oil & Gas Corp. p 5-04. tereby certify that the infade tank has been/will be con GNATURE Solo ype or print name	ON CHANGE PLAN IG MULTIPLE COM Yates Seven Rivers ed or completed operations. ( oposed work). SEE RULE 1 proposes to recomplete this w	IS       COMMENCE DR         MPL       CASING/CEMEN         MPL       OTHER:         (Clearly state all pertinent details, ar         1103. For Multiple Completions: A         well to the Yates Seven Rivers per at         well to the Yates Seven Rivers per at         complete to the best of my knowledg         MOCD guidelines ], a general permit         TITLE       Permitting Manage	RK       ALTERING CASING         RILLING OPNS.       P AND A         IT JOB       Image: Completion of the proposed completion of the proposed completion of proposed completion of the procedures under NMOCD order SD-         It ached proc
TEMPORARILY ABANDA PULL OR ALTER CASIN OTHER: Recomplete to 13. Describe propose of starting any pr or recompletion. itation Oil & Gas Corp. p 5-04. tereby certify that the infade tank has been/will be con GNATURE	ON CHANGE PLAN IG MULTIPLE COM Yates Seven Rivers ad or completed operations. ( roposed work). SEE RULE 1 proposes to recomplete this w proposes to recomplete this w formation above is true and c istructed or closed according to N NUL Ward	IS       COMMENCE DR         MPL       CASING/CEMEN         Image: Complete to the Vates Seven Rivers per at         complete to the best of my knowledg         MOCD guidelines [], a general permit []         TITLE       Permitting Manage         E-mail address:       sward@cog	RK       ALTERING CASING         RILLING OPNS.       P AND A         IT JOB       Image: Completion of the proposed completion of the proposed completion of the procedures under NMOCD order SD-         It ached proter procedures under NMO

3

### WORKOVER PROCEDURE

PROJECT:	State A #3 – OAP and Frac		
DRILLED &	COMPLETED: <u>5/40</u> LAST WO:	10/85: Acidized	
LOCATION:	2,310' FNL; 2,515' FEL; Sec 12; T-21-	S and R-35-E	
FIELD: <u> </u>	Eumont	COUNTY: Lea	STATE:
TD: <u>3,880'</u>	PBTD: DATU	JM: <u>3,581' DF</u> K	CB: <u>10'</u>

#### **CASING AND LINER RECORD**

ſ	SIZE	WEIGHT	DEPTH	CEMENT	HOLE	TOC	REMARKS
ľ	7 5/8"	26 ppf	1,576'	600 sxs	9 1/2"	Surf	Cmt circ'd
	4 1/2"	9.5 ppf	3,780'	150 sxs	6 3/4"	3,000"	TOC calc'd w/ 75% xs

Producing Formation: Queen Perfs: OH 3,780' - 3,880'

Rods: 1 <sup>1</sup>/<sub>4</sub>" x 16' PR w/ 1 <sup>1</sup>/<sub>2</sub>" x 10' PRL; (2') <sup>3</sup>/<sub>4</sub>" Grade KD subs; (149) <sup>3</sup>/<sub>4</sub>" Grade KD rods; 2" x 1 1/2" x 12' pump

Tubing: (1) 2 3/8" x 6' tb sub; (59 jnts) 2 3/8" 4.7 ppf J-55 eue 8rd; (62 jnts) 2 3/8" 4.7# J-55 10v; (1) 2 3/8" SN; (1) 2 3/8" perfd sub; (1 jnt) 2 3/8" BPMA

Note:

#### PROCEDURE

- > Notify NMOCD of planned work.
- > Use 2% KCl water for all water placed in wellbore.
- > RU gas buster pit and flowback manifold using secure steel lines w/ targeted connections.
- > Need air unit to clean out after frac flow back.
- > Locate and rack 3800' 2 7/8" 6.5# P-110 WS.
- > Locate and rack 3,800' 2 3/8" 4.7# L-80 WS.
- Contact Reef Chemical (Gary Hyer 432-570-7038) to line up 750 gal Gas Plus (375 gal per stage).
- 1. MIRU PU. Kill w/ 2% KCL water if necessary.
- 2. ND WH. NU BOP.
- 3. RIH w/ 3 7/8" MT skirted bit and 2 3/8" SN on 2 3/8" 4.7# L-80 WS to 3,770' (OH @ 3,780'). Tally in hole. POH w/bit.
- 4. RIH w/ 2 3/8" WS and set CIBP @ +/- 3,750'. POH 2 3/8" WS (Note: do not use WL set CIBP).
- 5. RIH and dump bail 2 1/2 sx cmt on CIBP @ +/- 3,750' (need 35' of cement on CIBP).
- 6. Load hole w/ 2% KCL and PT to 250 psi. (NOTIFY Midland of results.)

- 7. RIH w/ GR/CBL/CCL. Run f/ PBTD (3715') to TOC or minimum run. POH w/ logging tools. Evaluate log for cmt top.
- RU WL w/ full lubricator. RIH w/ 3 1/8" csg gun. Correlate to Welex Radioactive Log (GR / Neutron log) dated 10/7/57. Perf (stage 1) Seven Rivers w/ 1 SPF Select Fire (0.38" holes) as recommended by Reservoir group.
- 9. POOH w/ Csg guns.
- 10. RU hydrotesters and RIH w/ PPI Tool, 2 3/8" SN on 2 3/8" WS to bottom perf of 1st stage hydrotesting 2 3/8" L-80 WS to 7,000 psi (62% of new rating). Straddle target perfs and set PPI tool. Break down w/ 15% AS HCL acid (Max treating pressure = 6,000 psi). Rlse PPI tool and proceed to the next group of target perfs repeating the procedure until all Seven Rivers perfs are broken down / treated. (Note- Record Max and Min pressures, Average injection rate, ISIP and signs of communication for each treatment). POOH w/ PPI tool on 2 3/8" WS.
- 11. RU hydrotesters. RIH w/ Arrowset 1X Frac Pkr w/ Dual Direction flapper valves, P-110 Inner Flow Tube (2.0"ID) and T-2 On/Off tool and 2 7/8" SN on 2 7/8" 6.5 ppf P-110 WS. Test tbg to 10,000 psi BS (69% of new rating). Set PKR +/- 50' above top perf.
- 12. RU acid/frac company. Load csg w/ 2% KCl. Hold 500 psi on csg w/ pop off set at +/- 750 psi. Monitor csg throughout acid and frac job.
- Pump (375 Gallons) Reef GAS PLUS as per recommendation. Frac Seven Rivers perfs as per service company recommendation using CO<sub>2</sub>. Tag w/ IR-192 @ 0.5MC/1M# sand (74 day half-life). Record rates, max and min pressures and SIP's. (NOTE: Max pressure = 8,500 psi. All sand tagged w/ IR-192.)
- 14. RU gas buster pit and flowback manifold using secure steel lines w/ targeted connections. Connect steel lines to tubing via hose. Rlse On-Off Tool and sting +/- 10' out of packer. Check for backflow. Pump an tubing volume + 20 bbls of 2% KCL water using a pump truck down the back side, circulating out of the tubing to the steel lines, manifold and the gas buster pit (NOTE: Initial flowback will likely be hard due to CO2 bubble that will circulate off bottom).
- 15. POH w/ Inner Flow Tube and On-Off tool.
- 16. RU WL w/ full lubricator. Pressure csg to 500 psi w/ 2% KCL. RIH w/ 4" csg gun. Correlate to Gamma Ray Neutron log. Perf (stage 2) Yates w/ 1 SPF Select Fire (0.38" holes) as recommended by the Reservoir group.
- 17. POH w/ csg guns.
- 18. RIH w/ PPI Tool, 2 3/8" SN on 2 3/8" WS to bottom perf of 2<sup>nd</sup> stage. Straddle target perfs and set PPI tool. Break down w/ 15% AS HCL acid (Max treating pressure = 6,000 psi). RIse PPI tool and proceed to the next group of target perfs repeating the procedure until all Yates perfs are broken down / treated. . (Note- Record Max and Min pressures, Average injection rate, ISIP and signs of communication for each treatment). POOH w/ PPI tool on 2 3/8" WS.
- 19. RIH w/ treating PKR, 2 7/8" SN AND X-Over on 2 7/8" P-110 WS and set PKR +/- 50' above top perf.
- 20. Load csg w/ 2% KCl. Hold 500 psi on csg w/ pop off set at +/- 750 psi. Monitor csg throughout acid and frac job.
- 21. Pump (375 Gallons) Reef GAS PLUS as per recommendation. Frac Yates as per service company recommendation using CO<sub>2</sub>. Tag w/ SC-46 @ 0.5MC/1M# sand (84 day half-life). Record rates, max and min pressures and SIP's. (NOTE: Max pressure = 8,500 psi. All sand tagged w/SC-46.)
- 22. Flow well back to gas buster pit using flow-back manifold w/ targeted connections and secure steel lines.
- 23. Kill well w/ 2% KCL if required. Rlse Pkr. POH w/ 2 7/8" WS. LD Pkr and 2 7/8" P-110 WS.

2

.

- 24. RIH w/ frac Pkr retrieving head and 2 3/8" SN on 2 3/8" WS to frac Pkr. RU foam air unit and clean out sand to Pkr. RD foam air unit. Latch onto Pkr and release. POH w/ frac Pkr and 2 3/8" WS.
- 25. RIH w/ notched collar, 2 3/8" SN on 2 3/8" WS. Tag for fill. RU foam air unit and clean out frac sand to PBTD. CHC. RD foam air unit. POH w/ bit and LD 2 3/8" WS.
- 26. RU WL w/ Lubricator. Run After Frac Spectra (dual isotope) GR Log f/ 2,700' PBTD. POH and RD WL.
- 27. Run 2 3/8" 4.7 ppf J-55 eue 8rd production tbg string as follows:

QTY	ITEM	LENGTH	DEPTH
TUBING	KB	10'	10'
114	Jts 2 3/8" 4.7# J-55 eue 8rd tbg	3556'	3,566'
1	Jt 2 3/8" 4.7# J-55 eue 8rd IPC tbg	31'	3,597'
1	2 3/8" SN	1'	3,598'
1	2 3/8"x 4' TBG Sub	4'	3,602'
1	Cavins D2301G Desander	20'	3,622'
2	2 Jts 2 3/8" BPMA	62'	3,684'

- 28. RU Swab. Swab well until clean fluid is produced. RD Swab.
- 29. Run rod string as follows:

### RODS

1	1 1/4" x 16' PR w/ 1 1/2" x 10' Liner	16'	16'
Set	3/4" KD Rod Subs w/ SM couplings	10' (+/-)	26'
144	3/4" KD Rods w/ SM couplings	3600'	3626'
1	3/4" KD Rod Sub w/ SM couplings	2'	3628'
1	2" x 1 1/4" x 12' RHBC Pump	12'	3640'

- 30. Load tbg w 2% KCl and pressure test pump. Space out and hang well on. Place pumping unit in 44" SL at +/- 7 SPM (Expected production rate +/- 49 BFPD @ 100% efficiency and 1 1/4" pump).
- 31. RD MO PU. Return well to production and place on test.

## CITATION OIL AND GAS CORPORATION CURRENT WELLBORE DIAGRAM AND INFORMATION



TD @ 3,880'

# CITATION OIL AND GAS CORPORATION PROPOSED WELLBORE DIAGRAM AND INFORMATION

