

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06661
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name ALVES
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat PENROSE SKELLY; GRAYBURG

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☒ Other

2. Name of Operator
LANEXCO, INC

3. Address of Operator
1105 WEST KANSAS, JAL, NM 88252

4. Well Location
Unit Letter H : 1980 feet from the NORTH line and 660 feet from the EAST line
Section 18 Township 21S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Smith & Marrs Casing Pullers is contracted to plug this well.

SEE ATTACHED

*See attached plugging procedures.

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles Mann TITLE Production Supt. DATE 8/2/06

Type or print name CHARLES MANN E-mail address: Telephone No. 505-395-305

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 09 2006
Conditions of approval, if any

Lanexco, Inc.
1105 West Kansas
Jal, New Mexico 88252
505/395-3056
Fax 505/395-3205

LANEXCO, INC.

PLUGGING PROCEDURE

ALVES #1
30-025-~~0661~~ / 06661
LEA COUNTY, NM

1. Move in and rig up plugging unit and equipment.

2. Go in hole and tag existing plug at 3725'.

3. Set CIPB at 3600' cap with 25 sxs.

4. Load hole with salt gel.

5. Set ^{100'} ~~50'~~ plug base of salt ~~2495/2405~~ 2510'-2410'

PERF + SQZ. 50' OUT IN F/.

6. Set 50' plug top of salt 1315/1365. 1390'-1290' WOC + TAG

7. Set shoe plug surface/350. SHOE ? 162' ? IF @ 162' PERF + @ 212' + CIRC.
TO SURF.

8. Set markers.

Alves No. 1

