Submit 3 Copies To Appropriate District Office State of New Mexico Office Submit 3 Copies To Appropriate District Minorals and Natural Resources	Form C-103 May 27, 2004
District I  1625 N. French Dr., Hobbs, NM 88240 District II  ONL GONGERN A TRONG DIVISION IN THE CONTROLLED TO THE CONTR	WELL API NO. 30-025-04036
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name NORTHWEST EUMONT UNIT
1. Type of Well: Oil Well	8. Well Number: 131
2. Name of Operator RHOMBUS OPERATING CO., LTD	9. OGRID Number: 019111
3. Address of Operator	10. Pool name or Wildcat: EUMONT
PO BOX 8316, MIDLAND, TX 79708-8316  4. Well Location	YATES
Unit Letter M : 990' feet from the SOUTH line and 330' feet	from the WEST line
Section 23 Township 19S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	i de la companya de l
Pit or Below-grade Tank Application or Closure	
	nce from nearest surface water
	estruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	_
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF:
TEMPORARILY ABANDON	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	JOB 🔲
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including entined date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attorner or recompletion.	ach wellbore diagram of proposed completion
Surface casing: 8 5/8", 24# @ 1420', cement circulated	$\mathcal{L}_{\mathcal{O}}}}}}}}}}$
Surface casing: 8 5/8", 24# @ 1420', cement circulated Production casing: 5½", 14# @ 3799', TOC @ 590' by TS	Roce TIFIET
Surface casing: 8 5/8", 24# @ 1420', cement circulated  Production casing: 5½", 14# @ 3799', TOC @ 590' by TS  OH 3799-4050'.  Tubing @ 3964', w/ rods & pump	್ಷ ೪ ೯ ೯ ೯
OH 3799-4050'. Tubing @ 3964', w/ rods & pump	ISERV D 24 F OF PL
OH 3799-4050'. Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum	ISERV D 24 F OF PL
OH 3799-4050'. Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)	OF PLUE CENT on top of CHECK CONTROL OF PLUE CENT OF CHECK CONTROL OF CHEC
OH 3799-4050'. Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)	OF PLUMENTION OF PLUMENT OF PLUMENT OF PLUMENT OF CHECK CHILD OF CHILD OF CHECK CHILD OF CHILD OF CHECK CHILD OF CHIL
OH 3799-4050'. Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½' csg from +/- 590'.	OF PLUMING PLU
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½" csg from +/- 590' So' IN+DOT OF STOB  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.	OF PLUMING PLU
1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg. 2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum 3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt) 4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt 5. Cut & pull 5½" csg from +/- 590' So' IN+ DOT OF 5TOB 6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.	OF PLUMING PLU
1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½' csg from +/- 590' So' IN + DOT OF STUB  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.	OF PLUMING PLU
1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½' csg from +/- 590' So' IN + DOT OF STUB  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.	OF PLUMING PLU
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½' csg from +/- 590'.  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.  8. Cut off wellhead & install dry hole marker. Cut off anchors & level location.  I hereby certify that the information above is true and complete to the best of my knowledge.	OF PLUMING OPERATIONS  AP 35 CIC emt on top of CONGING OPERATIONS  A 35 CIC emt on top of CONGING OPERATIONS  and belief. I further certify that any pit or below-
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½' csg from +/- 590' So' IN + DOT OF STOB  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.  8. Cut off wellhead & install dry hole marker. Cut off anchors & level location	OF PLUERY PRIOR TO THE WOC + TAG  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½'' csg from +/- 590'  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.  8. Cut off wellhead & install dry hole marker. Cut off anchors & level location.  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \( \D \), a general permit \( \D \)  SIGNATURE \( \D \) \( \D \) CIELINSKI. E mail address: rhombusen@cox methods.	OF PLUMS PRIOR TO THE STATIONS.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan .  DATE 9-39-06
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½'' csg from +/- 590'  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.  8. Cut off wellhead & install dry hole marker. Cut off anchors & level location.  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \( \D \), a general permit \( \D \)  SIGNATURE \( \D \) \( \D \) CIELINSKI. E mail address: rhombusen@cox methods.	OF PLUMS PRIOR TO THE STATIONS.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan .  DATE 9-39-06
OH 3799-4050'.  Tubing @ 3964', w/ rods & pump  1. MIRU. POH w/ rods & pump. NU BOP. POH w/ tbg.  2. RIH w/ tbg set CIBP to 3749'. Set CIBP & circ hole w/ plugging mud. Pum  3. POOH w/ tbg to 2800' & pump 25 sx CL C cmt (base of salt)  4. POOH w/ tbg to 1470' & pump 25 sx CL C cmt  5. Cut & pull 5½" csg from +/- 590'  6. POH w/ tbg to 400' and pump 40 sx Cl C cmt.  7. Pump 10 sx Cl C cmt 50' to surface.  8. Cut off wellhead & install dry hole marker. Cut off anchors & level location  I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \( \preceq\), a general permit \( \preceq\)  SIGNATURE \( \frac{\text{Jap.}}{\text{Jap.}} \)  TITLE \( \text{President of the G}\)	OF PLUGING OPERATION  AD 35 CI-C emt on top of CAGING OPERATION  AD 35 CI-C emt on top of CAGING OPERATION  A 35 CI-C emt on top of CAGING OPERATION  A 35 CI-C emt on top of CAGING OPERATION  A 35 CI-C emt on top of CAGING OPERATION  A 35 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 36 CI-C emt on top of CAGING OPERATION  A 37 CI-C emt on top of CAGING OPERATION  A 47 CAG