Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

| District Office | 6,, | | |
|--|---|--|--|
| DISTRICT I | OIL CONSERVAT | | |
| P.O. Box 1980, Hobbs NM 88241-1980 | 2040 Pacheco St. | | WELL API NO. 30 - 025 - 21216 |
| DISTRICT II P.O. Drawer DD, Artesia, NM 88210 | Santa Fe, NM 87505 | | 5. Indicate Type of Lease STATE X FEE |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | | | 6. State Oil & Gas Lease No. E-4199 |
| SUNDRY NOT | ICES AND REPORTS ON | WELLS | |
| | OPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR 101) FOR SUCH PROPOSALS.) | | 7. Lease Name or Unit Agreement Name MESA QUEEN UNIT |
| . Type of Well: OIL GAS WELL WELL WELL | OTHER | | |
| . Name of Operator ERIC OIL & GAS CORPORATION | | | 8. Well No. 24 |
| 3. Address of Operator .0. BOX 352 MIDLAND TX 79702 | 2 | | 9. Pool name or Wildcat |
| 1. Well Location Unit Letter E: 1650 | Feet From TheNORTH | Line and 66 | 60 Feet From The WEST Line |
| Section 20 | Township 16S | Range 32E | NMPM LEA County |
| | | nether DF, RKB, RT, GR, et | |
| 11. Check Ap NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON | Propriate Box to Indic ENTION TO: PLUG AND ABANDON CHANGE PLANS | | BSEQUENT REPORT OF: ALTERING CASING |
| NOTICE OF INT | ENTION TO: PLUG AND ABANDON | SUE REMEDIAL WORK | BSEQUENT REPORT OF: ALTERING CASING IG OPNS. PLUG AND ABANDONMENT |
| NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON JULL OR ALTER CASING THER: | PLUG AND ABANDON CHANGE PLANS Determination (Clearly state all pertinent TAG @ 913') S WOC & TAG @ 418 ACE Approved | REMEDIAL WORK COMMENCE DRILLING CASING TEST AND COTHER: t details, and give pertinent | ALTERING CASING ALTERING CASING IG OPNS. PLUG AND ABANDONMENT EMENT JOB It dates, including estimated date of starting any property Well Bore. |
| NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON JUL OR ALTER CASING THER: 12. Describe Proposed or Completed Opwork) SEE RULE 1103. 7-17-03 SPOT 25 SKS 3300 WOC & TASPOT 25 SKS 1300' WOC & 7-18-03 PERF @ 600 SQUEEZE 50 SKS SPOT 20 SKS 100' TO SURFACE CIRCULATE MUD | PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Decrations Clearly state all pertinent and a graph of the state all pertinent and a graph | REMEDIAL WORK COMMENCE DRILLING CASING TEST AND COTHER: t details, and give pertinent as to plugging of the ander bond is retained estoration is completed | ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT EMENT JOB The dates, including estimated date of starting any property Well Bore. until d. |