New Mexico Oll Conserv.	ation Division. D	ริสัตว์ทร์ ศ. 1	
1625 N. Fra	anch Drive		
m 3180-5 UNITED STATES Hobbs, NI		FORM APPROVED	
DEPARTMENT OF THE INTERIOR		FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007	
BUREAU OF LAND MANAGEMENT		5. Lease Serial No.	·······
SUNDRY NOTICES AND REPORTS ON		NMNM0145685	<u></u>
Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for such	re-enter an h proposals.	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on r	everse side.	7. If Unit or CA/Agreement, Name and/or N	 No.
i. Type of Well XOil Well Gas Well Other	· · · · · · · · · · · · · · · · · · ·	-	
		8. Well Name and No.	
2. Name of Operator XOG_OPERATING, LLC		HORTON FEDERAL 5 9. API Well No.	
Ba Address 3b. Phone No.	(include area code)	30-041-10127	
	3-3171	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		MILNESAND SAN ANDRE	S
		11. County or Parish, State	
Sec. 30, TSS, R35E, SWNE, 1650 FNL, 2244 F		ROOSEVELT COUNTY, N	M
12. CHECK APPROPRIATE BOX(ES) TO INDICATE N	VATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
	Production ((Start/Resume) Water Shut-Off	<u></u>
L&INotice of Intent Alter Casing Fracture Tree			
Subsequent Report		Other	
Final Abandonment Notice	bandon L Temporarily Water Dispo		
 Describe Proposed or Completed Operation (clearly state all pertinent details, inch If the proposal is to deepen directionally or recomplete herizontally, give subsurfax Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) Notify BLM. 	on file with BLM/BIA. Rec tiple completion or recompleti	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file	0 days x1 once
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump.	on file with BLM/BIA. Re- tiple completion or recompleti all requirements, including rec	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato	0 days xd once n has
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg.	on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato	0 days xd onco r bas
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump.	on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato $A \downarrow \Box \vdash R \bigcirc U$ g on CIBP.	0 days xd onco r bas
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp	on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato ADDROU g on CIBP.	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ½'' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½'' csg. 	to a file with BLM/BIA. Rec iple completion or recompletion all requirements, including roc pot 7 sx (100') plug point & cut csg. TOOH. Tag plug	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file charaction, have been completed, and the operato A = P = R O V g on CIBP. SEP 18 20	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp. 5. TOOH. RU on 4 ½° csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½° csg. 8. TIH w/2 3/8° OE tbg to 473°. Spot 35 sx 	to a file with BLM/BIA. Rec iple completion or recompletion all requirements, including roc pot 7 sx (100') plug point & cut csg. TOOH. Tag plug	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file charaction, have been completed, and the operato A = P = R O V g on CIBP. SEP 18 20	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ¼'2' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½'' csg. 8. TIH w/2 3/8'' OE tbg to 473'. Spot 35 sx 9. Spot 10 sx plug @ surface. 	to a file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH.	prince subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato $A \vdash P R O V$ g on CIBP. g after set.	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp. 5. TOOH. RU on 4 ½° csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½° csg. 8. TIH w/2 3/8° OE tbg to 473°. Spot 35 sx 	to a file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH.	prince subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato $A \vdash P R O V$ g on CIBP. g after set.	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ¼2'' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½2'' csg. 8. TIH w/2 3/8'' OE tbg to 473'. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore location. 	to a file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH.	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set.	0 days ad onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp 5. TOOH. RU on 4 ¼2° csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½2° csg. 8. TIH w/2 3/8° OE tbg to 473°. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 	a on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set.	0 days xd onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & signature of the site is ready for final to 4600'. Set CIBP & signature of the transformation of the test is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & signature of the test is the test of test of the test of test of the test of t	a on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee:	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set.	0 days xd onco. rr has
If the proposal is to deepen directionally or recomplete herizontally, give subsurfac Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ½' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½'' csg. 8. TIH w/2 3/8'' OE tbg to 473'. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and porrect Name (Printed/Typed) Nick Hood Signature	a on file with BLM/BIA. Rec iple completion or recompleti- all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set.	0 days xd onco. rr has
 If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & signature of the site is ready for final to 4600'. Set CIBP & signature of the transformation of the test is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & signature of the test is the test of test of the test of test of the test of t	a on file with BLM/BIA. Rec iple completion or recompleti- all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. g after set. FICE USE	0 days ad onco r has
If the proposal is to deepen directionally or recomplete herizontally, give subsurfac Attach the Bond under which the work will be performed or provide the Bond No. following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ½' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½'' csg. 8. TIH w/2 3/8'' OE tbg to 473'. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and porrect Name (Printed/Typed) Nick Hood Signature	a on file with BLM/BIA. Rec iple completion or recompleti- all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. gulations. FICE USE	O days ad onco. r has
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600'. Set CIBP & sp 5. TOOH. RU on 4 ½' csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50') in 4½'' csg. 8. TIH w/2 3/8'' OE tbg to 473'. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Thereby certify that the foregoing is true and correct Name (<i>PrintedTyped</i>) Nick Hood Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not wa certify that the applicant holds legal or equitable title to those rights in the subject	a on file with BLM/BIA. Rec iple completion or recompleti all requirements, including rec point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06 AL OR STATE OFF Title	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. gulations. FICE USE	O days ad onco. r has
If the proposal is to deepen directionally or recomplete herizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp 5. TOOH. RU on 4 ½" csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½" csg. 8. TIH w/2 3/8" OE tbg to 473°. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and correct Name (Printed/Typed) Nick Hood Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not was certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	a on file with BLM/BIA. Rec iple completion or recompletion all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06 AL OR STATE OFF Trant or tlease Office	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. g after set. FICE USE	0 days d onco. r has /ED 06
If the proposal is to deepen directionally or recomplete horizontally, give subsurfar. Attach the Bond under which the work will be performed or provide the Bond No following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the size is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp 5. TOOH. RU on 4 ½" csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½" csg. 8. TIH w/2 3/8" OE tbg to 473°. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and porrect Name (<i>Printed/Typed</i>) Nick Hood Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not wat certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon. Title B USC. Section 1001 and Title 43 USC. Section 1212, make it a crime for a States any false, ficitious or fraudulent statements or representations as to anymatices.	a on file with BLM/BIA. Rec iple completion or recompletion all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06 AL OR STATE OFF Trant or tlease Office	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. g after set. FICE USE	0 days d onco. r has /ED 06
If the proposal is to deepen directionally or recomplete horizontally, give subsurfar. Attach the Bond under which the work will be performed or provide the Bond No following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the site is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp 5. TOOH. RU on 4 ½" csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½" csg. 8. TIH w/2 3/8" OE tbg to 473°. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and porrect Name (<i>Printed/Typed</i>) Nick Hood Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not was certify that the applicant to conduct operations thereon. Title B USC. Section 1001 and Title 43 USC. Section 1212, make it a crime for a States any false, fictitious or fraudulent statements or representations as to any market (Instructions on page 2)	a on file with BLM/BIA. Rec iple completion or recompleti- all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06 AL OR STATE OFF Taile rrant or tlease Office any person knowingly and watter within its jurisdiction.	quired subsequent reports shall be filed within 34 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. gulations. FICE USE VICE USE	0 days d onco. r has /ED 06
If the proposal is to deepen directionally or recomplete horizontally, give subsurfar Attach the Bond under which the work will be performed or provide the Bond No following completion of the involved operations. If the operation results in a mult testing has been completed. Final Abandonment Notices shall be filed only after a determined that the size is ready for final inspection.) 1. Notify BLM. 2. MIRU Pulling Unit. Pull rods and pump. 3. NU BOP. TOOH w/tbg. 4. PU CIBP & TIH to 4600°. Set CIBP & sp 5. TOOH. RU on 4 ½" csg. Determine free 6. TOOH & LD csg. 7. TIH w/tbg & spot 25 sx (50°) in 4½" csg. 8. TIH w/2 3/8" OE tbg to 473°. Spot 35 sx 9. Spot 10 sx plug @ surface. 10. Install Dry Hole marker and restore locati 14. Ihereby certify that the foregoing is true and sorrect Name (<i>Printed/Typed</i>) Nick Hood Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not was certify that the applicant to conduct operations thereon. Title B USC. Section 1001 and Tite 43 USC. Section 1212, make it a crime for a States any false, ficitious or frauduleaf statements or representations as to anyma (Instructions on page 2)	a on file with BLM/BIA. Rec iple completion or recompletion all requirements, including rec pot 7 sx (100') plug point & cut csg. TOOH. Tag plug plug. TOOH. ion as per BLM reg Title Enginee: Date 9/11/06 AL OR STATE OFF Trant or tlease Office	quired subsequent reports shall be filed within 30 ion in a new interval, a Form 3160-4 shall be file clamation, have been completed, and the operato g on CIBP. g after set. g after set. FICE USE	0 days d onco. r has /ED 06

•

. .

3 ·



XOG OPERATING, LLC

1801 W. Texas P. O. Box 352 Midland, Texas 79702 Horton Federal Unit #5 1650' FNL, 2243' FEL Sec 30, T8S, R35E API # 30-041-10127



Nick Hood 9/9/06