والأحميلية المسيمة الم						
Form 3160-5 (August 1999) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				F	FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000	
				5. Lease Se	1P3586C329 NM014 1013	
					, Allottee or Tribe Name	
	IPLICATE - Other instru		ə side	7. If Unit o	r CA/Agreement, Name and/or No.	
<ul> <li>Type of Well</li> <li>Oil Well Gas Well Other Sec. 19B, T19S, R34E, 660 from North line, 2,030 from</li> </ul>					8. Well Name and No. PENNZOIL RIDGE COM #1	
2. Name of Operator BEACH EXPLORATION, INC.				9. API We	9. API Well No. 30-025-27070	
3a. Address 800 N. MARIENFELI	3b. Phone No. (include area code) (432) 683-6226		10. Field an	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				QUAIL RIDGE; MORROW		
Sec. 19B, T19S, R34E, 660 from North line, 2,030 from the East line.				LEA		
	PPROPRIATE BOX(ES) T		IRE OF NOTICE	l		
TYPE OF SUBMISSION	FROFRIATE BOA(E3) I		YPE OF ACTION			
	Acidize	Deepen	Production (S	Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	, <b>(11)</b> (10)	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
G Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug and Abandon Plug Back	<ul><li>Temporarily</li><li>Water Dispose</li></ul>			
Attach the Bond under which the following completion of the im- testing has been completed. F determined that the site is ready 1)•RIH and chemically cu 2)•RIH w/WL set CIBP a 3)•RIH and circulate hole	the work will be performed or pre- volved operations. If the operatio inal Abandonment Notices shall y for final inspection.) at 2 7/8" tbg above perm pack- nd set on top of perm packer w/ 9 ppg mud.	ovide the Bond No. on fil n results in a multiple cor be filed only after all requ ter at 13,010'. POOH at 13,010'. Dump bail	e with BLM/BIA. Rempletion or recomplet uirements, including i w/tbg 35' class H cmt or	quired subsequer ion in a new inter eclamation, have 1 top	ths of all pertinent markers and zones. It reports shall be filed within 30 days val, a Form 3160-4 shall be filed once been completed, and the operator has	
5)•At 7,000' perf 5 1/2" cs 6)•RIH w/WL tag cmt ph 7)•Pump 8 5/8" intermedi 8)•Pump base of salt top ( 9)•Pump top of salt plug 2 10)•Pump surface shoe pl 11)•Pump surface plug 20	csg and sqz 70 sx class H cmt sg and sqz 60 sx class H cmt ig at 6,900' and cut 5 1/2" cas ate shoe plug 55 sx class C c of Yates plug 40 sx class C in 35 sx class C in 8 5/8" csg at iug 35 sx class C in 8 5/8" csg o sx class C in 8 5/8" csg at 6 surface. Install 4" dry hole m	plug inside and outsid sing at top of cmt plug mt at 5,291'. WOC. 7 a 8 5/8" csg at 3,430'. 1,675'. WOC. Tag pl g at 455'. WOC. Tag 3'.	le of 5 1/2" csg fro g. Pull and lay dow Fag plug at minimu WOC. Tag plug a lug at minimum of plug at minimum of	m 7,000' to 6,99 m 5 1/2" casing um of 5,191'. t minimum of 3 1,575'. of 355'.	00' min 3 3,330'.	
			SEE ATTA CONDITI	CHED FOONS OF	UR APPROVAL	
14. I hereby certify that the forego Name (Printed/Typed)	ing is true and correct					
Brenda Martin		Title	Regulatory Analy	yst		
Signature I. N.M.	toll bude	Date 9/20/06				
	THIS SPACE	FOR FEDERAL OR		JSE		
Approved by	Illian		Title	APPR	QVED	
Conditions of approval, if any, are certify that the applicant holds let which would entitle the applicant to	gal or equitable title to those rig	to in the subject loose !	Office	OCT 1	2 2006	
Title 18 U.S.C. Section 1001 and <sup>7</sup> States any false, fictitious or fraudu	Title 43 U.S.C. Section 1212, mak alent statements or representations	e it a crime for any person as to any matter within its	n knowingly and will s jurisdiction.	ully to make to a		
			P	FREDERICI	KWRIGH <b>T</b> ENGINEE <b>R</b>	



## SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. The abandonment procedure is modified and approved as follows:
- 2. Establish injection rate into existing perfs through the existing perfs.
- 3. Cut tubing above permenant packer @ 13010'
- 4. RIH with work string and packer and pump cement through tubing stub into existing perfs leaving at least 25 sx of cement in the 5 ½ " casing.
- 5. Set cement plugs @ 12751', 11125', 8040', 3380', 1675',5291', 455' and a surface plug. All plugs should be tagged and leave at least 25 sacks of cement inside of the casing and the casing should be perfed for the plugs at 11125' and 8040'. Class H cement should be used for all plugs below 8000'.