## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	WELL API NO. 30-025-29893
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 34
Type of Well: Oil Well X Gas Well Other	8. Well No. 222
Name of Operator     Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter L : 2019 Feet From The South 817 Fee	t From The West Line
Section 34 Township 18-S Range 38-I	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3625' GL	
Did D-1	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	ALTERING CASING  NS. PLUG & ABANDONMENT
	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed to 1. Kill well. Pull out of hole with ESP equipment.	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.	NS. PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Line of Note with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Line of Note with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Lilian Number of Pattern of P	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Line of Note with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Lill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.	NS. PLUG & ABANDONMENT IT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Lill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.	PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Like It. Well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.  11. Run back in hole with ESP equipment. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ns. PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.  panieodely  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Nill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.  11. Run back in hole with ESP equipment. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ns. PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.  11. Run back in hole with ESP equipment. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ns. PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7'' casing @4163'.  4. Set cement retainer in 7'' casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.  11. Run back in hole with ESP equipment. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative	ns. PLUG & ABANDONMENT  IT JOB  , including estimated date of starting any completion or recompletion.  panies a line of the panies are that any pit or below-grade tank has been/will be a OCD-approved  Associate  DATE 10/31/2006
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Squeeze/Perforate & Acid Treat Well X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. Pull out of hole with ESP equipment.  2. Clean out well to PBTD @4380'.  3. Run in hole with CIBP set in 7" casing @4163'.  4. Set cement retainer in 7" casing @4060.  5. Cement squeeze open perfs 4100' to 4156'.  6. Drill out cement retainer @4060'. Pressure test squeeze.  7. Perforate hole @4140-53', 4164-70'.  8. Acid treat well with 15% PAD acid.  9. Swab or flow back. Circ well clean.  10. Scale squeeze well.  11. Run back in hole with ESP equipment. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative mendy johnson@oxy.com	that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE  DATE  10/31/2006  TELEPHONE NO  806-592-6280