

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22796 <u>06565</u>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Ralph C. Bruton		6. State Oil & Gas Lease No.
3. Address of Operator 3500 Acoma, Hobbs, NM 88240		7. Lease Name or Unit Agreement Name Bunin
4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>890</u> feet from the <u>East</u> line Section <u>13</u> Township <u>21S</u> Range <u>37E</u> NMPM County <u>Lea</u>		8. Well Number 03Y
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3461 KB		9. OGRID Number 018687
		10. Pool name or Wildcat Wantz Abo

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Clean location - test or replace anchors. Set CIBP at 6944', cap with 35' cement. Spot 100' plug: 4957' - 5057'.
2. Perf at 3120' - squeeze to obtain 100' plug, 3020' - 3120', across 8 5/8" at 3070.
3. Perf at 1422' - squeeze to obtain 100' plug, 1322' - 1422' - W.D.C. + TAG
4. Spot surface plug - 60' to surface (or 10 sxs). Install dry hole marker. Clean location.

→ SPOT 100' PLUG F/192'-92' 1338" SHOE PLUG W.D.C. + TAG

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ralph C. Bruton TITLE Owner/Operator DATE 11/6/06

Type or print name Ralph C. Bruton E-mail address: tgray@valornet.com Telephone No. 505-390-0366

(This space for State use)

APPROVED BY Harry W. Wink TITLE CC FIELD REPRESENTATIVE II / STAFF MANAGER DATE 11/6/06

Conditions of approval, if any

NOV 17 2006