

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

**DISTRICT I**  
1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis Dr.  
Santa Fe, NM 87505

**DISTRICT II**  
1301 W. Grand Ave, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.  
30-025-07493

5. Indicate Type of Lease  
STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

North Hobbs (G/SA) Unit  
Section 31

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Occidental Permian Ltd.

8. Well No. 421

3. Address of Operator  
HCR 1 Box 90 Denver City, TX 79323

9. OGRID No. 157984

4. Well Location

Unit Letter H : 1370 Feet From The North 330 Feet From The East Line  
Section 31 Township 18-S Range 38-E NMPM Lea County

11. Elevation (Show whether DF, RKB, RT GR, etc.)  
3642' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type \_\_\_\_\_ Depth of Ground Water \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ Multiple Completion ☐

OTHER: Deepen/Squeeze perfs/Convert to sub ☒

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: \_\_\_\_\_ ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Pull out of hole w/rods & pump.
2. Clean out to TD @4265'.
3. Set CIBP @4160'.
4. Squeeze open perfs @4032-54', 4132-43'.
5. Drill out CIBP @4160'. Test squeeze.
6. Clean out well to TD @4265.
7. Deepen well to new TD @4490'.
8. Run CNL/GR/CCL log from 4490' to  $\pm 2700'$ .
9. Acid treat well w/15% CSA acid. Perform scale squeeze.
10. Run in hole with ESP equipment.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 11/17/2006

TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy\_johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only

APPROVED BY Gary W. White TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE \_\_\_\_\_

CONDITIONS OF APPROVAL IF ANY:

NOV 22 2006