District I	State of New M Energy, Minerals and Na			Form C- March 4,	
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-05562			
1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis Dr.		5. Indicate Type of			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM		STATE X		
1220 S. St. Francis Dr., Santa Fe, NM 87505	20, 1111	07505	6. State Oil & Gas	Lease No.	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"	ES AND REPORTS ON WELL LS TO DRILL OR TO DEEPEN ON TO TION FOR PERMIT" (FORM C-101)	DI TICE DE MODERNE TROVA	7. Lease Name or U	_	ne
PROPOSALS.)  1. Type of Well:  Oil Well Gas Well X C		1100 C C C C C C C C C C C C C C C C C C	8. Well Number		
2. Name of Operator	order (S) Sy	7/03/4 13	2		
LANEXCO	INC.		9. OGRID Number 13046		
3. Address of Operator	19	8	10. Pool name or W		
1105 WEST KANSAS, JA 4. Well Location	L,NM 88252	<del>0512110</del>	EUMONT QU	EEN	
		The second secon			
Unit Letter M : 9	90 feet from the SOUTI	line and 990	feet from t	the <u>WEST</u> li	ne
Section 6	Township 19S I	Range 37E	NMPM (	County LEA	
	11. Elevation (Show whether D.	•			
Pit or Below-grade Tank Application (For pi	t or below-grade tank closures, a for	m C-144 must be attached			
Pit Location: UL Sect Twp	Rng Pit type	Depth to Groundwater	Distance from neare	est fresh water well	
Distance from nearest surface water		SectTwp			
NOTICE OF INTE	propriate Box to Indicate 1 ENTION TO: PLUG AND ABANDON		Report or Other Da		
	LOG YND ABANDON []	REMEDIAL WORK	C □ Al	TERING CASING	
TEMPORARILY ABANDON [] (	CHANGE PLANS			TERING CASING	_
PULL OR ALTER CASING		REMEDIAL WORK	LING OPNS. PI	TERING CASING	
PULL OR ALTER CASING	CHANGE PLANS   MULTIPLE  COMPLETION	CASING TEST AN CEMENT JOB	LING OPNS. PI AF	TERING CASING LUG AND [BANDONMENT]	<u> </u>
PULL OR ALTER CASING OTHER:	CHANGE PLANS   MULTIPLE  COMPLETION	COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: TEMI	LING OPNS. PI	TERING CASING  LUG AND BANDONMENT  NDON [	<u> </u>
PULL OR ALTER CASING OTHER:  13. Describe proposed or complete of starting any proposed work)	CHANGE PLANS  MULTIPLE  COMPLETION  Code operations. (Clearly state all	COMMENCE DRIL  CASING TEST AN  CEMENT JOB  OTHER: TEMI  pertinent details, and ple Completions: Atta	LING OPNS. PI AND PORARILY ABAI give pertinent dates, iach wellbore diagram	LUG AND BANDONMENT  NDON Including estimated of proposed comple	X)
PULL OR ALTER CASING OTHER:  13. Describe proposed or complete of starting any proposed work)	CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all SEE RULE 1103. For Multi O6: Rig up pullir	COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: TEMP Pertinent details, and ple Completions: Atta	LING OPNS. PI AF  D  PORARILY ABAI  give pertinent dates, if ach wellbore diagram  1 2 3/8" tul	LIERING CASING LUG AND BANDONMENT  NDON Including estimated of proposed completed ing.	X)
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0	CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all SEE RULE 1103. For Multi O6: Rig up pullir CIBP at 3550' or	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI pertinent details, and ple Completions: Atta	LING OPNS. PI AF  D  PORARILY ABAI  give pertinent dates, if ach wellbore diagram  1 2 3/8" tul  Cap with 35	LUG AND BANDONMENT  NDON pincluding estimated of proposed completed bing.	date tion
PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Nip	CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all SEE RULE 1103. For Multi O6: Rig up pullir 'CIBP at 3550' or 'Run in hole wi	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI Pertinent details, and ple Completions: Atta Ig unit. Pull wireline. th 2 3/8" tu Test casir	LING OPNS. PI  AF  D  PORARILY ABAI  give pertinent dates, if ach wellbore diagram  1 2 3/8" tul  Cap with 35  abing. Circuit ag to 520 PS	LUG AND BANDONMENT  NDON Gincluding estimated of proposed complebing.  ' cement. Gulate hole will be the second complete the s	date tion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Niminutes. Ok. Ris	CHANGE PLANS  MULTIPLE COMPLETION  ed operations. (Clearly state all ). SEE RULE 1103. For Multi 06: Rig up pullir ' CIBP at 3550' or '. Run in hole wi pple up well head. g down pulling uni	CASING TEST AN CEMENT JOB OTHER: TEMPORTHER TEMPORTHER Pulls and ple Completions: Attag unit. Pulls wireline. The 2 3/8" to Test casing t. Well TA'	PORARILY ABAI give pertinent dates, is ach wellbore diagram 1 2 3/8" tull Cap with 35 libing. Circuit 10 10 10 10 10 10 10 10 10 10 10 10 10	TERING CASING  LUG AND BANDONMENT  NDON including estimated of proposed complete bing.  ' cement. ulate hole of the complete bing.	Adate tion  Top with
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Nipminutes. Ok. Rig	CHANGE PLANS  MULTIPLE COMPLETION  ed operations. (Clearly state all ). SEE RULE 1103. For Multi 06: Rig up pullir 'CIBP at 3550' or '. Run in hole wi pple up well head. g down pulling uni ove is true and complete to the lead according to NMOCD guidelines	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI pertinent details, and ple Completions: Atta g unit. Pul wireline. th 2 3/8" tu Test casin t. Well TA' pest of my knowledge G, a general permit G	LING OPNS. PI Af  D PORARILY ABAI give pertinent dates, i ach wellbore diagram 1 2 3/8" tul Cap with 35 abing. Circuit ng to 520 PS: D  and belief. I further corran (attached) alternative	TERING CASING  LUG AND BANDONMENT  NDON including estimated of proposed complete bing.  ' cement. ulate hole of the complete bing.	Adate tion  Top with
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Niminutes. Ok. Right in the constructed or close SIGNATURE	CHANGE PLANS  MULTIPLE COMPLETION  ed operations. (Clearly state all b. SEE RULE 1103. For Multi 06: Rig up pullir ' CIBP at 3550' or '. Run in hole wi pple up well head. g down pulling uni ove is true and complete to the lead according to NMOCD guidelines  TITLE F	CASING TEST AN CEMENT JOB OTHER: TEMPORTHER TEMPORTHER Pulls and ple Completions: Attag unit. Pulls wireline. The 2 3/8" to Test casing t. Well TA'	LING OPNS. PI Af  D PORARILY ABAI give pertinent dates, i ach wellbore diagram 1 2 3/8" tul Cap with 35 abing. Circuit ng to 520 PS: D  and belief. I further corran (attached) alternative	TERING CASING  LUG AND BANDONMENT  NDON including estimated of proposed complete bing.  ' cement. ulate hole of the complete bing.	date tion  Top with
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Nipminutes. Ok. Rig	CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all SEE RULE 1103. For Multi O6: Rig up pullir CIBP at 3550' or Run in hole wi pple up well head. Ed down pulling uni ove is true and complete to the lead according to NMOCD guidelines  TITLE F	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI pertinent details, and ple Completions: Att ag unit. Pul wireline. th 2 3/8" tu Test casin t. Well TA' pest of my knowledge Chageneral permit Conduction Su	LING OPNS. PI Af  D  PORARILY ABAI  give pertinent dates, i ach wellbore diagram 1 2 3/8" tul  Cap with 35  abing. Circu ag to 520 PS  D  and belief. I further corran (attached) alternativ  apt. D	TERING CASING  LUG AND BANDONMENT  NDON Including estimated of proposed completing.  ' cement. Lulate hole of the completing of the comple	date tion  Top with
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Niminutes. Ok. Right in the constructed or close SIGNATURE	CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all SEE RULE 1103. For Multi O6: Rig up pullir CIBP at 3550' or Run in hole wi pple up well head. Ed down pulling uni ove is true and complete to the lead according to NMOCD guidelines  TITLE F	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI pertinent details, and ple Completions: Att ag unit. Pul wireline. th 2 3/8" tu Test casin t. Well TA' pest of my knowledge Chageneral permit Conduction Su	LING OPNS. PI Af  D  PORARILY ABAI  give pertinent dates, i ach wellbore diagram 1 2 3/8" tul  Cap with 35  abing. Circu ag to 520 PS  D  and belief. I further corran (attached) alternativ  apt. D	TERING CASING  LUG AND BANDONMENT  NDON Including estimated of proposed completing.  ' cement. Lulate hole of the completing of the comple	date tion  Top with
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion. 12-15-0  12-18-06: Set 5½  of cement at 3515  packer fluid. Nipminutes. Ok. Rig  I hereby certify that the information aborgrade tank has been/will be constructed or closs  SIGNATURE  Type or print name Charles Man  (This space for State use)	CHANGE PLANS  MULTIPLE COMPLETION  ed operations. (Clearly state all SEE RULE 1103. For Multi 06: Rig up pullir CIBP at 3550' or Run in hole wi pple up well head. Government of the local according to NMOCD guidelines  TITLE F	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: TEMI pertinent details, and ple Completions: Att ag unit. Pul wireline. th 2 3/8" tu Test casin t. Well TA' pest of my knowledge Chageneral permit Conduction Su	PORARILY ABAI give pertinent dates, is ach wellbore diagram 1 2 3/8" tul Cap with 35 abing. Circuing to 520 PS: D and belief. I further corran (attached) alternative  Interpolation of Temporary at Expires	TERING CASING  LUG AND BANDONMENT  NDON Including estimated of proposed completions.  cement. Lulate hole of for 30  ertify that any pit or bell of OCD-approved plan [ATE 12-20-06]  hone No 505-397  /2/18/11	date tion  Top with

